

Estimate Written By: Brandon Martini
Email: Brandon@ClaimsFlowSolutions.com
Phone: 909-917-6777

No Supplements will be honored without reinspection!
Please contact Brandon Martini for all supplements!
All final supplements need 48 hours notice before needing vehicle to
be released or rental bill will be the shops responsibility!
Please call adjuster to confirm coverage and deductible amount prior
to repairs!

Property Damage Appraisers

P.O. Box 2233, Hawaiian Gardens, CA 90716
(714) 985-4624
Fax: (714) 630-7941
Email: pdasouthbay@pdaorg.net

Damage Assessed By: Brandon Martini

Appraised For: DERRON LAX
(877) 884-1977

THIS ESTIMATE IS NOT AN AUTHORIZATION FOR REPAIR. ALL COSTS AND

REPAIRS ARE THE SOLE RESPONSIBILITY OF THE VEHICLE OWNER, WHO

ULTIMATELY MUST AUTHORIZE ALL REPAIRS. NO SUPPLEMENTS WILL BE

HONORED WITHOUT THE PRIOR INSPECTION OF PROPERTY DAMAGE APPRAISERS.

PDA SPECIFIES THAT ALL REPAIRS AND/OR PARTS REPLACEMENT LISTED HEREIN

BE MADE IN STRICT ACCORDANCE WITH MANUFACTURERS SPECIFICATIONS.

Condition Code: Good
Date of Loss: 12/31/2013
Deductible: UNKNOWN
File Number: 5724060061
Claim Number: AB237-001455-99

Type of Loss: Collision

Insured: EDWARDS VACUUM, INC. STEVE HERSHENSON
Owner: EDWARDS VACUUM, INC. STEVE HERSHENSON
Address: 8512 TUSCANY AVE, PLAY DEL REY, CA 90293
Telephone:
Cell Phone: (310) 405-1401

ESTIMATE RECALL NUMBER: 06/10/2014 07:20:35 5724060061
Mitchell Data Version: OEM: MAY_14_V

Copyright (C) 1994 - 2014 Mitchell International
All Rights Reserved

Software Version: 7.1.164

Date: 6/10/2014 07:20 AM
 Estimate ID: 5724060061
 Estimate Version: 0
 Committed
 Profile ID: * PDA - South Bay

Mitchell Service: 911451

Description: 2014 Toyota Camry SE
 Body Style: 4D Sed
 VIN: 4T1BF1FK5EU326569
 Mileage: 12,493
 OEM/ALT: O
 Color: Grey
 Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, REAR WINDOW DEFOGGER
 MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
 TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS
 ALUM/ALLOY WHEELS, AUXILIARY INPUT, TINTED GLASS, TRIP COMPUTER
 VARIABLE ASSISTED STEERING, SIDE AIRBAGS, ANTI-THEFT SYSTEM
 AUTOMATIC HEADLIGHTS, SECOND ROW SIDE AIRBAG, SIDE HEAD CURTAIN AIRBAGS
 DAYTIME RUNNING LIGHTS, AM/FM STEREO CD/MP3 PLAYER, ELECTRONIC STABILITY CONTROL
 FRONT BUCKET SEATS, INTERIOR AIR FILTER, KEYLESS ENTRY SYSTEM, POWER DISC BRAKES
 POWER LIFTGATE/TRUNK, REAR SPOILER, STEERING WHEEL AUDIO CONTROLS

Vehicle Production Date: 10/13
 Drive Train: 2.5L Inj 4 Cyl 6A FWD
 License: NOPLATES

Search Code: 572

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units	CEG Unit
<u>Windshield</u>								
1	101228	GLS	REMOVE/INSTALL	Windshield			0.5* #	3.8
2				Rope/Mask Only				
<u>Rocker/Pillars/Floor</u>								
3	100806	REF	BLEND	L Roof Rail			C 0.6 #	1.6
4	100122	BDY	REMOVE/INSTALL	L Rocker Moulding			0.4	0.4
5	100127	BDY	REPAIR	L Rocker Moulding	Existing		1.5*	0.4
6		REF	REFINISH	L Rocker Moulding			C 1.4	1.4
<u>Front Door</u>								
7	101623	BDY	REPAIR	L Frt Door Shell	Existing		2.5* #	5.5
8		REF	REFINISH	L Frt Door Outside			C 2.2	2.2
9	101631	BDY	REMOVE/INSTALL	L Frt Rear View Mirror			INC #	0.7
10	101629	BDY	REMOVE/INSTALL	L Frt Otr Belt Moulding			0.9 #	0.9
11	101119	BDY	REMOVE/INSTALL	L Frt Door Trim Panel			INC	0.4
12	101387	BDY	REMOVE/INSTALL	L Frt Otr Door Handle			0.3	0.3
<u>Rear Door</u>								
13	102295	BDY	REPAIR	L Rear Door Shell	Existing		5.0*	5.3
14		REF	REFINISH	L Rear Door Outside			C 1.8	2.2
15	102299	BDY	REMOVE/INSTALL	L Rear Otr Belt Moulding			0.2	0.2
16	102311	BDY	REMOVE/INSTALL	L Rear Door Trim Panel			INC	0.4
17	102097	BDY	REMOVE/INSTALL	L Rear Otr Door Handle			1.0 #	1.0
<u>Roof</u>								
18	101954	BDY	REMOVE/INSTALL	L Roof Drip Moulding			0.4	0.4
<u>Back Window</u>								
19	101949	GLS	REMOVE/INSTALL	Back Window			0.5* #	3.6
20				Rope/Mask Only				
<u>Quarter Panel</u>								
21	100373	REF	REFINISH	L Add For Pillar			C 0.5	0.5
22	100383	REF	BLEND	L Fuel Door			INC #	0.5
23	100396	BDY	REPAIR	L Quarter Outer Panel	Existing		9.5* #	21.0
24		REF	REFINISH	L Quarter Panel Outside			C 1.8	2.2
25				7.5 for leg, 2 for pillar				
26	100401	BDY	REMOVE/INSTALL	L Quarter Fuel Door	Existing		0.3 r	0.3
27	100405	BDY	REMOVE/REPLACE	L Quarter Protector	58748-06070	4.94	0.2 #	0.2T
28	101244	BDY	REMOVE/INSTALL	L Quarter Wheelhouse Liner	Existing		0.4 r	0.4
<u>Rear Lamps</u>								
29	101692	BDY	REMOVE/INSTALL	L Rear Combination Lamp			0.9 #	0.9
<u>Rear Bumper</u>								

ESTIMATE RECALL NUMBER: 06/10/2014 07:20:35 5724060061

Mitchell Data Version: OEM: MAY_14_V

Copyright (C) 1994 - 2014 Mitchell International
 All Rights Reserved

Software Version: 7.1.164

Page 2 of 4

Insurance Co: LIBERTY MUTUAL INS(MIDDLE MKT)
Address: 2100 WALNUT HILL LN STE 100
IRVING, TX 75038
Work Phone: (877) 884-1977

Inspection Site: Owners Residence
Address: 8512 Tuscany Ave.
Playa Del Rey, CA 90293
Inspection Date: 6/ 9/2014

THIS REPAIR ESTIMATE/APPRaisal MAY BE PREPARED BASED UPON THE USE OF
ONE OR MORE AFTERMARKET CRASH AND/OR OTHER PARTS SUPPLIED BY A SOURCE
OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. PARTS USED IN THE
REPAIR OF YOUR VEHICLE OTHER THAN PARTS FROM THE ORIGINAL

MANUFACTURER

ARE REQUIRED TO BE LEAST EQUAL OF LIKE, KIND AND QUALITY IN TERMS OF
FIT, QUALITY, AND PERFORMANCE TO THE REPLACEMENT PARTS AVAILABLE FROM
THE ORIGINAL MANUFACTURER. WARRANTIES APPLICABLE TO THESE AFTERMARKET
CRASH AND/OR OTHER PARTS ARE PROVIDED BY THE PARTS MANUFACTURER OR
DISTRIBUTOR RATHER THAN YOUR OWN MOTOR VEHICLE MANUFACTURER.

FOR YOUR PROTECTION CALIFORNIA LAW REQUIRES THE FOLLOWING TO
APPEAR ON THIS FORM. ANY PERSON WHO KNOWINGLY PRESENTS A FALSE
OR FRAUDULENT CLAIM FOR THE PAYMENT OF A LOSS, IS GUILTY OF A
CRIME AND MAY BE SUBJECT TO FINES AND CONFINEMENT IN STATE
PRISON.
