

Date: 1/6/2013 10:36 PM
Estimate ID: 414371-CA
Estimate Version: 0
Committed
Profile ID: Doan California

Estimate Written By: Brandon Martini
Phone: 909-917-6777
Email: California@doan.com and CC:Brandon@BrandonMartiniSolutions.com

No Supplements will be honored without reinspection!
Please contact Brandon Martini for all supplements!
All final supplements need 48 hours notice before needing vehicle to be released or rental bill will be the shops responsibility!
Please call adjuster to confirm coverage and deductible amount prior to repairs!

DOAN & COMPANY

5090 HWY 212 559-840-0543, COVINGTON, GA 30016
(770) 778-8328
Fax: (559) 840-0543
Email: california@doan.com

Damage Assessed By: Brandon Martini

Appraised For: Suzanne Hamel
(860) 298-1238

THIS ESTIMATE IS NOT AN AUTHORIZATION FOR REPAIR. ALL COSTS AND REPAIRS ARE THE SOLE RESPONSIBILITY OF THE VEHICLE OWNER, WHO ULTIMATELY MUST AUTHORIZE ALL REPAIRS. NO SUPPLEMENTS WILL BE HONORED WITHOUT PRIOR INSPECTION.

ALL REPAIRS AND/OR PARTS REPLACEMENT LISTED HEREIN BE MADE IN STRICT ACCORDANCE WITH MANUFACTURERS SPECIFICATIONS.

Condition Code: Fair
Deductible: UNKNOWN
File Number: 414371-CA
Claim Number: 10-3256

Type of Loss: Collision

Insured: Academy Valet Parking
Claimant: Luis Cermeno
Address: 624 N Taylor Ave., Montebello, CA 90640
Telephone: Home Phone: (213) 798-0630

Mitchell Service: 918481

Description: 1992 Chevrolet Camaro RS
Body Style: 2D Cpe
VIN: 1G1FP23E0NL121053
Mileage: 176,226
OEM/ALT: O
Color: White
Options: POWER LOCK, POWER WINDOW, POWER STEERING, POWER BRAKE, MANUAL AIR CONDITION

Drive Train: 5.0L Inj 8 Cyl 4A
License: 5UBJ299 CA

Search Code: None

CRUISE CONTROL, TILT STEERING COLUMN, FM RADIO, ALUM/ALLOY WHEELS
MANUAL REMOTE MIRROR, POWER REMOTE MIRROR, AUTOMATIC TRANSMISSION

ESTIMATE RECALL NUMBER: 01/06/2013 22:36:04 414371-CA
Mitchell Data Version: OEM: OCT_12_V

Software Version: 7.0.482

Copyright (C) 1994 - 2012 Mitchell International
All Rights Reserved

Page 1 of 4

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units	CEG Unit
<u>Front Bumper/Grille</u>								
1	801830	BDY	REPAIR	Bumper/Grille Cover	Existing		0.5* #	4.4
2		REF	REFINISH/REPAIR	Bumper/Grille Cover			C 1.0*	2.4
3				MODIFIED REFINISH WITH FULL CLEAR COAT				
<u>Hood</u>								
4	810810	BDY	REPAIR	Hood Panel	Existing		2.0*	1.2
5		REF	REFINISH	Hood Outside			C 3.4	3.4
<u>Front Fender</u>								
6	811850	BDY	REMOVE/REPLACE	L Fender Panel	Qual Recycled Part	250.00	* 2.0 #	2.0T
7		REF	REFINISH	L Fender Outside			C 2.4	2.8
8		REF	REFINISH	L Add To Edge Fender			C 0.5	0.5
9				One Way Auto, 626-289-6126				
10				Line Markup %20.00		50.00		
11	811900	BDY	REMOVE/INSTALL	L Fender Splash Shield	Existing		0.3 r	0.3
<u>Rocker/Pillars/Floor</u>								
12	824220	BDY	REPAIR	L Rocker Outer Panel -S	Existing		1.0*	6.0
13		REF	REFINISH	L Rocker Panel			C 1.2	1.6
14				Lt Mld				
<u>Front Door</u>								
15	825140	REF	BLEND	L Frt Door Outside			C 1.0	2.4
16	825880	BDY	REMOVE/INSTALL	L Frt Door Adhesive Moulding	Existing		0.2 r	0.2
17	825920	BDY	REMOVE/INSTALL	L Frt Door Edge Moulding	Existing		r	
18	825960	BDY	REMOVE/INSTALL	L Frt Door Rear View Mirror	Existing		0.3 #r	0.3
19	800012	BDY	REMOVE/INSTALL	L Frt Door Trim Panel			0.4	0.4
20	826510	BDY	REMOVE/INSTALL	L Frt Door Outside Handle	Existing		0.2 #r	0.2
<u>Additional Costs & Materials</u>								
21	936014		ADD'L COST	Flex Additive		6.00	*	T
<u>ADDITIONAL OPERATIONS</u>								
22		REF	ADD'L OPR	Clear Coat			2.7	
23	933003	REF	ADD'L OPR	Tint Color			0.5*	
24				Material Cost is Calculated with the Refinish Oper				
25	933017	REF	ADD'L OPR	Finish Sand And Buff			1.0*	
26				Material Cost is Calculated with the Refinish Oper				
27	933018	REF	ADD'L OPR	Mask For Overspray			0.5*	
28				Material Cost is Calculated with the Refinish Oper				
<u>Additional Costs & Materials</u>								
29			ADD'L COST	Paint/Materials		393.00	*	T
30			ADD'L COST	Hazardous Waste Disposal		3.00	*	T
<u>MANUAL ENTRIES</u>								
31	900500	BDY *	REMOVE/INSTALL	L Rocker Mld Emblem	Existing		0.3* r	
32	900500	BDY *	REPAIR	L Mirror	Existing		0.3*	
33		REF	REFINISH/REPAIR	L Mirror			0.4*	
34	900500	BDY *	ADD'L LABOR OP	Mask L Headlamp Opening	Existing		0.3*	

* - Judgment Item

- Labor Note Applies

C - Included in Clear Coat Calc

r - CEG R&R Time Used For This Labor Operation

Prior Damage:

Front bumper

ESTIMATE RECALL NUMBER: 01/06/2013 22:36:04 414371-CA

Mitchell Data Version: OEM: OCT_12_V

Software Version: 7.0.482

Copyright (C) 1994 - 2012 Mitchell International
All Rights Reserved

Page 2 of 4

Estimate Totals

ARE REQUIRED TO BE LEAST EQUAL OF LIKE,KIND AND QUALITY IN TERMS OF
FIT, QUALITY, AND PERFORMANCE TO THE REPLACEMENT PARTS AVAILABLE FROM
THE ORIGINAL MANUFACTURER. WARRANTIES APPLICABLE TO THSE AFTERMAREKT
CRASH AND/OR OTHER PARTS ARE PROVIDED BY THE PARTS MANUFACTURER OR
DISTRIBUTOR RATHER THAN YOUR OWN MOTOR VEHICLE MANUFACTURER.

FOR YOUR PROTECTION CALIFORNIA LAW REQUIRES THE FOLLOWING TO
APPEAR ON THIS FORM. ANY PERSON WHO KNOWINGLY PRESENTS A FALSE
OR FRAUDULENT CLAIM FOR THE PAYMENT OF A LOSS, IS GUILTY OF A
CRIME AND MAY BE SUBJECT TO FINES AND CONFINEMENT IN STATE
PRISON.
