

PROPERTY DAMAGE SPECIALIST
P.O. BOX 2002 , INDIO , CA 92202
(760) 275-6795
Fax: (760) 863-5349

APPRAISAL REPORT

DAMAGE ASSESSED BY: CU TRAN

FILE NUMBER: None
CLAIM NUMBER: CO13009703
DATE OF LOSS: 5/30/2013
TYPE OF LOSS: Collision
APPRAISED FOR: ROBERT MORENO INS. / SHELLEY AMBRIZ

ASSIGNMENT DATE: None
CONTACT DATE: 6/13/2013
INSPECTION DATE: 6/24/2013
REC'D DATE: None

Point(s) of Impact

5 Right Rear Corner (P)

INSURED: DARIUS FOX
2144 S. PILGRIM ST.
STOCKTON, CA 95206
(209) 688-3693

CLAIMANT: None

OWNER: None

BODY SHOP: " NO REPAIR FACILITY CHOICE "
CA

FAX:

INSPECTION SITE: INSURED'S RESIDENCE
2144 S PILGRIM ST.
STOCKTON, CA 95206

QUALITY RECYCLED PARTS: No
AFTERMARKET NEW PARTS: No
VEHICLE DRIVEABLE: Yes

Comments:

Inspected vehicle at insured's residence in Stockton Ca. on
06/24/2013. Insured was not present at time of inspection, unable to
get odometer reading and registration photos.

Found vehicle had sustained right rear corner impacted. Damage to the
rear bumper cover and right retainer to right quarter panel.

Open items: Rear bumper absorber and reinforcement bar, pending the
removal of the rear bumper cover.

Insured was unable to provide a repair facility choice at time of
inspection, utilized local average rates for this report.

No child car seat was in use at time of loss.

Estimate day repairs: 2 days

Damage estimate and photos attached for your review and handling.

THANK YOU

COMPARISON ESTIMATE:	0.00	TOWING:	0.00	ACTUAL CASH VALUE:	17,375.00
APPRAISER ESTIMATE:	344.29	STORAGE:	0.00	SALVAGE VALUE:	0.00
AGREED UPON AMOUNT:	0.00	DEDUCTIBLE:	500.00	SETTLEMENT:	0.00
				REPAIR VS. ACV:	0.00
DRAFT/CHECK NUMBER:	0			ESTIMATE FEE:	0.00
DRAFT/CHECK AMOUNT:	0.00			TRAVEL EXPENSE:	0.00
DATE ISSUED:	None			PHOTO EXPENSE:	0.00
				MISC EXPENSE:	0.00
				TOTAL CHARGES:	0.00

FOR SUPPLEMENTS CALL RICH PEREA (760)275-6795 or E-mail: pds9593 @
verizon.net

PROPERTY DAMAGE SPECIALIST

P.O. BOX 2002 , INDIO , CA 92202
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: CU TRAN

Appraised For: ROBERT MORENO INS. / SHELLEY AMBRIZ
(714) 738-1383 ext. 2396

Condition Code: Good
Date of Loss: 5/30/2013
Contact Date: 6/13/2013
Deductible: 500.00
Claim Number: CO13009703

Type of Loss: Collision

Insured: DARIUS FOX
Address: 2144 S. PILGRIM ST., STOCKTON, CA 95206
Telephone: Home Phone: (209) 688-3693

Mitchell Service: 911404

Description: 2012 Honda Civic LX
Body Style: 4D Sed
VIN: 19XFB2F52CE389805
OEM/ALT: O
Color: GREY MET
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, REAR WINDOW DEFOGGER
MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS
AUXILIARY INPUT, FRONT AIR DAM, TINTED GLASS, TRIP COMPUTER
VARIABLE ASSISTED STEERING, SIDE AIRBAGS, ANTI-THEFT SYSTEM
SIDE HEAD CURTAIN AIRBAGS, DAYTIME RUNNING LIGHTS, AM/FM STEREO CD/MP3 PLAYER
ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS, INTERIOR AIR FILTER
KEYLESS ENTRY SYSTEM, POWER LIFTGATE/TRUNK, STEERING WHEEL AUDIO CONTROLS

Drive Train: 1.8L Inj 4 Cyl 5A FWD
License: 6YZB978 CA
Search Code: C641223

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Rear Bumper</u>							
1		BDY	OVERHAUL	Rear Bumper Cover Assy			1.0
2	100048	BDY	REMOVE/REPLACE	Rear Bumper Cover	04715-TR3-A90ZZ	303.38	INC
3		REF	REFINISH	Rear Bumper Cover			C 2.6
4	101190	BDY	REMOVE/REPLACE	R Rear Bumper Spacer	71593-TR0-A01	12.27	0.2 #
5		BDY	REMOVE/INSTALL	Rear Bumper Cover			INC
<u>ADDITIONAL OPERATIONS</u>							
6		REF	ADD'L OPR	Clear Coat			1.0
<u>ADDITIONAL REFINISH OPERATIONS</u>							
7	933003	BDY *	ADD'L OPR	TINT COLOR			0.5*
<u>Additional Costs & Materials</u>							
8			ADD'L COST	Paint/Materials		118.80	*
9			ADD'L COST	Hazardous Waste Disposal		3.00	*

ESTIMATE RECALL NUMBER: 06/24/2013 18:39:51 9640

Mitchell Data Version: OEM: APR_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

* - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc

Estimate Totals

														</	

BY THE APPRAISER. FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!***

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts

Itemized Totals

I. Labor Subtotals	Units	Rate	Totals
Body	1.7	70.00	119.00
Remove/Replace	0.2	"	14.00
Overhaul	1.0	"	70.00
Additional Operation	0.5	"	35.00
Refinish	3.6	70.00	252.00
Refinish Only	2.6	"	182.00
Additional Operation	1.0	"	70.00
Non-Taxable Labor			371.00
Labor Summary	5.3		371.00

II. Part Replacement Summary	Amount
Taxable Parts	315.65
New	315.65
Sales Tax @ 8.250%	26.04
Total Replacement Parts Amount	341.69

III. Additional Costs	Amount
Taxable Costs	118.80
Sales Tax @ 8.250%	9.80
Non-Taxable Costs	3.00
Total Additional Costs	131.60

IV. Adjustments	Amount
Insurance Deductible	500.00-
Customer Responsibility	500.00-

Paint Material Method: Rates
Init Rate = 33.00 , Init Max Hours = 99.9, Addl Rate = 0.00

I.	Total Labor:	371.00
II.	Total Replacement Parts:	341.69
III.	Total Additional Costs:	131.60
	Gross Total:	844.29
IV.	Total Adjustments:	500.00-
	Net Total:	344.29







