

Date: 10/31/2013 01:18 PM
Estimate ID: 10302013-100001
Estimate Version: 0
Preliminary
Profile ID: * Mitchell

Property Damage Specialist

P.O. Box 2002, Indio, CA 92202
(760) 275-6795
Fax: (760) 863-5349
Email: pds9593@verizon.com

Damage Assessed By: MITCHELL MITCHELL

Condition Code: Good
Contact Date: 10/29/2013
Deductible: 500.00
File Number: 10302013-100001
Policy No: AIC001729

Claim Number: AM13002175

Insured: ROBERTO SALGADO
Address: 56756 VAN ELLA, BAKER, CA 92309
Telephone: Home Phone: (760) 590-0864

Mitchell Service: 918752

Description: 2004 Toyota Sequoia Limited

Body Style: 4D Ut
VIN: 5TDBT48A54S220855

Drive Train: 4.7L Inj 8 Cyl 4WD
License: 6HNV870 CA

Mileage: 152,234
OEM/ALT: O

Search Code: None

Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW
REAR WINDOW DEFOGGER, CRUISE CONTROL, TILT STEERING COLUMN, REAR (DUAL-ZONE) AC
LEATHER SEAT, LUGGAGE RACK, SKID PLATES, PREMIUM SOUND SYSTEM
ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS, ALUM/ALLOY WHEELS
LEATHER STEERING WHEEL, TOW HITCH RECEIVER, 4WD OR AWD, FRONT AIR DAM
TINTED GLASS, AUTO AIR CONDITION, TRIP COMPUTER, THIRD ROW SPLIT BENCH SEAT
UNIVERSAL GARAGE DOOR OPENER, ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS
INTERIOR AUTOMATIC DAY/NIGHT OR ELECTROCHROMATIC MIRROR
AM/FM STEREO CASSETTE/CD, COLOR-KEYED RUNNING BOARDS
ELECTRONIC STABILITY CONTROL, FRONT CAPTAINS CHAIRS, FRONT HEATED SEATS
FRONT SEATS WITH POWER LUMBAR SUPPORT, KEYLESS ENTRY SYSTEM, POWER DISC BRAKES
POWER HEATED EXTERIOR MIRRORS, POWER LIFTGATE/TRUNK
REAR WINDOW DIVERSITY ANTENNA, REAR WINDOW WIPER, STEERING WHEEL AUDIO CONTROLS
STEP BUMPER, SUNROOF/MOONROOF (POWER)

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	AUTO	BDY	OVERHAUL	Frt Bumper Cover Assy			2.4
2	800023	BDY	REMOVE/REPLACE	Frt Bumper Cover	** QUAL REPL PART	199.00	* INC
3	AUTO	REF	REFINISH	Frt Bumper Cover			C 2.6
4	AUTO	BDY	REMOVE/REPLACE	Frt Add w/Fender Flare			0.2
5				LKQ 1800-525-3667			
6	800025	BDY	REMOVE/REPLACE	R Frt Bumper Extension	52112-0C900	72.47	INC
7	AUTO	REF	REFINISH	R Frt Bumper Extension			C 0.5
8	800032	BDY	REMOVE/REPLACE	Frt Bumper Filler Panel	53903-0C020	200.18	0.9 #
9	AUTO	REF	REFINISH	Frt Filler Panel			C 0.8
10	800055	BDY	REMOVE/INSTALL	R Headlamp Assy			INC #
11	800069	BDY	REMOVE/REPLACE	R Signal Lamp Lens & Housing	81511-0C020	86.08	INC
12	800250	BDY	REPAIR	R Fender Panel	Existing		1.0* #
13	AUTO	REF	REFINISH	R Fender Outside			C 2.1
14	800281	BDY	REMOVE/INSTALL	R Fender Wheel Opening Flare			INC
15	800283	BDY	REMOVE/INSTALL	R Fender Wheel Opening Mldg			0.2

ESTIMATE RECALL NUMBER: 10/31/2013 13:18:26 10302013-100001

Mitchell Data Version: OEM: AUG_13_V

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Software Version: 7.0.487

Page 1 of 3

16	800285	BDY	REMOVE/INSTALL	R Fender Mudguard			0.2
17	AUTO	REF	ADD'L OPR	Clear Coat			1.7
18	933003	REF	ADD'L OPR	TINT COLOR			0.5*
19	900500	BDY *	CHECK/ADJUST	HAZMAT	Sublet	3.50 *	0.0*

* - Judgment Item

- Labor Note Applies

C - Included in Clear Coat Calc

Estimate Totals

Date: 10/31/2013 01:18 PM
Estimate ID: 10302013-100001
Estimate Version: 0
Preliminary
Profile ID: * Mitchell

Body Shop: NO SHOP CHOICE

ESTIMATE RECALL NUMBER: 10/31/2013 13:18:26 10302013-100001
Mitchell Data Version: OEM: AUG_13_V

Software Version: 7.0.487

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3