

**Claim Summary been saved successfully...**



**Property Damage Specialist**

P.O. Box 2002, Indio

California, United States

92202

## Claim Information

Claim Number : CO13010442

Policy Number :

Insurance Company : Robert Moreno Insurance

Adjuster : Brandt Faraone

Date of Loss : 2013-06-12

Whose Claim : Claimant

Owner Name : CARLOS GRODOY

Insured Name : GREG YESITSYAN

Claimant Name : CARLOS GRODOY

Inspection Location : RESIDENCE

## Appraisal Information

File Number : 07012013-1000020

Appraiser : Jaime Munoz

Reinspector : Not Assigned

Loss Type : Collision

Inspection Date : 2013-07-05

Assigned Date/Time : 2013-07-01 19:00:00

Assignment Type : Full Appraisal

ERT (Days) :

Possible Supplement : YES

## Vehicle Information

Year : 2007

Make : Toyota

Model : Corolla

Sub-model : S  
VIN : 1NXBR32E67Z918455  
Plate : 6AFR582  
State : California  
Milage : 177291  
Drivable : No  
Primary POI : REAR  
Secondary POI : FRONT  
Vehicle Condition : Fair  
Interior Condition : Fair  
Paint Condition : Fair  
Engine : Fair

## Repair Information

Recommendation : Total Loss  
Estimate 1 Total : 10426.16  
Estimate 2 Total : 0.00  
Estimate 1 Betterment : 0.00  
Estimate 2 Betterment : 0.00  
Supplement 1 Total : 0.00  
Supplement 1 Betterment : 0.00  
Supplement 2 Total : 0.00  
Supplement 2 Betterment : 0.00  
Supplement 3 Total : 0.00  
Supplement 3 Betterment : 0.00  
Supplement 4 Total : 0.00  
Supplement 4 Betterment : 0.00  
Subtotal : 10426.16  
Deductible : 0.00  
Original Net Loss : 10426.16  
Gross Total : 10426.16  
Supplement Net Loss : 0.00

## Tire Information

Make : GOODYEAR  
Size : 195/65R /15

Tired Depth (in 32nds)

L/F      7/32 R/F      7/32

L/R      7/32 R/R      7/32

Spare :

## Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

## Miscellaneous

Towing Charges :            N/A

Storage Per Day :           N/A

Days :

Approximate Total :        NaN

Rental Vehicle :            Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

## Claim Remarks

\*\*\*\*\* TOTAL LOSS \*\*\*\*\*

Completed inspection and estimate on the vehicle at residence in the town of Pasadena , CA. on 7/05/2013 . Front and rear end collision as photos show. Front bumper, front inner structural, right fender, front frame rails, ac unit , radiator, rear bumper, deck lid, rear inner structural , etc damaged due to loss. Estimate completed using prevailing labor rates in the area with industry accepted repair procedures. Excessive damage to the vehicle. Repairs exceeded 80% ACV. Therefore we suggest this vehicle appears to be a total loss. Vehicle remains at residence . Vehicle interior and exterior condition considered average for year and model. The

vehicle is not drivable. No commitments were made.

No copies of this appraisal were released. Appraisal assignment completed 7/07/2013. Jaime Munoz, Independent Appraiser. CCC Form and KBB value enclosed.No storage charges accruing.

Date: 7/7/2013 07:59 PM  
Estimate ID: CO13010442  
Estimate Version: 0  
Preliminary  
Profile ID: \* Robert Moreno Ins.

FOR SUPPLEMENT CALL RICH PEREA 760-275-6795 OR E MAIL  
pds9593@verizon.net

# PROPERTY DAMAGE SPECIALIST

P.O. BOX 2002, INDIO, CA 92201  
(760) 275-6795  
Fax: (760) 863-5349  
Email: pds9593@verizon.net

Damage Assessed By: Jaime Munoz

Appraised For: Brandt Faraone  
(714) 738-1383 ext. 2419

Condition Code: Fair  
Date of Loss: 6/12/2013  
Contact Date: 6/12/2013  
Payer: Insurance  
File Number: CO13010442  
Claim Number: CO13010442

Type of Loss: Collision  
Arrival Date: 7/3/2013  
Accident Date: 6/12/2013  
Deductible: 0.00

Insured: GEVORG YERITSYAN  
Claimant: CARLOS GODOY  
Address: 1308 E. COLORADO BLVD. APT # 101, PASADENA, CA 91106  
Owner: CARLOS GODOY  
Address: 1308 E. COLORADO BLVD. APT # 101, PASADENA, CA 91106  
Telephone:

Cell Phone: (626) 376-2895

Contact Phone: (818) 886-6600

Mitchell Service: 911754

Description: 2007 Toyota Corolla S  
Body Style: 4D Sed  
VIN: 1NXBR32E67Z918455  
Mileage: 177,291  
OEM/ALT: A  
Color: SILVER  
Options:

Vehicle Production Date: 4/07  
Drive Train: 1.8L Inj 4 Cyl 4A FWD  
License: 6AFR582 CA

Search Code: 975

PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, REAR WINDOW DEFOGGER  
MANUAL AIR CONDITION, TILT STEERING COLUMN, FOG LIGHTS, LEATHER STEERING WHEEL  
POWER ADJUSTABLE EXTERIOR MIRROR, AUTOMATIC TRANSMISSION, FRONT AIR DAM  
REAR AIR DAM, TINTED GLASS, VARIABLE ASSISTED STEERING, ANTI-THEFT SYSTEM  
DAYTIME RUNNING LIGHTS, AM/FM STEREO CD, FRONT BUCKET SEATS, INTERIOR AIR FILTER  
POWER LIFTGATE\TRUNK

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	100022	REF	REFINISH	R Frt Spoiler			C 0.7
2	100027	BDY	OVERHAUL	Frt Bumper Cover Assy			1.1 #
3	102343	BDY	REMOVE/REPLACE	Frt Bumper Cover	Remanufactured	176.48	INC #
4	AUTO	REF	REFINISH	Frt Bumper Cover			C 2.5
5	104161	BDY	REMOVE/REPLACE	Frt Bumper Impact Absorber	52611-02100	77.75	INC
6	100044	BDY	REMOVE/REPLACE	Frt Bumper Reinforcement Bar	52021-02060	177.84	0.4 #
7	AUTO	BDY	REMOVE/INSTALL	Frt Bumper Cover			INC #
8	102371	BDY	REMOVE/REPLACE	R Frt Bumper Spoiler	76081-02030-C0	431.82	INC
9	103046	BDY	REMOVE/INSTALL	Grille Assy			INC
10	103210	BDY	REMOVE/REPLACE	Grille	53100-02090	131.54	INC
11	100065	BDY	REMOVE/REPLACE	Grille Emblem	75311-02110	25.08	INC #
12	104164	BDY	REMOVE/REPLACE	Grille Bolt 2@9.94	53119-02050	19.88	
13	100068	BDY	CHECK/ADJUST	Headlamps			0.4

ESTIMATE RECALL NUMBER: 07/07/2013 19:50:02 CO13010442

Mitchell Data Version: JUN\_13\_V  
MAPP:JUN\_13\_V  
Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International  
All Rights Reserved

Page 1 of 4

14	102382	BDY	REMOVE/REPLACE	R Front Combination Lamp Assembly	Remanufactured	138.75	INC	#
15	100115	BDY	REMOVE/REPLACE	Hood Panel	53301-02110	396.79	1.2	
16	AUTO	REF	REFINISH	Hood Outside			C	2.3
17	AUTO	REF	REFINISH	Add For Hood Underside			C	1.2
18	100117	BDY	REMOVE/REPLACE	Hood Insulator Retainer 8@1.49	90467-A0003	11.92		
19	100118	BDY	REMOVE/REPLACE	Frnt Hood Seal	53381-02070	25.17	0.2	
20	100122	BDY	REMOVE/REPLACE	R Hood Hinge	53410-12410	28.99	0.2	#
21	AUTO	REF	REFINISH	R Hinge			C	0.5
22	AUTO	BDY	REMOVE/INSTALL	Hood Assy			INC	
23	100123	BDY	REMOVE/REPLACE	L Hood Hinge	53420-12330	28.99	0.2	#
24	AUTO	REF	REFINISH	L Hinge			C	0.5
25	100133	BDY	REMOVE/REPLACE	Hood Latch	53510-02230	49.88	INC	
26	100224	BDY	REMOVE/REPLACE	R Fender Panel	53801-02070	247.98	1.5	#
27	AUTO	REF	REFINISH	R Fender Outside			C	1.6
28	AUTO	REF	REFINISH	R Add To Edge Fender			C	0.5
29	100230	BDY	REMOVE/REPLACE	R Fender Liner	53875-02090	93.38	INC	
30	100236	BDY	REMOVE/REPLACE	R Fender Retainer 4@1.09	90467-10183	4.36		
31	100252	MCH	REMOVE/REPLACE	Evacuate & Recharge A/C	-M			1.4
32	100253	MCH	REMOVE/REPLACE	A/C Refrigerant Recovery	-M			0.3
33	100254	BDY	REMOVE/REPLACE	Front Body Radiator Support	-S	53201-02100	330.57	9.1 #
34	AUTO	REF	REFINISH	Radiator Support Complete				1.5
35	AUTO	MCH	REMOVE/REPLACE	Add To R&R Mechanical Components	-M			0.4 #
36	AUTO	REF	REFINISH	R Apron/Lower Side Rail Complete				1.5
37	100292	BDY	REMOVE/REPLACE	R Front Body Apron Assy	-S	53701-02120	247.44	6.0 #
38	100311	BDY	REPAIR	R Otr Front Body Side Rail	-S	Existing		4.0* #
39	100315	BDY	REPAIR	R Inr Front Body Side Rail Assy	-S	Existing		3.0* #
40	101156	REF	BLEND	R Frt Door Outside			C	0.9
41	101176	BDY	REMOVE/INSTALL	R Frt Otr Belt Moulding				0.2
42	101178	BDY	REMOVE/INSTALL	R Frt Door Mirror				0.7 #
43	101309	BDY	REMOVE/INSTALL	R Frt Otr Door Handle				0.4
44	931105	MCH	REMOVE/REPLACE	Four Wheel Alignment	Sublet	89.95	*	0.0*
45	936003		ADD'L COST	Coolant		12.00	*	
46	102002	REF	REFINISH	Add For Edge & Inside				0.8
47	103763	BDY	REMOVE/REPLACE	Rear Body Panel	58307-02120	310.48	9.2	#
48	AUTO	REF	REFINISH	Rear Body Panel			C	1.8
49	102008	BDY	REMOVE/REPLACE	Rear Body Floor Pan	58311-02904	478.68	12.0	#
50	AUTO	REF	REFINISH	Floor Pan Assy				1.5
51	102067	REF	REFINISH	R Rear Cover			C	0.5
52	102068	REF	REFINISH	L Rear Cover			C	0.5
53	102071	REF	REFINISH	Rear Impact Bar				0.5
54	102074	BDY	OVERHAUL	Rear Bumper Cover Assy				0.5 #
55	102077	BDY	REMOVE/REPLACE	Rear Bumper Cover	Remanufactured	182.33	INC	#
56	AUTO	REF	REFINISH	Rear Bumper Cover			C	2.3
57	104290	BDY	REMOVE/REPLACE	R Rear Bumper Spoiler	76087-02010-J2	180.91	0.2	
58	102103	BDY	REMOVE/REPLACE	R Rear Bumper Seal	52591-02050	21.46	INC	
59	102104	BDY	REMOVE/REPLACE	L Rear Bumper Seal	52592-02040	20.86	INC	
60	103784	BDY	REMOVE/REPLACE	Rear Bumper Impact Absorber	52615-02060	80.13	INC	
61	102109	BDY	REMOVE/REPLACE	Rear Bumper Reinforcement Bar	52023-02080	191.21	INC	#
62	AUTO	BDY	REMOVE/INSTALL	Rear Bumper Cover			INC	#
63	936012		ADD'L COST	Hazardous Waste Disposal		3.00	*	
64	936014		ADD'L COST	Flex Additive		3.00	*	
65	936016		ADD'L COST	Weld Thru Primer		5.00	*	
66	936018		ADD'L COST	R134A Freon & Oil		25.00	*	
67	933006	FRM	ADD'L OPR	Frame/Rack Set Up				2.0*
68	933030	FRM	ADD'L OPR	Pull For Sway				2.0*
69	933034	FRM	ADD'L OPR	Pull For Sag				2.0*
70	933035	FRM	ADD'L OPR	Unibody Pull				2.0*
71	AUTO	REF	ADD'L OPR	Clear Coat				3.7
72	933003	BDY *	ADD'L OPR	Tint Color				0.5*
73	933004	BDY	ADD'L OPR	Undercoating		8.00	*	0.5*
74	900500	BDY *	REMOVE/REPLACE	Caulk & seal	** QUAL REPL PART	3.00	*	0.3*
75	933005	BDY	ADD'L OPR	Restore Corrosion Protection		7.00	*	0.3*

ESTIMATE RECALL NUMBER: 07/07/2013 19:50:02 CO13010442

Mitchell Data Version: JUN\_13\_V  
 MAPP:JUN\_13\_V  
 Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International  
 All Rights Reserved

Date: 7/7/2013 07:59 PM  
 Estimate ID: CO13010442  
 Estimate Version: 0  
 Preliminary  
 Profile ID: \* Robert Moreno Ins.

76	900500	BDY *	REPAIR	Clean adhesive	Existing		0.5*
77	900500	BDY *	REPAIR	Weld spot damage	Existing		0.5*
78	900500	BDY *	REPAIR	Pinch clamp damage	Existing		0.5*
79	900500	REF *	REFINISH/REPAIR	Pinch clamp damage	Existing		0.5*
80	900500	BDY *	REMOVE/REPLACE	Cover car for primer	** QUAL REPL PART	5.00 *	0.3*
81	900500	BDY *	REMOVE/REPLACE	Mask jams for overspay	** QUAL REPL PART	3.00 *	0.3*
82	900500	BDY *	REMOVE/INSTALL	Set back main harness wiring	Existing		0.5*
83	900500	MCH *	REPAIR	Disconnect & reconnect electrical	Existing		0.5*
84	AUTO		ADD'L COST	Paint/Materials		903.00 *	

\* - Judgment Item

# - Labor Note Applies

\*\* QUAL REPL PART - Quality Replacement Parts

C - Included in Clear Coat Calc

RPW HEADLAMPS  
 1809 N. 9TH ST.  
 INDIANOLA  
 IA 50125  
 (800) 336-4028

METRO DISTRIBUTORS  
 2800 EAST LA CADENA DR.  
 RIVERSIDE  
 CA 92507  
 (951) 682-1025

14	** 8111002370	138.75	3	** TO1000298R	176.48
			55	** TO1100209R	182.33

## Estimate Totals

I. Labor Subtotals						II. Part Replacement Summary				Amount
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals					
Body	54.7	50.00	15.00	0.00	2,750.00	Taxable Parts				4,121.67
Refinish	25.8	50.00	0.00	0.00	1,290.00	Sales Tax	@	9.000%		370.95
Frame	8.0	65.00	0.00	0.00	520.00					
Mechanical	2.6	95.00	0.00	0.00	247.00	Non-Taxable Parts				89.95
						Total Replacement Parts Amount				4,582.57
Non-Taxable Labor					4,807.00					
Labor Summary	91.1				4,807.00					
III. Additional Costs					Amount	IV. Adjustments				Amount
Taxable Costs					951.00	Insurance Deductible				0.00
Sales Tax			@	9.000%	85.59	Customer Responsibility				0.00
Total Additional Costs					1,036.59					
Paint Material Method: Rates Init Rate = 35.00 , Init Max Hours = 99.9, Addl Rate = 0.00										
						I. Total Labor:				4,807.00
						II. Total Replacement Parts:				4,582.57
						III. Total Additional Costs:				1,036.59
						Gross Total:				10,426.16
						IV. Total Adjustments:				0.00
						Net Total:				10,426.16
										TOTAL LOSS

ESTIMATE RECALL NUMBER: 07/07/2013 19:50:02 CO13010442

Mitchell Data Version: JUN\_13\_V

MAPP:JUN\_13\_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International  
 All Rights Reserved

Page 3 of 4

**This is a preliminary estimate.**  
**Additional changes to the estimate may be required for the actual repair.**

Point(s) of Impact

15 Total Loss (P)

Insurance Co: Robert Moreno Insurance Services  
Address: P.O. BOX 5185  
FULLERTON, CA 92838  
Telephone: (714) 738-1383  
Fax Phone: (714) 738-5035

Inspection Site: HOME  
Address: 3455 BRANDON ST  
PASADENA, CA 91107  
Inspection Date: 7/5/2013

Body Shop: OWNER'S CHOICE OF SHOP

\*\*\*COLLECT ALL FROM OWNER\*\*\*  
\*\*\*THIS IS NOT AN AUTHORIZATION FOR REPAIR OR  
GUARANTEE OF PAYMENT.\*\*\*  
\*\*\*ANY DAMAGE NOT ON THIS ESTIMATE MUST BE  
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER.  
FAILURE TO HAVE REINSPECTION WILL RESULT IN  
NON-PAYMENT!!!!!!!!!!\*\*\*

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.  
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND  
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

Pursuant to California Code of Regulations Section 2695.8(g)  
The insurance company named on this damage estimate warrants that all  
non-original equipment replacement parts listed herein are of like,  
kind, quality, safety, fit and performance as original equipment  
manufacturer replacement crash parts.