

 **View Claim Summary - File Number: 06122013-1000025-S1**

[GO BACK](#)

Claim Summary been saved successfully...



Property Damage Specialist
P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : CO13008763
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Anni Chung
Date of Loss : -0001-11-30
Whose Claim : Claimant
Owner Name : MARIA ANN DAVIS
Insured Name : NA NA
Claimant Name : MARIA ANN DAVIS
Inspection Location :

Appraisal Information

File Number : 06122013-1000025-S1
Appraiser : Roberta Kear
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-06-07
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) : 2
Possible Supplement :

Vehicle Information

Year : 2008
Make : Land Rover
Model : Range Rover
Sub-model :

VIN : SALFR24N28H066704
Plate : 6GXZ844
State : California
Milage : 42227
Drivable : Yes
Primary POI : REAR
Secondary POI :
Vehicle Condition : Good
Interior Condition : good
Paint Condition : good
Engine : Good

Repair Information

Recommendation : Repairable
Estimate 1 Total : 1426.02
Estimate 2 Total : 0.00
Estimate 1 Betterment : 0.00
Estimate 2 Betterment : 0.00
Supplement 1 Total : 413.90
Supplement 1 Betterment : 0.00
Supplement 2 Total : 0.00
Supplement 2 Betterment : 0.00
Supplement 3 Total : 0.00
Supplement 3 Betterment : 0.00
Supplement 4 Total : 0.00
Supplement 4 Betterment : 0.00
Subtotal : 1839.92
Deductible : 0.00
Original Net Loss : 1839.92
Gross Total : 1426.02
Supplement Net Loss : 413.90

Tire Information

Make :
Size :
Tired Depth (in 32nds)

L/F R/F

L/R R/R

Spare :

Shop Information

Shop Name : Golden Hammer Auto Body

Address 1 : 2231 Butler Ave.

Address 2 :

City : Los Angeles

State : California

Zip : 90064

Phone Number : 310-479-4311

Fax : 310-444-7108

Agreed Price : Yes

Federal Tax ID # : 95-3922712

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total : 0.00

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

07/31/2013 Received supplement request from shop for ppl's and minor additional items and labor rate adjustment.

Called shop and obtained invoices, discussed labor rates and negotiated shop request to cut holes for sensors.

Bumper cover does not come with sensor holes and shop has to measure and cut, made concession to allow for this operation, as well as time to transfer sensor brackets/sensors to new cover.

No open items at this time. Shop will complete and release vehicle.

This vehicle is still repairable.

I emailed a copy of this estimate tot he shop at goldenhammerla@gmail.com

Date: 7/31/2013 09:21 AM
Estimate ID: CO13008763
Estimate Version: 0
Supplement: 1 (F F) 7/31/2013 09:12:00 AM
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA, 760-275-6795 OR EMAIL
PDS9593@VERIZON.NET

Property Damage Specialist

P.O. BOX 3237, INDIO, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: PDS9593@VERIZON.NET

Damage Assessed By: Roberta Kear
Supplemented By: Roberta Kear

Appraised For: ROBERT MORENO INS - ANNI CHUNG

Type of Loss: Property Damage
Date of Loss: 5/ 7/2013
Deductible: NONE
File Number: CO13008763
Claim Number: CO13008763-C

Arrival Date: 6/ 7/2013

Insured: ROSE LIDIA FARJARDO
Claimant: MARIA ANN DAVIS
Address: 1400 CALIFORNIA AVE #306, SANTA MONICA, CA 90403
Telephone: Home Phone: (989) 295-1643
Owner: MARIA ANN DAVIS
Address: 1400 CALIFORNIA AVE #306, SANTA MONICA, CA 90403
Telephone: Home Phone: (989) 295-1643

Mitchell Service: 910867

Description: 2008 Land Rover LR2 HSE
Body Style: 4D Ut
VIN: SALFR24N28H066704
Mileage: 41,455
OEM/ALT: A
Color: BLACK
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW
POWER STEERING, REAR WINDOW DEFOGGER, CRUISE CONTROL, TILT STEERING COLUMN
LEATHER SEAT, POWER PASSENGER SEAT, TELESCOPIC STEERING COLUMN, SPOILER
PREMIUM SOUND SYSTEM, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS
ALUM/ALLOY WHEELS, AUXILIARY INPUT, BLUETOOTH WIRELESS CONNECTIVITY
LEATHER STEERING WHEEL, FRONT AIR DAM, TINTED GLASS, AUTO AIR CONDITION
TRIP COMPUTER, SUBWOOFER, SIDE AIRBAGS, ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS
INTERIOR AUTOMATIC DAY/NIGHT OR ELECTROCHROMATIC MIRROR
SIDE HEAD CURTAIN AIRBAGS, AM/FM STEREO CD CHANGER/MP3 PLAYER
ELECTRONIC PARKING AID, ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS
FRONT HEATED SEATS, FRONT SEATS WITH POWER LUMBAR SUPPORT, INTERIOR AIR FILTER
KEYLESS ENTRY SYSTEM, PANORAMIC SUNROOF/MOONROOF, POWER DISC BRAKES
POWER HEATED EXTERIOR MIRRORS, RAIN SENSING WIPERS, REAR SPOILER
REAR WINDOW DIVERSITY ANTENNA, REAR WINDOW WIPER, STEERING WHEEL AUDIO CONTROLS

Vehicle Production Date: 10/07
Drive Train: 3.2L Inj 6 Cyl AWD
License: 6GXZ844 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Rear Bumper</u>							
1	001589	BDY	OVERHAUL	Rear Bumper Cover Assy			1.7 #
2		BDY	REMOVE/INSTALL	R Rear Combination Lamp			0.3
3		BDY	REMOVE/INSTALL	L Rear Combination Lamp			0.3
4	001590	BDY	REMOVE/REPLACE	Rear Add w/Parking Sensor			0.4

This estimate has been re-calculated with a modified profile.

ESTIMATE RECALL NUMBER: 07/23/2013 06:49:30 CO13008763

Mitchell Data Version: OEM: MAY_13_V
MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

S1	5	001869	BDY	REMOVE/REPLACE	Rear Bumper Cover	LR031908	730.30	*	INC	#
	6		REF	REFINISH	Rear Bumper Cover				C	2.8
S1	7	000036	BDY	REMOVE/REPLACE	Rear Bumper Insert	LR005751	92.21	*	INC	#
S1	8	000037	BDY	REMOVE/INSTALL	R Rear Otr Parking Bracket	Existing			0.3*	#
S1	9	000038	BDY	REMOVE/INSTALL	L Rear Otr Parking Bracket	Existing			0.3*	#
S1	10	000039	BDY	REMOVE/INSTALL	R Rear Inr Parking Bracket	Existing			0.3*	#
S1	11	000040	BDY	REMOVE/INSTALL	L Rear Inr Parking Bracket	Existing			0.3*	#
<u>MANUAL ENTRIES</u>										
S1	12	900500	BDY *	REPAIR	CUT HOLES FOR SENSORS IN BUMPER COVER	Existing			2.0*	
<u>Rear Bumper</u>										
S1	13	000041	BDY	REMOVE/REPLACE	Rear Parking Sensor Unit	LR039635	121.78	*	INC	#
	14		BDY	REMOVE/INSTALL	Rear Bumper Cover				INC	#
S1	15	001248	BDY	REMOVE/REPLACE	L Rear Bumper Reflector	LR006349	46.78	*	INC	
<u>Additional Costs & Materials</u>										
S1	16	936012		ADD'L COST	Hazardous Waste Disposal		3.00	*		
<u>MANUAL ENTRIES</u>										
	17	900500	MCH *	REPAIR	RESET ELECTRICAL COMPONENTS	Existing			1.0*	
	18				RESET PARKING SYSTEM					
<u>Additional Costs & Materials</u>										
	19	936014		ADD'L COST	Flex Additive		8.00	*		
<u>ADDITIONAL OPERATIONS</u>										
	20		REF	ADD'L OPR	Clear Coat				1.1	
	21	933003	BDY *	ADD'L OPR	Tint Color				0.5*	
S1	22	933017	BDY *	ADD'L OPR	Finish Sand And Buff				0.5*	
	23				CONCESSION TO REACH AGREED PRICE					
<u>Additional Costs & Materials</u>										
	24			ADD'L COST	Paint/Materials		132.60	*		

* - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc

Prior Damage:
FRONT BUMPER COVER

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	6.9	48.00	0.00	0.00	331.20	Taxable Parts	991.07
Refinish	3.9	48.00	0.00	0.00	187.20	Sales Tax @ 9.000%	89.20
Mechanical	1.0	85.00	0.00	0.00	85.00		
	Non-Taxable Labor				603.40	Total Replacement Parts Amount	1,080.27
Labor Summary	11.8				603.40		

This estimate has been re-calculated with a modified profile.

ESTIMATE RECALL NUMBER: 07/23/2013 06:49:30 CO13008763

Mitchell Data Version: OEM: MAY_13_V

MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

III. Additional Costs	Amount	IV. Adjustments	Amount
Taxable Costs	140.60	Insurance Deductible	0.00
Sales Tax @ 9.000%	12.65	Customer Responsibility	0.00
Non-Taxable Costs	3.00		
Total Additional Costs	156.25		

Paint Material Method: Rates
Init Rate = 34.00 , Init Max Hours = 99.9, Addl Rate = 0.00

I.	Total Labor:	603.40
II.	Total Replacement Parts:	1,080.27
III.	Total Additional Costs:	156.25
	Gross Total:	1,839.92
IV.	Total Adjustments:	0.00
	Net Total:	1,839.92
	Less Original Net Total:	1,426.02
	Net Supplement Amount:	413.90
	S1: Roberta Kear	413.90

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

6 Rear Center (P)

Insurance Co: ROBERT MORENO INSURANCE SERVICES
Address: P.O. BOX 5185
FULLERTON, CA 92838
Telephone: (714) 578-3366
Fax Phone: (714) 738-5035

Inspection Site: CLAIMANT'S RESIDENCE
Address: 1400 CALIFORNIA AVE
SANTA MONICA, CA 90403
(989) 295-1643
Inspection Date: 6/ 7/2013

Body Shop: GOLDEN HAMMER AUTO BODY
Address: 2231 UTLER AVE.
LOS ANGELES, CA 90064
Telephone: (310) 479-4311
Fax Phone: (310) 444-7108
State Lic. No: 95-3922712

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

This estimate has been re-calculated with a modified profile.

ESTIMATE RECALL NUMBER: 07/23/2013 06:49:30 CO13008763

Mitchell Data Version: OEM: MAY_13_V
MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Date: 7/31/2013 09:21 AM
 Estimate ID: CO13008763
 Unrelated Prior Damage
 Estimate Version: 0
 Supplement: 1 (F F) 7/31/2013 09:12:00 AM
 Preliminary
 Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA, 760-275-6795 OR EMAIL
 PDS9593@VERIZON.NET

Property Damage Specialist

P.O. BOX 3237, INDIO, CA 92201
 (760) 275-6795
 Fax: (760) 863-5349
 Email: PDS9593@VERIZON.NET

Unrelated Prior Damage

Damage Assessed By: Roberta Kear
 Supplemented By: Roberta Kear

Appraised For: ROBERT MORENO INS - ANNI CHUNG

Type of Loss: Property Damage
 Date of Loss: 5/ 7/2013

Arrival Date: 6/ 7/2013

File Number: CO13008763
 Claim Number: CO13008763-C

Insured: ROSE LIDIA FARJARDO
 Claimant: MARIA ANN DAVIS
 Address: 1400 CALIFORNIA AVE #306, SANTA MONICA, CA 90403
 Telephone: Home Phone: (989) 295-1643
 Owner: MARIA ANN DAVIS
 Address: 1400 CALIFORNIA AVE #306, SANTA MONICA, CA 90403
 Telephone: Home Phone: (989) 295-1643

Mitchell Service: 910867

Description: 2008 Land Rover LR2 HSE
 Body Style: 4D Ut
 VIN: SALFR24N28H066704
 Mileage: 41,455
 OEM/ALT: A
 Color: BLACK
 Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW
 POWER STEERING, REAR WINDOW DEFOGGER, CRUISE CONTROL, TILT STEERING COLUMN
 LEATHER SEAT, POWER PASSENGER SEAT, TELESCOPIC STEERING COLUMN, SPOILER
 PREMIUM SOUND SYSTEM, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS
 ALUM/ALLOY WHEELS, AUXILIARY INPUT, BLUETOOTH WIRELESS CONNECTIVITY
 LEATHER STEERING WHEEL, FRONT AIR DAM, TINTED GLASS, AUTO AIR CONDITION
 TRIP COMPUTER, SUBWOOFER, SIDE AIRBAGS, ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS
 INTERIOR AUTOMATIC DAY/NIGHT OR ELECTROCHROMATIC MIRROR
 SIDE HEAD CURTAIN AIRBAGS, AM/FM STEREO CD CHANGER/MP3 PLAYER
 ELECTRONIC PARKING AID, ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS
 FRONT HEATED SEATS, FRONT SEATS WITH POWER LUMBAR SUPPORT, INTERIOR AIR FILTER
 KEYLESS ENTRY SYSTEM, PANORAMIC SUNROOF/MOONROOF, POWER DISC BRAKES
 POWER HEATED EXTERIOR MIRRORS, RAIN SENSING WIPERS, REAR SPOILER
 REAR WINDOW DIVERSITY ANTENNA, REAR WINDOW WIPER, STEERING WHEEL AUDIO CONTROLS

Vehicle Production Date: 10/07
 Drive Train: 3.2L Inj 6 Cyl AWD
 License: 6GXZ844 CA
 Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
-----------	--------------	------------	-----------	-----------------------	------------------------	---------------	-------------

Front Bumper

This estimate has been re-calculated with a modified profile.

ESTIMATE RECALL NUMBER: 07/23/2013 06:49:30 CO13008763

Mitchell Data Version: OEM: MAY_13_V

MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
 All Rights Reserved

Page 1 of 3

Date: 7/31/2013 09:21 AM
 Estimate ID: CO13008763
 Unrelated Prior Damage
 Estimate Version: 0
 Supplement: 1 (F F) 7/31/2013 09:12:00 AM
 Preliminary
 Profile ID: * PDS

1	002264	BDY	REPAIR	Frt Bumper Cover Assy	Existing	4.0* #
2		REF	REFINISH	Frt Bumper Cover		C 2.5 #
<u>ADDITIONAL OPERATIONS</u>						
3		REF	ADD'L OPR	Clear Coat		1.0
<u>Additional Costs & Materials</u>						
4			ADD'L COST	Paint/Materials		119.00 *

* - Judgment Item

- Labor Note Applies

C - Included in Clear Coat Calc

Prior Damage:
 FRONT BUMPER COVER

Estimate Totals

I. Labor Subtotals						II. Part Replacement Summary	
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals		Amount
Body	4.0	48.00	0.00	0.00	192.00		
Refinish	3.5	48.00	0.00	0.00	168.00	Total Replacement Parts Amount	0.00
Non-Taxable Labor					360.00		
Labor Summary	7.5				360.00		
III. Additional Costs					Amount	IV. Adjustments	
Taxable Costs					119.00	Total Adjustments:	
Sales Tax					10.71	0.00	
@ 9.000%							
Total Additional Costs					129.71		
Paint Material Method: Rates							
Init Rate = 34.00 , Init Max Hours = 99.9, Addl Rate = 0.00							
						I.	Total Labor:
						II.	Total Replacement Parts:
						III.	Total Additional Costs:
							Gross Total:
							489.71
						IV.	Total Adjustments:
							Unrelated Damage Net Total:
							0.00
							489.71

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

6 Rear Center (P)

This estimate has been re-calculated with a modified profile.

ESTIMATE RECALL NUMBER: 07/23/2013 06:49:30 CO13008763

Mitchell Data Version: OEM: MAY_13_V

MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
 All Rights Reserved

Page 2 of 3

Date: 7/31/2013 09:21 AM
Estimate ID: CO13008763
Unrelated Prior Damage
Estimate Version: 0
Supplement: 1 (F F) 7/31/2013 09:12:00 AM
Preliminary
Profile ID: * PDS

Insurance Co: ROBERT MORENO INSURANCE SERVICES
Address: P.O. BOX 5185
FULLERTON, CA 92838
Telephone: (714) 578-3366
Fax Phone: (714) 738-5035

Inspection Site: CLAIMANT'S RESIDENCE
Address: 1400 CALIFORNIA AVE
SANTA MONICA, CA 90403
(989) 295-1643
Inspection Date: 6/ 7/2013

Body Shop: GOLDEN HAMMER AUTO BODY
Address: 2231 UTLER AVE.
LOS ANGELES, CA 90064
Telephone: (310) 479-4311
Fax Phone: (310) 444-7108
State Lic. No: 95-3922712

This estimate has been re-calculated with a modified profile.

ESTIMATE RECALL NUMBER: 07/23/2013 06:49:30 CO13008763

Mitchell Data Version: OEM: MAY_13_V

MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3

Property Damage Specialist

P.O. BOX 3237, INDIO, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: PDS9593@VERIZON.NET

Supplement Delta Report Comparison of Estimate CO13008763 Supplement 0 and Supplement 1

Damage Assessed By: Roberta Kear
Supplemented By: Roberta Kear

Insured: ROSE LIDIA FARJARDO
Owner: MARIA ANN DAVIS
Vehicle Description: 2008 Land Rover LR2 HSE
Date of Loss: 5/ 7/2013

Line Item	Labor Type	Operation	Line Item Description	Part Type	Dollar Amount	Labor Units	CEG Unit
Changed Entries							
4	BDY	REMOVE/REPLACE	Rear Bumper Cover	LR031908	676.20	INC	1.7T
S1 5<	BDY	REMOVE/REPLACE	Rear Bumper Cover	LR031908	730.30 *<	INC	1.7T
6	BDY	REMOVE/REPLACE	Rear Bumper Insert	LR005751	64.03	INC	0.4T
S1 7<	BDY	REMOVE/REPLACE	Rear Bumper Insert	LR005751	92.21 *<	INC	0.4T
7	BDY	REMOVE/REPLACE	Rear Parking Sensor Unit	LR039635	92.25	0.1	0.1T
S1 13<	BDY	REMOVE/REPLACE	Rear Parking Sensor Unit	LR039635	121.78 *<	INC <	0.1T
9		ADD'L COST	Hazardous Waste Disposal		3.00 *	0.0	T
S1 16<		ADD'L COST	Hazardous Waste Disposal		3.00 *	0.0	<
15		ADD'L COST	Paint/Materials		124.80 *	0.0	T
24<		ADD'L COST	Paint/Materials		132.60 *<	0.0	T
Added Entries							
S1 4	BDY	REMOVE/REPLACE	Rear Add w/Parking Sensor			0.4	0.4
S1 8	BDY	REMOVE/INSTALL	R Rear Otr Parking Bracket	Existing		0.3*	
S1 9	BDY	REMOVE/INSTALL	L Rear Otr Parking Bracket	Existing		0.3*	
S1 10	BDY	REMOVE/INSTALL	R Rear Inr Parking Bracket	Existing		0.3*	
S1 11	BDY	REMOVE/INSTALL	L Rear Inr Parking Bracket	Existing		0.3*	
S1 12	BDY	REPAIR	CUT HOLES FOR SENSORS IN BUMPER COVER	Existing		2.0*	
S1 15	BDY	REMOVE/REPLACE	L Rear Bumper Reflector	LR006349	46.78 *	INC	0.2T
S1 22	BDY	ADD'L OPR	Finish Sand And Buff			0.5*	
23			CONCESSION TO REACH AGREED PRICE			0.0	

Global Changes

Labor Rates	From:	To:	Adjustments	From:	To:
Body	42.00	48.00			
Refinish	42.00	48.00			
Glass	42.00	48.00			

Estimate profile calculation settings (other than labor rates and adjustments) have changed.

ESTIMATE RECALL NUMBER: 7/23/2013 06:49:30 CO13008763

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 2

Date: 7/31/2013 09:21 AM
Estimate ID: CO13008763
Estimate Version: 0
Supplement: 1 (F F) 7/31/2013 09:12:00 AM
Profile ID: * PDS

		Amount
Original Estimate:		1,426.02
Supplement 1	413.90	
Orig Total Tax	87.14	
Supp 1 Total Tax	101.85	
Net Supplement Amount	413.90	
Net Total		1,839.92
	Program Calc Versions	Data Versions
Supp 0	7.0.485	MAY_13_V
Supp 1	7.0.485	MAY_13_V

ESTIMATE RECALL NUMBER: 7/23/2013 06:49:30 CO13008763

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 2 of 2

HORNBURG JAGUAR / LAND ROVER SANTA MONICA



"The Oldest Jaguar Dealer in the West"
3300 Olympic Boulevard
Santa Monica, California 90404



PHONE: (310) 453-3377

FAX: (310) 453-6062

WHOLESALE DIRECT LINE: 1 (800) 300-5247

Leas est.

DISCLAIMER OF WARRANTIES - Any warranties on the products sold hereby are those made by the manufacturer. The Seller, HORNBURG JAGUAR, hereby expressly disclaims all warranties, either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose, and HORNBURG JAGUAR neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

NO REFUNDS WITHOUT THIS INVOICE.
MERCHANDISE NOT RETURNABLE AFTER 10 DAYS.
15% HANDLING CHARGE WILL BE MADE ON RETURNED MERCHANDISE.
ELECTRICAL & SPECIAL ORDER SALES ARE FINAL.
PARTS RETURNED MUST BE IN ORIGINAL CONTAINER
AND IN RESALEABLE CONDITION.

I have read, understood and accept all provision of the statements.

RECEIVED
BY

DATE ENTERED	YOUR ORDER NO.	DATE SHIPPED	INVOICE DATE	INVOICE NUMBER
22 JUL 13	52167	22 JUL 13	22 JUL 13	83939

SOLD TO ACCOUNT NO. 15189
GOLDEN HAMMER
2231 BUTLER AVE
LOS ANGELES, CA 90064-1501

SHIP TO PAGE 1 OF 1

SHIP VIA		SLSM.	B/L NO.	TERMS		F.O.B. POINT	
		299	(310) 479-4311	CHARGE		09:12:27	
QTY	SHIP	S.O.	PART NO.	DESCRIPTION	LIST	NET	AMOUNT
1		0	LR039635	23407 SENSOR - P	121.77	97.42	97.42
1		0	LR031908	40102 BUMPER - R	730.30	584.24	584.24
THIS PART IS NOT RETURNABLE							
1		0	LR005751	33603 PLATE	92.21	73.77	73.77
SPECIAL ORDERS ARE NOT RETURNABLE * * * * * DAMAGED PARTS WILL NOT BE ACCEPTED AFTER 24HRS. INSPECT PART IMMEDIATELY THANK YOU FOR YOUR BUSINESS!!!!				PARTS		755.43	
				SUBLET			
				FREIGHT		0.00	
				SALES TAX		0.00	
CUSTOMER'S SIGNATURE				TOTAL			\$755.43
X							

Parts
Department
Hours:

Monday - Friday
7:30 am - 5:30 pm

*Thank
You
For
Your
Business!*

Bumper on dock -

HORNBURG JAGUAR / LAND ROVER SANTA MONICA



"The Oldest Jaguar Dealer in the West"
3300 Olympic Boulevard
Santa Monica, California 90404



PHONE: (310) 453-3377

FAX: (310) 453-6062

WHOLESALE DIRECT LINE: 1 (800) 300-5247

Dear est.

DISCLAIMER OF WARRANTIES - Any warranties on the products sold hereby are those made by the manufacturer. The Seller, HORNBURG JAGUAR, hereby expressly disclaims all warranties, either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose, and HORNBURG JAGUAR neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

NO REFUNDS WITHOUT THIS INVOICE.
MERCHANDISE NOT RETURNABLE AFTER 10 DAYS.
15% HANDLING CHARGE WILL BE MADE ON RETURNED MERCHANDISE.
ELECTRICAL & SPECIAL ORDER SALES ARE FINAL.
PARTS RETURNED MUST BE IN ORIGINAL CONTAINER
AND IN RESALEABLE CONDITION.

I have read, understood and accept all provision of the statements.

RECEIVED
BY _____

DATE ENTERED	YOUR ORDER NO.	DATE SHIPPED	INVOICE DATE	INVOICE NUMBER
22 JUL 13	52167	22 JUL 13	22 JUL 13	83950

SOLD TO ACCOUNT NO. 15189
GOLDEN HAMMER
2231 BUTLER AVE
LOS ANGELES, CA 90064-1501

SHIP TO PAGE 1 OF 1

SHIP VIA		SLSM.	B/L NO.	TERMS	F.O.B. POINT	
		299	(310) 479-4311	CHARGE	10:41:23	
QUANTITY	PART NO.	DESCRIPTION		LIST	NET	AMOUNT
1	LR006349	129 REFLECTOR		46.78	37.42	37.42
<p>**SPECIAL ORDERS ARE NOT RETURNABLE** * * * * * DAMAGED PARTS WILL NOT BE ACCEPTED AFTER 24HRS. INSPECT PART IMMEDIATELY THANK YOU FOR YOUR BUSINESS!!!!</p>				<p>PARTS 37.42</p> <p>SUBLET</p> <p>FREIGHT 0.00</p> <p>SALES TAX 0.00</p> <p>TOTAL \$37.42</p>		
CUSTOMER'S SIGNATURE						
X <i>[Signature]</i>						

**Parts
Department
Hours:**

Monday - Friday
7:30 am - 5:30 pm

*Thank
You
For
Your
Business!*