

Property Damage Specialist
P.O. BOX 3237, INDIO, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: PDS9593@VERIZON.NET

APPRAISAL REPORT

DAMAGE ASSESSED BY: ROBERTA KEAR

FILE NUMBER: CO13009886
CLAIM NUMBER: CO13009886
DATE OF LOSS: 6/ 2/2013
TYPE OF LOSS: Collision
APPRAISED FOR: ROBERT MORENO INSURANCE - LORENA BAUTISTA

ASSIGNMENT DATE: None
CONTACT DATE: None
INSPECTION DATE: 6/ 6/2013
REC'D DATE: None

Point(s) of Impact

6 Rear Center (P), 12 Front Center (S)

INSURED: DELMY ESPERANZ ESCOBAR FLORES
P.O. BOX 90696
LONG BEACH, CA 90809
(562) 607-1580

CLAIMANT: None

OWNER: DELMY ESPERANZ ESCOBAR FLORES
P.O. BOX 90696
LONG BEACH, CA 90809
(562) 607-1580

BODY SHOP: M.R. AUTO BODY COLLISION
1849 W GAGE AVE
LOS ANGELES, CA 90047
(323) 752-3946

HOVAK

FAX: (323) 752-3953
TIN 20-0802347

INSPECTION SITE: M.R. AUTO BODY
1849 W GAGE AVE
LOS ANGELES, CA 90047
(323) 752-3953

QUALITY RECYCLED PARTS: No
AFTERMARKET NEW PARTS: Yes
VEHICLE DRIVEABLE: No

Comments:

06/06/2013 I inspected insured's 2013 Toyota Rav 4 at M>R Auto Body Collision at approximately 11:20 am. I met with Hovik at the shop. I noted damage to both the front and rear of customer's vehicle, approximate repair time is 14 days.

This was a moderate impact to the rear of customer's vehicle, and minor to moderate impact to the front of customer's vehicle with no airbag deployment.

Did not completed lkq/qrp search as vehicle is new with only 1719 miles. Reviewed estimate with shop and shop removed front bumper cover for me while I was there to see internal damage to front end

Negotiated repair times, replacement items and shop labor rates.

Open items include possible minor internal damage after tear down, clips, brackets, possible left front headlight, appears loose but could not see damage.

This vehicle is repairable.

Towing was \$130.00, a copy of the tow bill is included in the file.

I EMAILED A COPY OF THIS ESTIMATE TO THE SHOP AT MRABC@SBCGLOBAL.NET

COMPARISON ESTIMATE:	0.00	TOWING:	0.00	ACTUAL CASH VALUE:	22,825.00
APPRAISER ESTIMATE:	10,200.70	STORAGE:	0.00	SALVAGE VALUE:	0.00
AGREED UPON AMOUNT:	0.00	DEDUCTIBLE:	1,000.00	SETTLEMENT:	0.00
				REPAIR VS. ACV:	0.00
DRAFT/CHECK NUMBER:	0			ESTIMATE FEE:	0.00
DRAFT/CHECK AMOUNT:	0.00			TRAVEL EXPENSE:	0.00
DATE ISSUED:	None			PHOTO EXPENSE:	0.00
				MISC EXPENSE:	0.00
				TOTAL CHARGES:	0.00

Date: 6/10/2013 07:06 AM
 Estimate ID: CO13009886
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA, 760-275-6795 OR EMAIL
 PDS9593@VERIZON.NET

Property Damage Specialist

P.O. BOX 3237, INDIO, CA 92201
 (760) 275-6795
 Fax: (760) 863-5349
 Email: PDS9593@VERIZON.NET

Damage Assessed By: ROBERTA KEAR

Appraised For: ROBERT MORENO INSURANCE - LORENA BAUTISTA

Condition Code: Good
 Date of Loss: 6/ 2/2013
 Deductible: 1,000.00
 File Number: CO13009886
 Claim Number: CO13009886

Type of Loss: Collision

Insured: DELMY ESPERANZ ESCOBAR FLORES
 Owner: DELMY ESPERANZ ESCOBAR FLORES
 Address: P.O. BOX 90696, LONG BEACH, CA 90809
 Telephone: Home Phone: (562) 607-1580

Mitchell Service: 910651

Description: 2012 Toyota RAV4
 Body Style: 4D Ut
 VIN: 2T3WFREV0DW016783
 Mileage: 1,719
 OEM/ALT: A
 Color: BLUE MET
 Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
 REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
 TELESCOPIC STEERING COLUMN, LUGGAGE RACK, ANTI-LOCK BRAKE SYS., TRACTION CONTROL
 FOG LIGHTS, ALUM/ALLOY WHEELS, AUXILIARY INPUT, IPOD ADAPTER, FRONT AIR DAM
 TINTED GLASS, TRIP COMPUTER, SIDE AIRBAGS, ANTI-THEFT SYSTEM
 AUTOMATIC HEADLIGHTS, SIDE HEAD CURTAIN AIRBAGS, AM/FM STEREO CD/MP3 PLAYER
 ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS, INTERIOR AIR FILTER
 KEYLESS ENTRY SYSTEM, LIMITED SLIP DIFFERENTIAL, POWER DISC BRAKES, REAR SPOILER
 REAR WINDOW WIPER, SECOND ROW SPLIT FOLDING BENCH SEAT
 STEERING WHEEL AUDIO CONTROLS, STEERING WHEEL MOUNTED CONTROLS
 SUNROOF/MOONROOF (POWER)

Vehicle Production Date: 4/13
 Drive Train: 2.5L Inj 4 Cyl 2WD
 License: 7AGT390 CA
 Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Front Bumper</u>							
1		BDY	OVERHAUL	Frt Bumper Cover Assy			1.4
2	003253	BDY	REMOVE/REPLACE	Frt Bumper Cover	52119-42970	278.91	INC
3		REF	REFINISH	Frt Bumper Cover			C 2.6
4	003261	BDY	REMOVE/REPLACE	Frt Up'r Bumper Reinforcement	52029-0R010	31.42	INC
5	003482	BDY	REMOVE/REPLACE	Frt Up'r Bumper Cover Grille	53112-0R010	31.40	INC #
6		BDY	REMOVE/INSTALL	Frt Bumper Cover			INC
7	003218	BDY	REMOVE/REPLACE	Frt Bumper Impact Bar	52021-42082	191.21	0.4 #
<u>Grille</u>							
8	003178	BDY	REMOVE/INSTALL	Grille Assy			INC #
<u>Front Lamps</u>							
9	004750	BDY	REMOVE/INSTALL	R Front Combination Lamp			INC #

ESTIMATE RECALL NUMBER: 06/10/2013 07:06:44 CO13009886

Mitchell Data Version: OEM: MAY_13_V
 MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
 All Rights Reserved

Page 1 of 5

10	004751	BDY	REMOVE/INSTALL	L Front Combination Lamp				INC #
				<u>Cooling</u>				
11	003078	BDY	REMOVE/REPLACE	Cooling Radiator	16400-0V030	499.68	INC	
12	004838	BDY	REMOVE/INSTALL	Cooling Fan Shroud	Existing		0.3 #r	
				<u>A/C /Heater/Ventilation</u>				
13	000193	MCH	REMOVE/REPLACE	Air Cond Condenser Assy -M	88460-0R011	849.01	INC #	
14		MCH	REMOVE/REPLACE	Evacuate & Recharge A/C -M			1.4	
				<u>Front Inner Structure</u>				
15	000310	BDY	REMOVE/REPLACE	Front Body Radiator Support	53205-0R010	262.58	7.8 #	
16		REF	REFINISH	Radiator Support Complete			1.5	
17		BDY	CHECK/ADJUST	Headlamps			0.4	
18		MCH	REMOVE/REPLACE	Add To R&R Mechanical Components -M			0.8 #	
19	000321	BDY	REMOVE/REPLACE	Front Body Lower Tie Bar	57104-0R011	498.76	3.0	
20	002809	BDY	REMOVE/REPLACE	Upr Front Body Cover	53289-0R010	207.19	INC	
21	002847	BDY	REMOVE/REPLACE	R Front Body Air Deflector	53293-0R010	43.18		
22	002848	BDY	REMOVE/REPLACE	L Front Body Air Deflector	53294-0R010	45.51		
				<u>Air Bag System</u>				
23	002165	MCH	REMOVE/REPLACE	Disable & Enable Air Bag System -M			0.3	
				<u>MANUAL ENTRIES</u>				
24	900500	MCH *	REPAIR	RESET ELECTRICAL COMPONENTS	Existing		1.0*	
25				RESET AIRBAGSS				
				<u>Rear Door</u>				
26	001572	BDY	REPAIR	L Rear Door Repair Panel	Existing		1.0* #	
27		REF	REFINISH/REPAIR	L Rear Door Repair Panel			C 1.2*	
28				MODIFIED REFINISH WITH FULL CLEAR COAT				
				<u>Roof</u>				
29	002584	REF	BLEND	L Otr Roof Rail			C 0.6 #	
30	001779	BDY	REMOVE/INSTALL	L Ctr Roof Moulding	Existing		0.2 r	
31	001781	BDY	REMOVE/INSTALL	L Rear Roof Moulding	Existing		0.2 r	
				<u>Quarter Panel</u>				
32	002532	REF	BLEND	L Fuel Door			INC #	
33	001900	BDY	REPAIR	L Quarter Outer Panel	Existing		9.0* #	
34		REF	REFINISH	L Quarter Panel Outside			C 2.4	
35	002170	BDY	REMOVE/INSTALL	L Quarter Fuel Door	Existing		0.3 r	
36	004661	BDY	REMOVE/REPLACE	L Quarter Wheel Opening Flare	75654-0R901	56.23	0.4	
37		REF	REFINISH	L Quarter Wheel Opening Flare			C 0.6	
38	004158	BDY	REMOVE/REPLACE	L Quarter Stone Guard	75992-0R010	16.29	0.2 #	
39	002006	BDY	REMOVE/INSTALL	L Quarter Vent Louver Duct	Existing		0.1 #r	
40		BDY	REMOVE/INSTALL	Rear Bumper Assy			INC	
41	002019	BDY	REMOVE/INSTALL	R Lwr Quarter Trim Panel	Existing		0.4 #r	
42	002020	BDY	REMOVE/INSTALL	L Lwr Quarter Trim Panel	Existing		0.4 #r	
				<u>Rear Gate</u>				
43	004859	BDY	REMOVE/REPLACE	Rear Gate Shell	67005-42420	652.02	5.0 #	
44		REF	REFINISH	Rear Gate Outside			C 2.0	
45		REF	REFINISH	Add For Edge & Inside			C 1.2	
46	003359	BDY	REMOVE/INSTALL	Rear Gate Spoiler	Existing		INC #r	
47	003546	BDY	REMOVE/REPLACE	Rear Gate Adhesive Nameplate	75431-42030	26.12	0.1	
48	002570	BDY	REMOVE/INSTALL	Lwr Rear Gate Trim Panel			INC	
49	004763	BDY	REMOVE/INSTALL	R Rear Gate Trim	Existing		INC #r	
50	004764	BDY	REMOVE/REPLACE	L Rear Gate Trim	67938-0R010-B0	43.18	INC #	
51	002141	BDY	REMOVE/INSTALL	Ctr Upr Rear Gate Trim	Existing		INC #r	
52	002147	GLS	REMOVE/INSTALL	Rear Gate Glass	Existing		INC #r	
53	003994	BDY	REMOVE/INSTALL	Rear Gate Wiper Motor	Existing		INC #r	
54	002164	BDY	REMOVE/INSTALL	Rear Gate Washer Nozzle	Existing		INC r	
				<u>Rear Body</u>				
55	002280	BDY	REMOVE/REPLACE	Otr Rear Body Panel	58302-0R011	176.73	7.0	
56		REF	REFINISH	Rear Body Panel Complete			C 1.5	
57	002283	BDY	REMOVE/REPLACE	Inr Rear Body Panel	58307-0R011	346.51	3.0	
58	002292	BDY	REMOVE/REPLACE	Rear Body Floor Pan	58311-0R010	311.31	9.5 #	

ESTIMATE RECALL NUMBER: 06/10/2013 07:06:44 CO13009886

Mitchell Data Version: OEM: MAY_13_V

MAPP:MAY_13_V

Software Version:

7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 2 of 5

59		REF	REFINISH	Rear Floor Pan				1.5	
60		REF	REFINISH	Floor Underside				0.8	
61	004353	BDY	REMOVE/REPLACE	L Rear Body Rear Sidemember (HSS) -S	57604-0R010	121.85	2.5	#	
62	002692	BDY	REMOVE/INSTALL	Rear Body Trim Panel	Existing			INC	r
63	002313	BDY	REMOVE/INSTALL	Rear Body Tonneau Cover	Existing		0.2	r	
64	002327	BDY	REMOVE/INSTALL	Rear Body Storage Compartment	Existing		0.3	r	
<u>Rear Lamps</u>									
65	004152	BDY	REMOVE/INSTALL	R Rear Combination Lamp				INC	#
66	004153	BDY	REMOVE/INSTALL	L Rear Combination Lamp				INC	#
67	003842	BDY	REMOVE/REPLACE	L Rear Combination Lamp	81560-0R010	235.32	INC	#	
68	002602	BDY	REMOVE/INSTALL	High Mount Stop Lamp				INC	#
<u>Rear Bumper</u>									
69		BDY	OVERHAUL	Rear Bumper Cover Assy				0.6	
70	004297	BDY	REMOVE/REPLACE	Rear Bumper Cover	52159-42906	287.02	INC		
71	004728	BDY	REMOVE/REPLACE	Rear Protector	PT747-42060	55.00	INC		
72	001910	BDY	REMOVE/REPLACE	L Rear Bumper Reflector	81920-13022	31.86	INC		
73	002239	BDY	REMOVE/REPLACE	R Rear Bumper Bracket	52591-0R010	46.86	0.2	#	
74	002240	BDY	REMOVE/REPLACE	L Rear Bumper Bracket	52592-0R010	43.85	0.2	#	
75	002243	BDY	REMOVE/REPLACE	Rear Bumper Impact Bar	52350-0R020	161.68	INC	#	
76	002251	BDY	REMOVE/REPLACE	R Rear Bumper Support	52155-0R010	42.84	0.1	#	
77	002252	BDY	REMOVE/REPLACE	L Rear Bumper Support	52156-0R010	42.84	0.1	#	
78	002254	BDY	REMOVE/REPLACE	R Rear Bumper Retainer	52562-0R010	21.98	0.1	#	
79	002255	BDY	REMOVE/REPLACE	L Rear Bumper Retainer	52563-0R010	21.98	0.1	#	
<u>Additional Costs & Materials</u>									
80	936012		ADD'L COST	Hazardous Waste Disposal			3.00	*	
81	936014		ADD'L COST	Flex Additive			8.00	*	
<u>Additional Operations</u>									
82	933006	FRM	ADD'L OPR	FRAME/RACK SET UP				2.0*	
83	933035	FRM	ADD'L OPR	UNIBODY PULL				4.0*	
84				PULL & SQUARE REAR UNIBODY					
85	933035	FRM	ADD'L OPR	UNIBODY PULL				2.0*	
86				PULL & SQUARE FRONT UNIBODY					
87	933002	REF	ADD'L OPR	Clear Coat				2.5*	
88	933003	BDY *	ADD'L OPR	Tint Color				0.5*	
89	933005	BDY	ADD'L OPR	Restore Corrosion Protection			8.00	*	
90	933017	BDY *	ADD'L OPR	Finish Sand And Buff				2.0*	
91				.5 PER PANEL 2.5 MAX - 4 PANELS					
92	933018	BDY *	ADD'L OPR	Mask For Overspray			5.00	*	0.3*
<u>MANUAL ENTRIES</u>									
93	900500	BDY *	REMOVE/REPLACE	SEAM SEALER	** QUAL REPL PART		8.50	*	0.2*
94	900500	BDY *	REMOVE/INSTALL	R&I LT QUARTER GLASS	Sublet		65.00	*	r
95				SAFELITE, 800-800-2727					
<u>Additional Costs & Materials</u>									
96			ADD'L COST	Paint/Materials			625.60	*	

* - Judgment Item

- Labor Note Applies

C - Included in Clear Coat Calc

r - CEG R&R Time Used For This Labor Operation

Date: 6/10/2013 07:06 AM
Estimate ID: CO13009886
Estimate Version: 0
Preliminary
Profile ID: * PDS

Body Shop: M.R. AUTO BODY COLLISION
Address: 1849 W GAGE AVE
LOS ANGELES, CA 90047
Telephone: (323) 752-3946
Fax Phone: (323) 752-3953
State Lic. No: TIN 20-0802347

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."


MARIO'S TOWING

ROAD SERVICE

1746 W. Browning Blvd. • Los Angeles, CA 90062



Cell. (323) 595-1090



Local-Long Distance-Tire Change
Lockouts-Battery-Jump Starts

0979

24 HOURS TOWING

SE COMPRAN JUNK CARS

NAME

MR. Auto DATE 5-03-13

STREET

1845 W Gage CITY

REGISTERED OWNER

DELANY ESCOBAR PHONE 562 607 1580

STREET

4667 MAPLEWOOD CITY L.A.

YEAR & MAKE

TOY. RAV 2013 LIC. NO. NO PLATE

VIN NO.

AUTHORITY OF POLICE

OWNER

PRIVATE PROPERTY

IMPOUNDED

WRECKED

MECH.

STORED

TOWED FROM:

4667 Delany Escobar
Los Angeles CA

1ST TOW

\$ 130.00

2ND TOW

STORAGE

LIEN CHS.

LABOR

WINCH

DOLLY CHG.

HAZARDOUS MATERIAL

STAND BY TIME

ROLLOVER

AFTER HR CHG.

GATE FEE

TOTAL

\$ 130.00

SIGN HERE FOR PERSONAL PROPERTY REMOVAL

It is understood that the owner or his agent has examined said vehicle and agrees to release Mario's Towing Service from any or all claims which may arise from damage to said vehicle or loss of public or private property.

SIGNED

OWNED OK TOW

DRIVER'S LIC. NO.

TYPE CAR

LIC NO.

MARIO'S TOWING SERVICE

"Bienaventurado todo aquel que teme a Jehová, que anda en sus caminos. Cuando comieres el trabajo de tus manos. Bienaventurado serás, y te irá bien". Salmo 128:1-2

"Todo lo que pidáis en oración, creyendo, lo recibireis." Mateo 21:22























FD BY: TOYOTA MOTOR MANUFACTURING CANADA INC.

GWR: 2035KG (4485LB)

GAWR: FRT. 1150KG (2535LB) WITH 225/65R17 TIRES,
17X7.0J RIMS, AT 230KPA (33PSI) COLD.

RR. 1150KG (2535LB) WITH 225/65R17 TIRES,
17X7.0J RIMS, AT 230KPA (33PSI) COLD.

THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR
VEHICLE SAFETY AND THEFT PREVENTION STANDARDS IN EFFECT ON
THE DATE OF MANUFACTURE SHOWN ABOVE.

2T3WFREV0DWO16783 MPV



C/TR: 8V5/FA20

A/TM: -02A/U760E

ASA42L-CNTMKA
MADE IN CANADA

794

A

04/13

06/06/2013



06/06/2013



















REGISTRATION CARD VALID FROM: 05/05/2013 TO: 05/08/2014

REGISTERED OWNER
ESCOBAR DELMY
1130 ORIZABA ST 8
LONG BEACH CA 90804

TOYOTA MTR CRDT CORP
PO BX 105386
ATLANTA GA 30348

AMOUNT PAID \$ 259.00

AMOUNT DUE \$ 259.00

AMOUNT RECD CASH :
CHCK : 259.00
CRDT :

06/06/2013



