

Date: 6/9/2013 10:57 AM
Estimate ID: CO13009751
Estimate Version: 0
Preliminary
Profile ID: * Robert Moreno Ins.

FOR SUPPLEMENT CALL RICH PEREA 760-275-6795 OR E MAIL
pds9593@verizon.net

PROPERTY DAMAGE SPECIALIST

P.O. BOX 2002, INDIO, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: pds9593@verizon.net

Damage Assessed By: Jaime Munoz

Appraised For: ANNI CHUNG
(714) 738-1383 ext. 2426

Condition Code: Fair
Date of Loss: 5/19/2013
Contact Date: 5/19/2013
Payer: Insurance
File Number: CO13009751
Claim Number: CO13009751

Type of Loss: Collision
Arrival Date: 6/7/2013
Accident Date: 5/19/2013
Deductible: 0.00

Insured: KENNY DU
Claimant: CHERYL STEVENSON
Address: 2001 CEDAR AVE APT 12A, LONG BEACH, CA 90806
Owner: CHERYL STEVENSON
Address: 2001 CEDAR AVE APT 12A, LONG BEACH, CA 90806
Telephone:
Cell Phone: (909) 436-7134

Mitchell Service: 918778

Description: 2001 Nissan Frontier SE
Body Style: 4D Pkup 4' Bed 116" WB
VIN: 1N6ED27T41C368801
Mileage: 114,386
OEM/ALT: A
Color: WHITE

Drive Train: 3.3L Inj 6 Cyl 2WD
License: 6P19550 CA

Search Code: 975

Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, SLIDING REAR PICKUP WINDOW
LUGGAGE RACK, SKID PLATES, ANTI-LOCK BRAKE SYS., FOG LIGHTS, ALUM/ALLOY WHEELS
LEATHER STEERING WHEEL, TINTED GLASS, AM/FM STEREO CD, FRONT BUCKET SEATS
KEYLESS ENTRY SYSTEM, LIMITED SLIP DIFFERENTIAL, POWER FOLDING EXTERIOR MIRRORS
STEP BUMPER

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	800021	BDY	OVERHAUL	Frt Bumper Cover Assy			2.0
2	800026	BDY	REMOVE/REPLACE	Frt Bumper Cover	Remanufactured	232.00	INC
3	AUTO	REF	REFINISH	Frt Bumper Cover			C 2.5
4	800030	BDY	REMOVE/REPLACE	Frt Lwr Bumper Clip 4@4.30	63848-9E00A	17.20	INC
5	800035	BDY	REMOVE/REPLACE	Frt Bumper License Plate Bracket	96210-9Z400	18.90	INC
6	800050	BDY	REMOVE/INSTALL	R Frt Lwr Bumper Flare	Existing		INC r
7	800051	BDY	REMOVE/INSTALL	L Frt Lwr Bumper Flare	Existing		INC r
8	936012		ADD'L COST	Hazardous Waste Disposal		3.00 *	
9	936014		ADD'L COST	Flex Additive		3.00 *	
10	AUTO	REF	ADD'L OPR	Clear Coat			1.0
11	933003	BDY *	ADD'L OPR	Tint Color			0.5*
12	AUTO		ADD'L COST	Paint/Materials		112.00 *	

ESTIMATE RECALL NUMBER: 06/09/2013 10:57:29 CO13009751

Mitchell Data Version: MAY_13_V
MAPP:MAY_13_V
Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

* - Judgment Item
** QUAL REPL PART - Quality Replacement Parts
C - Included in Clear Coat Calc
r - CEG R&R Time Used For This Labor Operation

KEYSTONE AUTOMOTIVE
2530 LINDSAY PRIVADO #3
ONTARIO
CA 91761
(800) 421-7866 (909) 986-4586

2 ** NI1000185R 232.00

Estimate Totals

		Units	Rate	Add'l Labor Amount	Sublet Amount	Totals										
I.	Labor Subtotals															
	Body	2.5	40.00	0.00	0.00	100.00										
	Refinish	3.5	40.00	0.00	0.00	140.00										
						Non-Taxable Labor										
	Labor Summary	6.0				240.00										
II.	Part Replacement Summary															
	Taxable Parts															
	Sales Tax			@	9.000%											

Insurance Co: Robert Moreno Insurance Services
Address: P.O. BOX 5185
FULLERTON, CA 92838
Telephone: (714) 738-1383
Fax Phone: (714) 738-5035

Inspection Site: WORK
Address: 200 E. LIVE OAK
IRWINDALE, CA 91706
(909) 436-7134
Inspection Date: 6/8/2013

Body Shop: OWNER'S CHOICE OF SHOP

COLLECT ALL FROM OWNER
***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER.
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!!!***

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.