

Date: 11/13/2013 06:51 PM
Estimate ID: C013014028
Estimate Version: 0
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 762-275-6795 OR EMAIL
pds9593@verizon.net

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: pds9593@verizon.net

Damage Assessed By: DAVID SILVA

Appraised For: ROBERT MORENO INSURANCE -GEORGE BURGHARDT
(800) 453-1588

Condition Code: Fair
Date of Loss: 10/26/2013
Contact Date: 11/12/2013
Deductible: NONE
File Number: 11132013-1000036
Claim Number: C013014028

Arrival Date: 11/13/2013

Insured: GUSTAVO GARCIA MENDEZ
Claimant: JOSE MAGANA
Owner: JOSE MAGANA

Mitchell Service: 914703

Description: 2000 Acura Integra LS
Body Style: 2D Cpe
VIN: JH4DC435XY005695
Mileage: 163,033
OEM/ALT: A
Color: GREEN

Drive Train: 1.8L Inj 4 Cyl 5M
License: 4MHU230 CA

Search Code: B870059

Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, REAR WINDOW DEFOGGER
MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN, ANTI-LOCK BRAKE SYS.
FOG LIGHTS, ALUM/ALLOY WHEELS, LEATHER STEERING WHEEL, REAR AIR DAM
TINTED GLASS, VARIABLE ASSISTED STEERING, ANTI-THEFT SYSTEM, FRONT BUCKET SEATS
POWER ANTENNA, POWER DISC BRAKES, POWER FOLDING EXTERIOR MIRRORS
REAR WINDOW WIPER, STEERING WHEEL MOUNTED CONTROLS, SUNROOF/MOONROOF (POWER)

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Front Bumper</u>							
1	400059	BDY	REPAIR	Frnt Bumper Cover	Existing		2.0* #
2		REF	REFINISH	Frnt Bumper Cover			C 2.8
3	401180	BDY	REMOVE/INSTALL	Frnt Bumper Emblem	Existing		0.2 #r
<u>Front Lamps</u>							
4	401764	BDY	CHECK/ADJUST	Headlamps			0.4
5	401767	BDY	REMOVE/REPLACE	R Headlamp Lens & Housing	Qual Recycled Part	250.00 *	1.6 #
6				HI-WAY AUTO RECYCLERS 800-898-8634 STK#CC101			
7	401781	BDY	REMOVE/REPLACE	R Signal/Marker Lamp Lens & Housing	Qual Recycled Part	30.00 *	0.3 #
8				LKQ LAKENOR-1-800-525-3667 STK#116-58656			
<u>Hood</u>							
9	400605	BDY	ALIGN	Hood Panel	Existing		0.3*
<u>Front Fender</u>							
10	400619	BDY	REPAIR	R Fender Panel	Existing		4.0*
11		REF	REFINISH	R Fender Outside			C 2.0
<u>ADDITIONAL OPERATIONS</u>							
12		REF	ADD'L OPR	Clear Coat			1.5
<u>Additional Costs & Materials</u>							
13			ADD'L COST	Paint/Materials		176.40 *	

ESTIMATE RECALL NUMBER: 11/13/2013 18:50:21 C013014028

Mitchell Data Version: OEM: OCT_13_V

MAPP: OCT_13_V

Software Version: 7.0.487

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

* - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc
r - CEG R&R Time Used For This Labor Operation

Prior Damage:
RR BUMPER COVER-SCRAPE

Estimate Totals

I.	Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II.	Part Replacement Summary			Amount
	Body	8.8	42.00	0.00	0.00	369.60		Taxable Parts			280.00
	Refinish	6.3	42.00	0.00	0.00	264.60		Sales Tax	@	9.000%	25.20
	Non-Taxable Labor					634.20		Total Replacement Parts Amount			305.20
	Labor Summary	15.1				634.20					
III.	Additional Costs					Amount	IV.	Adjustments			Amount
	Taxable Costs					176.40		Insurance Deductible			0.00
	Sales Tax					15.88		Customer Responsibility			0.00
	Total Additional Costs					192.28					
	Paint Material Method: Rates										
	Init Rate = 28.00 , Init Max Hours = 99.9, Addl Rate = 0.00										
							I.	Total Labor:			634.20
							II.	Total Replacement Parts:			305.20
							III.	Total Additional Costs:			192.28
								Gross Total:			1,131.68
							IV.	Total Adjustments:			0.00
								Net Total:			1,131.68

Point(s) of Impact

12 Front Center (P), 2 Right Front Side (S)

Insurance Co: ROBERT MORENO INSURANCE

Inspection Site: WORK
VERNON, CA
Inspection Date: 11/13/2013

Body Shop: NOT AT SHOP

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE REINSPECTED PRIOR TO REPAIR
BY THE APPRAISER.
FAILURE TO HAVE REINSPECTION WILL RESULT IN NON-PAYMENT!!!!!!***
Pursuant to California Code of Regulations Section 2695.8(g)

ESTIMATE RECALL NUMBER: 11/13/2013 18:50:21 C013014028

Mitchell Data Version: OEM: OCT_13_V

MAPP:OCT_13_V

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Software Version: 7.0.487

Date: 11/13/2013 06:51 PM
Estimate ID: C013014028
Estimate Version: 0
Profile ID: * PDS

The insurance company named on this damage estimate warrants that all non-original equipment replacement parts listed herein are of like, kind, quality, safety, fit and performance as original equipment manufacturer replacement crash parts

ESTIMATE RECALL NUMBER: 11/13/2013 18:50:21 C013014028

Mitchell Data Version: OEM: OCT_13_V

MAPP:OCT_13_V

Software Version: 7.0.487

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3

Date: 11/13/2013 06:51 PM
Estimate ID: C013014028
Unrelated Prior Damage
Estimate Version: 0
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 762-275-6795 OR EMAIL
pds9593@verizon.net

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: pds9593@verizon.net

Unrelated Prior Damage

Damage Assessed By: DAVID SILVA

Appraised For: ROBERT MORENO INSURANCE -GEORGE BURGHARDT
(800) 453-1588

Condition Code: Fair
Date of Loss: 10/26/2013
Contact Date: 11/12/2013

Arrival Date: 11/13/2013

File Number: 11132013-1000036
Claim Number: C013014028

Insured: GUSTAVO GARCIA MENDEZ
Claimant: JOSE MAGANA
Owner: JOSE MAGANA

Mitchell Service: 914703

Description: 2000 Acura Integra LS
Body Style: 2D Cpe
VIN: JH4DC435XY5005695
Mileage: 163,033
OEM/ALT: A

Drive Train: 1.8L Inj 4 Cyl 5M
License: 4MHU230 CA

Search Code: B870059

Color: GREEN

Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, REAR WINDOW DEFOGGER
MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN, ANTI-LOCK BRAKE SYS.
FOG LIGHTS, ALUM/ALLOY WHEELS, LEATHER STEERING WHEEL, REAR AIR DAM
TINTED GLASS, VARIABLE ASSISTED STEERING, ANTI-THEFT SYSTEM, FRONT BUCKET SEATS
POWER ANTENNA, POWER DISC BRAKES, POWER FOLDING EXTERIOR MIRRORS
REAR WINDOW WIPER, STEERING WHEEL MOUNTED CONTROLS, SUNROOF/MOONROOF (POWER)

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
				<u>Rear Bumper</u>			
1	425330	REF	REFINISH	Rear Bumper Cover			C 2.0
				<u>ADDITIONAL OPERATIONS</u>			
2		REF	ADD'L OPR	Clear Coat			0.8
				<u>Additional Costs & Materials</u>			
3			ADD'L COST	Paint/Materials		78.40	*

* - Judgment Item

C - Included in Clear Coat Calc

Prior Damage:

RR BUMPER COVER-SCRAPE

ESTIMATE RECALL NUMBER: 11/13/2013 18:50:21 C013014028

Mitchell Data Version: OEM: OCT_13_V

MAPP:OCT_13_V

Software Version: 7.0.487

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 2

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Refinish	2.8	42.00	0.00	0.00	117.60		
	Non-Taxable Labor				117.60	Total Replacement Parts Amount	0.00
Labor Summary	2.8				117.60		
III. Additional Costs					Amount	IV. Adjustments	Amount
Taxable Costs					78.40	Total Adjustments:	0.00
Sales Tax		@	9.000%		7.06		
Total Additional Costs					85.46		
Paint Material Method: Rates							
Init Rate = 28.00 , Init Max Hours = 99.9, Addl Rate = 0.00							
						I. Total Labor:	117.60
						II. Total Replacement Parts:	0.00
						III. Total Additional Costs:	85.46
						Gross Total:	203.06
						IV. Total Adjustments:	0.00
						Unrelated Damage Net Total:	203.06

Point(s) of Impact

12 Front Center (P), 2 Right Front Side (S)

Insurance Co: ROBERT MORENO INSURANCE

Inspection Site: WORK
 VERNON, CA

Inspection Date: 11/13/2013

Body Shop: NOT AT SHOP

Itemized Totals

I. Labor Subtotals				II. Part Replacement Summary			
	Units	Rate	Totals				Amount
Body	8.8	42.00	369.60	Taxable Parts			280.00
Remove/Replace	1.9	"	79.80	Qual Recycled Part			280.00
Repair	6.0	"	252.00				
Remove/Install	0.2	"	8.40				
Align	0.3	"	12.60				
Check Adjust	0.4	"	16.80				
Refinish	6.3	42.00	264.60	Sales Tax	@	9.000%	25.20
Refinish Only	4.8	"	201.60				
Additional Operation	1.5	"	63.00				
Non-Taxable Labor			634.20	Total Replacement Parts Amount			305.20
Labor Summary	15.1		634.20				
III. Additional Costs				IV. Adjustments			
			Amount				Amount
Taxable Costs			176.40	Insurance Deductible			0.00
Sales Tax	@	9.000%	15.88	Customer Responsibility			0.00
Total Additional Costs			192.28				
Paint Material Method: Rates							
				I. Total Labor:			634.20
				II. Total Replacement Parts:			305.20
				III. Total Additional Costs:			192.28
				Gross Total:			1,131.68
				IV. Total Adjustments:			0.00
				Net Total:			1,131.68