

 **View Claim Summary - File Number: 07022013-100004**

[GO BACK](#)

Claim Summary been saved successfully...



Property Damage Specialist
P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : CO13010837
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Lorena Bautista
Date of Loss : 2013-06-28
Whose Claim : Insured
Owner Name : FILIPAU SEEI SCOTT
Insured Name : FILIPAU SEEI SCOTT
Claimant Name :
Inspection Location : CONTRERAS AUTO

Appraisal Information

File Number : 07022013-100004
Appraiser : Roberta Kear
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-02
Assigned Date/Time : 2013-06-28 19:00:00
Assignment Type : Full Appraisal
ERT (Days) : 11
Possible Supplement : yes

Vehicle Information

Year : 2009
Make : Nissan
Model : Altima
Sub-model : 3.5se

VIN : 1N4ABL21E69C177398
Plate : 6XJA688
State : California
Milage :
Drivable : No
Primary POI : REAR
Secondary POI :
Vehicle Condition : Good
Interior Condition : GOOD
Paint Condition : GOOD
Engine : 3.5L 6 CYL

Repair Information

Recommendation : Repairable
Estimate 1 Total : 7895.61
Estimate 2 Total : 0.00
Estimate 1 Betterment : 0.00
Estimate 2 Betterment : 0.00
Supplement 1 Total : 0.00
Supplement 1 Betterment : 0.00
Supplement 2 Total : 0.00
Supplement 2 Betterment : 0.00
Supplement 3 Total : 0.00
Supplement 3 Betterment : 0.00
Supplement 4 Total : 0.00
Supplement 4 Betterment : 0.00
Subtotal : 7895.61
Deductible : 500.00
Original Net Loss : 7395.61
Gross Total : 7895.61
Supplement Net Loss : 0.00

Tire Information

Make : BRIDGESTONE
Size :
Tired Depth (in 32nds)

L/F R/F

L/R R/R

Spare :

Shop Information

Shop Name : CONTRERAS

Address 1 : 310 S CATALINA ST

Address 2 :

City : LOS ANGELES

State : California

Zip : 90020

Phone Number : 213-252-9044

Fax : 213-252-9563

Agreed Price : Yes

Federal Tax ID # : 20-8018087

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total : 0.00

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

ESTIMATE AT 47% OF ACV

7/2/2013 - I INSPECTED THE INSURED'S 2009 NISSAN ALTIMA AT CONTRERAS AUTO BODY, 310 S CATALINA ST, LOS ANGELES AT APPROX 12:35 PM. SHOP CONTACT WAS DAVID.

I NOTED DAMAGE TO THE REAR OF THE VEHICLE. APPROX REPAIR TIME IS 11 DAYS & THE VEHICLE IS NOT DRIVABLE.

POI WAS A MODERATE TO HARD IMPACT TO THE REAR OF THE VEHICLE WITH NO AIRBAG DEPLOYMENT.

LKQ/QRP SEARCH DID FIND PARTS FOR THIS VEHICLE BUT OEM PARTS WERE MORE COST EFFECTIVE. OEM PARTS WERE USED IN THE ESTIMATE.

I ADDED A FRAME PULL TO THE ESTIMATE TO PULL & SQUARE THE REAR UNIBODY PRIOR TO REPLACEMENT.

I ADDED A 4 WHEEL ALIGNMENT TO THE ESTIMATE DUE TO THE FRAME PULL TO THE REAR UNIBODY & FRAME.

I HAD GOOD ACCESS TO THE INTERIOR OF THE TRUNK AND RAIL AS THE REAR WAS WIDE OPEN. I WAS ABLE TO GET INTO THE TRUNK AND SEE BOTH RAILS AND THE FLOOR, THERE WAS NO SIGNIFICANT DAMAGE (BENDS OR KINKS) TO THE AREA. I WENT OVER THE FLOOR AND RAILS WITH THE SHOP AND WE AGREED THAT THE PULL AND MINOR REPAIR TO THE FLOOR WAS ALL THAT WOULD BE REQUIRED AS THE IMPACT WAS A HIGH IMPACT.

NO UPD WAS NOTED TO THE VEHICLE.

NO BETTERMENT WAS APPLIED. NO TOW BILL.

NO STORAGE CHARGES WERE APPLIED.

SHOP IS CONTRERAS AUTO BODY, TIN 20-8018087, I NEGOTIATED LABOR RATES WITH THE SHOP ACCEPTABLE FOR THE TYPE OF SHOP & THE AREA.

OPEN ITEMS INCLUDE POSSIBLE ADDITIONAL DAMAGE AFTER TEARDOWN.

THIS VEHICLE IS REPAIRABLE.

I EMAILED A COPY OF THIS ESTIMATE TO THE SHOP AT DARBAIZ@YAHOO.COM

Date: 7/8/2013 12:54 PM
Estimate ID: CO13010837
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA, 760-275-6795 OR EMAIL
PDS9593@VERIZON.NET

Property Damage Specialist

P.O. BOX 3237, INDIO, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: PDS9593@VERIZON.NET

Damage Assessed By: Roberta Kear

Appraised For: ROBERT MORENO INSURANCE - LORENA BAUTISTA

Condition Code: Good
Date of Loss: 6/28/2013
Deductible: 500.00
File Number: CO13010837
Claim Number: CO13010837

Type of Loss: Collision

Insured: FILIPAU SCOTT
Owner: FILIPAU SCOTT
Address: 4832 CHALLENGE AVE, RIVERSIDE, CA 92503
Telephone: Work Phone: (951) 689-0202

Home Phone: (951) 264-0419

Mitchell Service: 910825

Description: 2009 Nissan Altima 3.5 SE
Body Style: 4D Sed
VIN: 1N4BL21E69C177398
Mileage: 59,688
OEM/ALT: A
Color: BLUE MET

Vehicle Production Date: 3/09
Drive Train: 3.5L Inj 6 Cyl AT FWD
License: 6XJA688 CA

Search Code: None

Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS
ALUM/ALLOY WHEELS, AUXILIARY INPUT, LEATHER STEERING WHEEL
AUTOMATIC TRANSMISSION, FRONT AIR DAM, TINTED GLASS, TRIP COMPUTER
VARIABLE ASSISTED STEERING, SIDE AIRBAGS, ANTI-THEFT SYSTEM
AUTOMATIC HEADLIGHTS, SIDE HEAD CURTAIN AIRBAGS, AM/FM STEREO CD
DRIVER SEAT WITH POWER LUMBAR SUPPORT, FRONT BUCKET SEATS, INTERIOR AIR FILTER
KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, POWER HEATED EXTERIOR MIRRORS
POWER LIFTGATE/TRUNK, REAR WINDOW DIVERSITY ANTENNA
STEERING WHEEL AUDIO CONTROLS, STEERING WHEEL MOUNTED CONTROLS
SUNROOF/MOONROOF (POWER)

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Air Bag System</u>							
1	000405	MCH	REMOVE/REPLACE	Disable & Enable Air Bag System -M			INC
2	000406	MCH	REMOVE/REPLACE	Air Bag System Diagnosis -M			0.5 #
<u>Body Components</u>							
3	931105	BDY *	REPAIR	FOUR WHEEL ALIGNMENT	Sublet	79.95 *	0.0*
<u>Air Bag System</u>							
4	000193	MCH	REMOVE/INSTALL	R Air Bag Side Curtain Module -M	Existing		INC #r
<u>Rocker/Pillars/Floor</u>							
5	001875	REF	BLEND	R Roof Rail			C 0.6 #
<u>MANUAL ENTRIES</u>							
6	900500	REF *	REFINISH/REPAIR	BLEND RIGHT ROCKER PANEL	Existing		0.5*

ESTIMATE RECALL NUMBER: 07/08/2013 12:54:12 CO13010837

Mitchell Data Version: OEM: MAY_13_V
MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 5

<u>Rocker/Pillars/Floor</u>							
7	001962	BDY	REMOVE/INSTALL	R Rocker Moulding			0.4
8	001963	BDY	REMOVE/INSTALL	L Rocker Moulding			0.4
9	000823	BDY	REMOVE/INSTALL	R Frt Otr Rocker Scuff Plate	Existing		0.2 #r
10	000829	BDY	REMOVE/INSTALL	R Rear Otr Rocker Scuff Plate	Existing		INC #r
<u>Rear Seat</u>							
11	001880	BDY	REMOVE/INSTALL	Rear Seat Assy			INC
<u>Rear Door</u>							
12	001306	BDY	REPAIR	R Rear Door Repair Panel	Existing		2.0* #
13		REF	REFINISH	R Rear Door Outside		C	2.1
14	001314	BDY	REMOVE/INSTALL	R Rear Otr Belt Moulding			0.3
15	001894	BDY	REMOVE/INSTALL	R Rear Door Trim Panel			INC
16	001902	BDY	REMOVE/INSTALL	R Rear Door Handle			INC #
17	002301	BDY	REMOVE/INSTALL	R Rear Otr Door Handle			0.9 #
<u>Roof</u>							
18	001449	BDY	REMOVE/INSTALL	R Frt Roof Drip Rail Moulding	Existing		0.2 #r
19	001910	BDY	REMOVE/INSTALL	Roof Headliner			3.5
<u>Back Window</u>							
20	001504	GLS	REMOVE/REPLACE	Back Window Glass	** QUAL REPL PART	401.75 *	INC #
21				SAFELITE AUTO GLASS 800-800-2727			
<u>Quarter Panel</u>							
22	001511	REF	BLEND	L Quarter Panel Outside		C	0.9
23	001528	BDY	REMOVE/REPLACE	R Quarter Outer Panel	78100-JA030	618.50	15.0 #
24		REF	REFINISH	R Quarter Panel Outside		C	1.7
25		REF	REFINISH	R Quarter Panel Edge		C	0.5
26		REF	REFINISH	R Add For Pillar		C	0.5
27		MCH	REMOVE/REPLACE	R Add To R&L/R&R Side Curtain Air Bags-M			0.8 #
28	001530	BDY	REMOVE/REPLACE	R Quarter Rear Corner Panel	78140-JA030	44.50	0.5 #
29		REF	REFINISH	R Corner Panel		C	0.5
30	001566	BDY	REMOVE/INSTALL	R Rear Quarter Trim Panel	Existing		INC r
<u>Luggage Lid</u>							
31	003311	BDY	REMOVE/REPLACE	Luggage Lid Panel	84300-JA035	d568.43	1.3
32		REF	REFINISH	Luggage Lid Outside		C	1.8
33		REF	REFINISH	Luggage Lid Underside		C	1.1
34		BDY	REMOVE/REPLACE	Rear Add w/Spoiler			0.2
35	001599	BDY	REMOVE/INSTALL	Luggage Lid Opening Weatherstrip	Existing		INC r
36	001605	BDY	REMOVE/REPLACE	Luggage Lid Spoiler	96030-JA11E	320.90	INC #
37		REF	REFINISH	Spoiler		C	1.2
38	002498	BDY	REMOVE/REPLACE	Luggage Lid Moulding	84810-ZN52E	93.13	INC #
39		REF	REFINISH	Moulding		C	0.5
40	001607	BDY	REMOVE/REPLACE	Luggage Lid Adhesive Emblem	84890-JA000	24.48	0.1
41	001608	BDY	REMOVE/REPLACE	Luggage Lid Adhesive Nameplate	84895-JA000	26.57	0.1
42	001611	BDY	REMOVE/REPLACE	Luggage Lid Adhesive Nameplate	84896-JA300	26.57	0.1
43	002633	BDY	REMOVE/REPLACE	Luggage Lid Adhesive Nameplate	84897-JA00A	26.57	0.1
<u>Rear Body</u>							
44	002277	BDY	REMOVE/REPLACE	Rear Body Panel	G9110-JA0AA	393.35	5.7 #
45		REF	REFINISH	Rear Body Panel		C	1.6
46		REF	REFINISH	Add For Jambs & Inside			1.0
47	001720	BDY	REPAIR	Rear Body Floor Pan	Existing		2.0* #
48				REPAIR AT WELD AREA			
49		REF	REFINISH/REPAIR	Rear Body Floor Pan			0.5*
50	003229	BDY	REMOVE/INSTALL	Rear Body Trim Panel	Existing		INC r
51	001745	BDY	REMOVE/INSTALL	R Rear Body Side Trim Panel	Existing		INC r
52	001746	BDY	REMOVE/INSTALL	L Rear Body Side Trim Panel	Existing		0.3 r
53	001749	BDY	REMOVE/INSTALL	Rear Body Carpet	Existing		r
54	001750	BDY	REMOVE/INSTALL	Rear Body Spare Wheel Well Cover	Existing		r
55	001751	BDY	REMOVE/INSTALL	L Rear Body Partition Board	Existing		r
56	003236	BDY	REMOVE/INSTALL	Keyless Entry Antenna	Existing		0.2 #r
<u>Rear Lamps</u>							

ESTIMATE RECALL NUMBER: 07/08/2013 12:54:12 CO13010837

Mitchell Data Version: OEM: MAY_13_V

MAPP:MAY_13_V

Software Version:

7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

57	001927	BDY	REMOVE/INSTALL	L Rear Combination Lamp			INC
58	001753	BDY	REMOVE/REPLACE	R Rear Combination Lamp Assembly	26550-ZN50A	139.78	INC
59	001754	BDY	REMOVE/REPLACE	L Rear Combination Lamp Assembly	26555-ZN50A	139.79	INC
<u>Rear Bumper</u>							
60	001929	BDY	REMOVE/INSTALL	Rear Bumper Cover			INC #
61	002637	BDY	REMOVE/INSTALL	L Rear Mudguard			0.2
62	001930	BDY	OVERHAUL	Rear Bumper Assy			0.7 #
63	001784	BDY	REMOVE/REPLACE	Rear Bumper Cover	85022-JA040	324.34	INC #
64		REF	REFINISH	Rear Bumper Cover			C 2.5
65	001792	BDY	REMOVE/REPLACE	Rear Bumper Impact Absorber	85090-JA00A	78.04	INC
66	001785	BDY	REMOVE/REPLACE	Rear Bumper Reinforcement Bar	85032-JA00B	252.06	INC #
67	001786	BDY	REMOVE/REPLACE	R Rear Bumper Reinf Bracket	85210-JA00A	64.57	0.2 #
68	001789	BDY	REMOVE/REPLACE	R Rear Bumper Bracket	85220-JA01A	36.33	INC
<u>Additional Costs & Materials</u>							
69	936012		ADD'L COST	Hazardous Waste Disposal		3.00	*
<u>MANUAL ENTRIES</u>							
70	900500	BDY *	REMOVE/REPLACE	SEAM SEALER	** QUAL REPL PART	8.00	* 0.0*
71	900500	BDY *	REPAIR	ROPE WINDSHIELD	Existing		0.3*
<u>Additional Costs & Materials</u>							
72	936014		ADD'L COST	Flex Additive		8.00	*
73	936016		ADD'L COST	Weld Thru Primer		10.00	*
<u>Additional Operations</u>							
74	933006	FRM	ADD'L OPR	FRAME/RACK SET UP			2.0*
75	933035	FRM	ADD'L OPR	UNIBODY PULL			2.0*
76				PULL & SQ RT REAR UNIBODY			
77		REF	ADD'L OPR	Clear Coat			3.6
78	933003	BDY *	ADD'L OPR	Tint Color			0.5*
79	933004	BDY	ADD'L OPR	Undercoating			0.5*
80	933005	BDY	ADD'L OPR	Restore Corrosion Protection		8.00	*
81	933017	BDY *	ADD'L OPR	Finish Sand And Buff			2.0*
82				.5 PER PANEL 2.5 MAX - 4 PANELS			
83	933018	BDY *	ADD'L OPR	Mask For Overspray		5.00	* 0.3*
<u>MANUAL ENTRIES</u>							
84	900500	BDY *	REPAIR	PULL BACK CARPETING	Existing		0.5*
85	900500	MCH *	REPAIR	PULL BACK WIRING	Existing		0.5*
<u>Additional Operations</u>							
86	933024	GLS	ADD'L OPR	BROKEN GLASS CLEANUP			0.5*
<u>MANUAL ENTRIES</u>							
87	900500	BDY *	REMOVE/REPLACE	Mask Jambs for primer	** QUAL REPL PART	2.50	* 0.2*
88	900500	BDY *	REMOVE/REPLACE	Cover Car Interior	** QUAL REPL PART	2.50	* 0.2*
<u>Additional Costs & Materials</u>							
89			ADD'L COST	Paint/Materials		717.40	*

* - Judgment Item

- Labor Note Applies

d - Discontinued by the Manufacturer

C - Included in Clear Coat Calc

r - CEG R&R Time Used For This Labor Operation

Estimate Totals

I. Labor Subtotals						II. Part Replacement Summary				Amount
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals					
Body	39.1	44.00	13.00	79.95	1,813.35	Taxable Parts				3,592.66
Refinish	21.1	44.00	0.00	0.00	928.40	Sales Tax	@	9.000%		323.34
Glass	0.5	44.00	0.00	0.00	22.00					
Frame	4.0	60.00	0.00	0.00	240.00	Total Replacement Parts Amount				3,916.00
Mechanical	1.8	95.00	0.00	0.00	171.00					
Non-Taxable Labor					3,174.75					
Labor Summary	66.5				3,174.75					
III. Additional Costs					Amount	IV. Adjustments				Amount
Taxable Costs					738.40	Insurance Deductible				500.00-
Sales Tax			@	9.000%	66.46	Customer Responsibility				500.00-
Total Additional Costs					804.86					
Paint Material Method: Rates										
Init Rate = 34.00 , Init Max Hours = 99.9, Addl Rate = 0.00										
						I. Total Labor:				3,174.75
						II. Total Replacement Parts:				3,916.00
						III. Total Additional Costs:				804.86
						Gross Total:				7,895.61
						IV. Total Adjustments:				500.00-
						Net Total:				7,395.61

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

6 Rear Center (P)

Insurance Co: ROBERT MORENO INSURANCE SERVICES
Address: P.O. BOX 5185
FULLERTON, CA 92838
Telephone: (714) 578-3366
Fax Phone: (714) 738-5035

Inspection Site: CONTRERAS AUTO
Address: 310 S CATALINA ST
LOS ANGELES, CA 90020

Body Shop: CONTRERAS AUTO
Address: 310 S CATALINA ST
LOS ANGELES, CA 90020
Telephone: (213) 252-9044
Fax Phone: (213) 252-9563
State Lic. No: TIN 20-80180867

ESTIMATE RECALL NUMBER: 07/08/2013 12:54:12 CO13010837

Mitchell Data Version: OEM: MAY_13_V

MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Date: 7/8/2013 12:54 PM
Estimate ID: CO13010837
Estimate Version: 0
Preliminary
Profile ID: * PDS

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

ESTIMATE RECALL NUMBER: 07/08/2013 12:54:12 CO13010837

Mitchell Data Version: OEM: MAY_13_V

MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 5 of 5













07/02/2013

M/D BY NISSAN MOTOR CO. LTD 03/09

DATE:	2022	KG
GWR:	4457	LB
	1086	KG
GWR FR.:	2394	LB
GWR RR.:	993	KG
	2189	LB

THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR VEHICLE SAFETY, BUMPER, AND THEFT PREVENTION STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.

IN4BL21E69C 177398
PASSENGER CAR 781
MODEL: BLJALDWL4AEUARD-EZ
COLOR: RAB TRIM: G 9N00A



M/D BY NISSAN MOTOR CO. LTD 03/09

DATE:	2022	KG
GWR:	4457	LB
	1086	KG
GWR FR.:	2394	LB

GWR RR.:	993	KG
	2189	LB

THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR VEHICLE SAFETY, BUMPER, AND THEFT PREVENTION STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.

IN4BL21E69C 177398
PASSENGER CAR 781

MODEL: BLJALDWL4AEUARD-EZ
COLOR: RAB TRIM: G 9N00A

07/02/2013





















REGISTRATION CARD VALID FROM: 05/16/2013 TO: 05/16/2014

NAME	YR MODEL	YR 1ST SOLD	VLP CLASS	TYPE VEH	TYPE LIC	LICENSE NUMBER
NIS	2009	2012	FT	170	11	6XJA688
VEHICLE ID NUMBER:						1N4BL21B69C177396
STICKER ISSUED						M5703804
PR EXP DATE:						05/16/2014
DATE ISSUED:						05/14/13
ST/ALCH:						19
DT FEE RECVD:						05/14/13
FIC:						8
REGISTERED OWNER						AMOUNT PAID
SCOTT MARK A						\$ 246.00
OR SCOTT JESSE I						
4573 W 1ST ST APT 5						
LOS ANGELES						
CA 90004						
LIEBHOLDERS						
CAPITAL ONE AUTO FIN						
PO BX 255605						
SACRAMENTO						

CASH BACK

07/02/2013

