

Property Damage Specialist  
P.O. BOX 3237, INDIO, CA 92201  
(760) 275-6795  
Fax: (760) 863-5349  
Email: PDS9593@VERIZON.NET

APPRAISAL REPORT

DAMAGE ASSESSED BY: Roberta Kear

FILE NUMBER: CO13010108  
CLAIM NUMBER: CO13010108  
DATE OF LOSS: 6/ 6/2013  
TYPE OF LOSS: Collision  
APPRAISED FOR: ROBERT MORENO INSURANCE - SHELLEY AMBRIZ

ASSIGNMENT DATE: None  
CONTACT DATE: None  
INSPECTION DATE: 6/13/2013  
REC'D DATE: None

Point(s) of Impact

3 Right Side (P)

INSURED: MYUNGHEE LEE  
808 N EL CAMINO REAL  
#8  
SAN CLEMENTE, CA 92672  
(213) 718-3949

CLAIMANT: None

OWNER: MYUNGHEE LEE  
808 N EL CAMINO REAL  
#8  
SAN CLEMENTE, CA 92672  
(213) 718-3949

BODY SHOP: NATIONWIDE COLLISION  
1312 DEWEY AVE  
LOS ANGELES, CA 90006  
(213) 389-8830

CHARLIE

FAX: (213) 389-8831  
TIN 27-0493541

INSPECTION SITE: NATIONWIDE COLLISION  
1312 DEWEY AVE  
LOS ANGELES, CA 90006  
(213) 389-8831

QUALITY RECYCLED PARTS: No  
AFTERMARKET NEW PARTS: Yes  
VEHICLE DRIVEABLE: Yes

Prior Damage:

REAR BUMPER COVER

Comments:

6/13/2013 - I INSPECTED THE INSURED'S 2011 BMW 328i AT NATIONWIDE COLLISION, 1312 DEWEY AVE, LOS ANGELES AT APPROX 12:30 PM. SHOP CONTACT WAS CHARLIE.

I NOTED DAMAGE TO THE RIGHT SIDE OF THE VEHICLE. APPROX REPAIR TIME IS 10 DAYS & THE VEHICLE IS DRIVABLE.

POI WAS A MINOR TO MODERATE SIDESWIPE IMPACT TO THE ENTIRE RIGHT SIDE OF THE VEHICLE WITH NO AIRBAG DEPLOYMENT.

COMPLETED LKQ SEARCH VIA CARPART.COM AND LKQ.COM, NO LKQ MIRROR LOCATED FOR THIS VEHICLE..

I ADDED A 4 WHEEL ALIGNMENT TO THE ESTIMATE DUE TO THE IMPACT TO THE RIGHT REAR WHEEL.

SHOP INDICATED CUSTOMER HAD ANOTHER ACCIDENT ON WED 06/12/13 TO REAR BUMPER OF VEHICLE. WROTE UPD ESTIMATE FOR THIS NEW LOSS. IT SHOULD BE NOTED I ALLOWED SPOT REFINISH FOR THIS LOSS AS THE NEW DAMAGE WAS NOT PRIOR.

NO BETTERMENT WAS APPLIED. NO TOW BILL.

SHOP IS NATIONWIDE COLLISION, TIN 27-0493541, I NEGOTIATED LABOR RATES

WITH THE SHOP ACCEPTABLE FOR THE TYPE OF SHOP & THE AREA.

OPEN ITEMS INCLUDE POSSIBLE ADDITIONAL DAMAGE AFTER TEARDOWN.

THIS VEHICLE IS REPAIRABLE.

COMPARISON ESTIMATE:	0.00	TOWING:	0.00	ACTUAL CASH VALUE:	28,700.00
APPRAISER ESTIMATE:	2,059.11	STORAGE:	0.00	SALVAGE VALUE:	0.00
AGREED UPON AMOUNT:	0.00	DEDUCTIBLE:	1,000.00	SETTLEMENT:	0.00
				REPAIR VS. ACV:	0.00
DRAFT/CHECK NUMBER:	0			ESTIMATE FEE:	0.00
DRAFT/CHECK AMOUNT:	0.00			TRAVEL EXPENSE:	0.00
DATE ISSUED:	None			PHOTO EXPENSE:	0.00
				MISC EXPENSE:	0.00
				TOTAL CHARGES:	0.00

Date: 6/15/2013 08:25 AM  
 Estimate ID: CO13010108  
 Estimate Version: 0  
 Preliminary  
 Profile ID: \* PDS

FOR SUPPLEMENTS CALL RICH PEREA, 760-275-6795 OR EMAIL  
 PDS9593@VERIZON.NET

## Property Damage Specialist

P.O. BOX 3237, INDIO, CA 92201  
 (760) 275-6795  
 Fax: (760) 863-5349  
 Email: PDS9593@VERIZON.NET

Damage Assessed By: Roberta Kear

Appraised For: ROBERT MORENO INSURANCE - SHELLEY AMBRIZ

Condition Code: Good  
 Date of Loss: 6/ 6/2013  
 Deductible: 1,000.00  
 File Number: CO13010108  
 Claim Number: CO13010108

Type of Loss: Collision  
 Arrival Date: 6/13/2013

Insured: MYUNGHEE LEE  
 Owner: MYUNGHEE LEE  
 Address: 808 N EL CAMINO REAL #8, SAN CLEMENTE, CA 92672  
 Telephone: Home Phone: (213) 718-3949

Mitchell Service: 910534

Description: 2011 BMW 328i  
 Body Style: 4D Sed  
 VIN: WBAPH5C59BF093755  
 Mileage: 28,288  
 OEM/ALT: A  
 Color: BLACK  
 Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW  
 REAR WINDOW DEFOGGER, CRUISE CONTROL, TILT STEERING COLUMN, LEATHER SEAT  
 TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS  
 ALUM/ALLOY WHEELS, NAVIGATION SYSTEM, AUXILIARY INPUT, LEATHER STEERING WHEEL  
 AUTOMATIC TRANSMISSION, FRONT AIR DAM, GENUINE WOOD TRIM, AUTO AIR CONDITION  
 TRIP COMPUTER, VARIABLE ASSISTED STEERING, SIDE AIRBAGS, ANTI-THEFT SYSTEM  
 AUTOMATIC HEADLIGHTS, SIDE HEAD CURTAIN AIRBAGS, DAYTIME RUNNING LIGHTS  
 AM/FM STEREO CD/MP3 PLAYER, ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS  
 INTERIOR AIR FILTER, KEYLESS ENTRY SYSTEM, POWER DISC BRAKES  
 POWER HEATED EXTERIOR MIRRORS, POWER LIFTGATE\TRUNK, RAIN SENSING WIPERS  
 REAR WINDOW DIVERSITY ANTENNA, STEERING WHEEL AUDIO CONTROLS  
 SUNROOF/MOONROOF (POWER)

Vehicle Production Date: 10/11  
 Drive Train: 3.0L Inj 6 Cyl 6A RWD  
 License: 6UYK159 CA  
 Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Front Bumper</u>							
1	004621	BDY	REMOVE/INSTALL	Frt Bumper Cover			1.0
<u>Front Lamps</u>							
2	004415	BDY	REMOVE/INSTALL	R Front Combination Lamp			0.4 #
3	001842	BDY	REMOVE/INSTALL	R Side Repeater Lamp			0.2 #
<u>Front Fender</u>							
4	001891	REF	BLEND	R Fender Outside			C 0.8
5	000217	BDY	REMOVE/INSTALL	R Fender Front Splash Shield	Existing		0.3 r
6	000222	BDY	REMOVE/INSTALL	R Fender Rear Splash Shield	Existing		0.3 r
<u>Body Components</u>							
7	931105	BDY *	REPAIR	FOUR WHEEL ALIGNMENT	Sublet	79.95 *	0.0*

ESTIMATE RECALL NUMBER: 06/15/2013 08:25:39 CO13010108

Mitchell Data Version: OEM: MAY\_13\_V  
 MAPP:MAY\_13\_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International  
 All Rights Reserved

Page 1 of 4

8				CONCESSION TO REACH AGREED PRICE			
				<u>Wheel</u>			
9	000267	BDY	REPAIR	Alloy Wheel	Existing		0.5*
10				POLISH OUT SCUFFS			
				<u>Front Door</u>			
11	001932	REF	REFINISH	R Frt Door Outside		C	2.0
12	000639	BDY	REPAIR	R Frt Door Shell	Existing		4.5* #
13	001942	BDY	REMOVE/INSTALL	R Frt Belt Moulding		INC	#
14	001946	BDY	REMOVE/INSTALL	R Frt Pillar Moulding			1.2 #
15	001940	BDY	REMOVE/INSTALL	R Frt Rear View Mirror		INC	#
16	000651	BDY	REMOVE/REPLACE	R Frt Door Rear View Mirror	51 16 7 189 978	482.08	0.3 #
17	001948	BDY	REMOVE/INSTALL	R Frt Door Trim Panel		INC	
18	001972	BDY	REMOVE/INSTALL	R Frt Otr Door Handle			0.3
19	000745	BDY	REPAIR	R Frt Door Outside Handle	Existing		0.2* #
				<u>Rear Door</u>			
20	000786	BDY	REPAIR	R Rear Door Shell	Existing		8.5*
21		REF	REFINISH	R Rear Door Outside		C	1.6
22	001958	BDY	REMOVE/INSTALL	R Rear Otr Belt Moulding		INC	
23	001960	BDY	REMOVE/INSTALL	R Rear Pillar Moulding			0.5 #
24	001964	BDY	REMOVE/INSTALL	R Rear Door Trim Panel			0.4
25	001980	BDY	REMOVE/INSTALL	R Rear Otr Door Handle			0.3
				<u>Roof</u>			
26	002989	BDY	REMOVE/INSTALL	R Roof Drip Moulding			0.6
				<u>MANUAL ENTRIES</u>			
27	900500	BDY *	REPAIR	ROPE REAR GLASS	Existing		0.3*
				<u>Side Body</u>			
28	001821	BDY	REPAIR	R Quarter Outer Panel Assy	Existing		9.5* #
29		REF	REFINISH	R Quarter Panel Outside		C	2.0
30				NO BLEND TO TRUNK AS DMG TO WHEELHOUSE AREA			
31	002044	BDY	REMOVE/INSTALL	R Rocker Moulding			0.5
				<u>Rear Lamps</u>			
32	001999	BDY	REMOVE/INSTALL	R Rear Combination Lamp		INC	
				<u>Rear Bumper</u>			
33	004609	BDY	REPAIR	Rear Bumper Cover	Existing		1.0* #
34				SPOT REFINISH DUE TO NEW DAMAGE SEE UPD			
35		REF	REFINISH/REPAIR	Rear Bumper Cover		C	1.0*
36				MODIFIED REFINISH WITH FULL CLEAR COAT			
37	001996	BDY	REMOVE/INSTALL	Rear Bumper Cover			1.8 #
				<u>Additional Costs &amp; Materials</u>			
38	936012		ADD'L COST	Hazardous Waste Disposal		3.00	*
39	936014		ADD'L COST	Flex Additive		8.00	*
				<u>ADDITIONAL OPERATIONS</u>			
40		REF	ADD'L OPR	Clear Coat			2.3
41	933003	BDY *	ADD'L OPR	Tint Color			0.5*
42	933017	BDY *	ADD'L OPR	Finish Sand And Buff			2.5*
43				.5 PER PANEL 2.5 MAX - 5 PANELS			
44	933018	BDY *	ADD'L OPR	Mask For Overspray		5.00	* 0.3*
				<u>MANUAL ENTRIES</u>			
45	900500	BDY *	REPAIR	ROPE WINDSHIELD	Existing		0.3*
46	900500	BDY *	REMOVE/REPLACE	Mask Jams for primer	** QUAL REPL PART	2.50	* 0.2*
				<u>Additional Costs &amp; Materials</u>			
47			ADD'L COST	Paint/Materials		329.80	*

\* - Judgment Item  
# - Labor Note Applies  
C - Included in Clear Coat Calc  
r - CEG R&R Time Used For This Labor Operation

Prior Damage:  
REAR BUMPER COVER

## Estimate Totals

Date: 6/15/2013 08:25 AM  
Estimate ID: CO13010108  
Estimate Version: 0  
Preliminary  
Profile ID: \* PDS

Inspection Site: NATIONWIDE COLLISION  
Address: 1312 DEWEY AVE  
LOS ANGELES, CA 90006  
(213) 389-8830  
(213) 389-8831  
Inspection Date: 6/13/2013

Body Shop: NATIONWIDE COLLISION  
Address: 1312 DEWEY AVE  
LOS ANGELES, CA 90006  
Telephone: (213) 389-8830  
Fax Phone: (213) 389-8831  
State Lic. No: TIN 27-0493541

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.  
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND  
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

Date: 6/15/2013 08:25 AM  
 Estimate ID: CO13010108  
 Unrelated Prior Damage  
 Estimate Version: 0  
 Preliminary  
 Profile ID: \* PDS

FOR SUPPLEMENTS CALL RICH PEREA, 760-275-6795 OR EMAIL  
 PDS9593@VERIZON.NET

## Property Damage Specialist

P.O. BOX 3237, INDIO, CA 92201  
 (760) 275-6795  
 Fax: (760) 863-5349  
 Email: PDS9593@VERIZON.NET

## Unrelated Prior Damage

Damage Assessed By: Roberta Kear

Appraised For: ROBERT MORENO INSURANCE - SHELLEY AMBRIZ

Condition Code: Good  
 Date of Loss: 6/ 6/2013

Type of Loss: Collision  
 Arrival Date: 6/13/2013

File Number: CO13010108  
 Claim Number: CO13010108

Insured: MYUNGHEE LEE  
 Owner: MYUNGHEE LEE  
 Address: 808 N EL CAMINO REAL #8, SAN CLEMENTE, CA 92672  
 Telephone: Home Phone: (213) 718-3949

Mitchell Service: 910534

Description: 2011 BMW 328i  
 Body Style: 4D Sed  
 VIN: WBAPH5C59BF093755  
 Mileage: 28,288  
 OEM/ALT: A  
 Color: BLACK  
 Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW  
 REAR WINDOW DEFOGGER, CRUISE CONTROL, TILT STEERING COLUMN, LEATHER SEAT  
 TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS  
 ALUM/ALLOY WHEELS, NAVIGATION SYSTEM, AUXILIARY INPUT, LEATHER STEERING WHEEL  
 AUTOMATIC TRANSMISSION, FRONT AIR DAM, GENUINE WOOD TRIM, AUTO AIR CONDITION  
 TRIP COMPUTER, VARIABLE ASSISTED STEERING, SIDE AIRBAGS, ANTI-THEFT SYSTEM  
 AUTOMATIC HEADLIGHTS, SIDE HEAD CURTAIN AIRBAGS, DAYTIME RUNNING LIGHTS  
 AM/FM STEREO CD/MP3 PLAYER, ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS  
 INTERIOR AIR FILTER, KEYLESS ENTRY SYSTEM, POWER DISC BRAKES  
 POWER HEATED EXTERIOR MIRRORS, POWER LIFTGATE/TRUNK, RAIN SENSING WIPERS  
 REAR WINDOW DIVERSITY ANTENNA, STEERING WHEEL AUDIO CONTROLS  
 SUNROOF/MOONROOF (POWER)

Vehicle Production Date: 10/11  
 Drive Train: 3.0L Inj 6 Cyl 6A RWD  
 License: 6UYK159 CA  
 Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Rear Bumper</u>							
1	004579	BDY	OVERHAUL	Rear Bumper Cover Assy	Remanufactured	450.00 *	2.8 #
2	004609	BDY	REMOVE/REPLACE	Rear Bumper Cover			INC #
3		REF	REFINISH	Rear Bumper Cover			C 2.7
4				NEW DAMAGE FROM LOSS AFTER THIS ONE			
<u>ADDITIONAL OPERATIONS</u>							
5		REF	ADD'L OPR	Clear Coat			1.1

ESTIMATE RECALL NUMBER: 06/15/2013 08:25:39 CO13010108

Mitchell Data Version: OEM: MAY\_13\_V  
 MAPP:MAY\_13\_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International  
 All Rights Reserved

Page 1 of 3

6

ADD'L COST

Additional Costs & Materials  
Paint/Materials

129.20 \*

\* - Judgment Item  
# - Labor Note Applies  
C - Included in Clear Coat Calc

Prior Damage:  
REAR BUMPER COVER

## Estimate Totals



Date: 6/15/2013 08:25 AM  
Estimate ID: CO13010108  
Unrelated Prior Damage  
Estimate Version: 0  
Preliminary  
Profile ID: \* PDS

Insurance Co: ROBERT MORENO INSURANCE SERVICES  
Address: P.O. BOX 5185  
FULLERTON, CA 92838  
Telephone: (714) 578-3366  
Fax Phone: (714) 738-5035

Inspection Site: NATIONWIDE COLLISION  
Address: 1312 DEWEY AVE  
LOS ANGELES, CA 90006  
(213) 389-8830  
(213) 389-8831  
Inspection Date: 6/13/2013

Body Shop: NATIONWIDE COLLISION  
Address: 1312 DEWEY AVE  
LOS ANGELES, CA 90006  
Telephone: (213) 389-8830  
Fax Phone: (213) 389-8831  
State Lic. No: TIN 27-0493541

ESTIMATE RECALL NUMBER: 06/15/2013 08:25:39 CO13010108

Mitchell Data Version: OEM: MAY\_13\_V

Software Version: MAPP:MAY\_13\_V  
7.0.485

Copyright (C) 1994 - 2013 Mitchell International  
All Rights Reserved

Page 3 of 3






































AUTO 02/02/2013 TO 02/02/2014 11 6UYK159

REGISTRATION VALID FROM TYPE LICENSE NUMBER

VEHICLE IDENTIFICATION NUMBER  
WBAPH5C59BF093755

MAKE  
BMW

DATE FIRST SOLD CLASS  
00/00/2012 KJ

MODEL  
2011

DATE ISSUED  
01/31/2013

TOTAL FEES PAID  
\$313 1900

REGISTERS OWNER  
LEE MYUNGHEE  
730 S KINGSLEY DR APT 219  
LOS ANGELES CA 90005-2449

BMW BK NA  
PO BX 3608  
DUBLIN  
OH

R0069  
L0214

43016  
141011720130126

STATE OF CALIFORNIA  
DEPARTMENT OF MOTOR VEHICLES  
VALIDATED REGISTRATION CARD  
READ REVERSE SIDE - IMPORTANT INSTRUCTIONS

N1748492

06/13/2013









