

 **View Claim Summary - File Number: 06272013-1000029**

GO BACK

Claim Summary been saved successfully...



Property Damage Specialist
P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : co13010605
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Steve Dernoncourt
Date of Loss : 2013-06-21
Whose Claim : Insured
Owner Name : erin wood
Insured Name : erin wood
Claimant Name :
Inspection Location : WORK PLACE

Appraisal Information

File Number : 06272013-1000029
Appraiser : Tony Nguyen
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-05
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) :
Possible Supplement :

Vehicle Information

Year : 2001
Make : Chevrolet
Model : S-10
Sub-model : PICK UP
VIN : 1GCDT13W01K190614
Plate : 6R125518

Date: 7/8/2013 11:30 AM
 Estimate ID: CO13010605
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
 (760) 275-6795
 Fax: (760) 863-5349

Damage Assessed By: TONY NGUYEN

Appraised For: STEVE DERNONCOURT / SD
 (714) 738-1383 ext. 2334

ROBERT MORENO INS
 (714) 738-1383

Condition Code: Good
 Date of Loss: 6/21/2013
 Deductible: 1,000.00
 File Number: CO13010605
 Claim Number: CO13010605

Type of Loss: Property Damage

Insured: ERIN WOOD
 Owner: ERIN WOOD
 Address: 28300 MOUNTAIN VIEW PL, QUAIL VALLEY, CA 92587
 Telephone: Home Phone: (951) 751-4882

Mitchell Service: 916492

Description: 2001 Chevrolet S10 LS
 Body Style: 4D PkUpCrw 4' Bed 122" WB
 VIN: 1GCDT13W01K190614

Drive Train: 4.3L Inj 6 Cyl 4WD
 License: 6R125518 CA
 Search Code: None

OEM/ALT: A
 Color: BLUE

Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, MANUAL AIR CONDITION
 CRUISE CONTROL, TILT STEERING COLUMN, SLIDING REAR PICKUP WINDOW
 ANTI-LOCK BRAKE SYS., FOG LIGHTS, PICKUP TRUCK BED LINER, ALUM/ALLOY WHEELS
 V6 ENGINE, 4WD OR AWD, FRONT AIR DAM, TINTED GLASS, VARIABLE ASSISTED STEERING
 ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS, DAYTIME RUNNING LIGHTS, AM/FM STEREO CD
 ELECTRONIC SHIFT TRANSFER CASE, FRONT AIR DAM WITH FOG LIGHTS
 FRONT BUCKET SEATS, KEYLESS ENTRY SYSTEM, POWER DISC BRAKES
 POWER HEATED EXTERIOR MIRRORS, STEP BUMPER

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	AUTO	REF	REFINISH	Tailgate Complete			C 2.5
2	631067	BDY	REPAIR	L Pickup Bed Side Panel Assy	Existing		8.0* #
3	AUTO	REF	REFINISH	L Bed Outer Side Panel			C 2.2
4	631086	BDY	REMOVE/REPLACE	Tailgate Shell	Qual Recycled Part	200.00	* 1.3 #r
5				@UNID AUTO 909-622-1381			
6				Line Markup %20.00		40.00	
7	627030	BDY	REMOVE/INSTALL	L Pickup Bed Wheel Opening Flare			0.3
8	601482	BDY	REMOVE/REPLACE	Tailgate Adhesive Nameplate	15126056 GM PART	57.52	0.1
9	602272	BDY	REMOVE/REPLACE	Tailgate Adhesive Nameplate	15629983 GM PART	33.58	0.1

ESTIMATE RECALL NUMBER: 07/08/2013 11:30:40 CO13010605

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Software Version: 7.0.486

All Rights Reserved

Page 1 of 3

Date: 7/8/2013 11:30 AM
 Estimate ID: CO13010605
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

10	601501	BDY	REMOVE/INSTALL	L Rear Combination Lamp				0.3
11	AUTO	BDY	OVERHAUL	Rear Bumper Assy				0.9
12	602054	BDY	REMOVE/REPLACE	Rear Bumper Face Bar	Remanufactured		421.00	* INC
13				@KEYSTONE 800-421-7866				
14	631719	BDY	REMOVE/REPLACE	Rear Otr Bumper Step Pad	15008936	GM PART	49.08	INC
15	933036	BDY *	ADD'L OPR	Sheetmetal Pull				2.0*
16	AUTO	REF	ADD'L OPR	Clear Coat				1.4
17	933003	BDY *	ADD'L OPR	Tint Color				0.5*
18	933018	BDY *	ADD'L OPR	Mask For Overspray			5.00	* 0.2*
19	AUTO		ADD'L COST	Paint/Materials			195.20	*

* - Judgment Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc
 r - CEG R&R Time Used For This Labor Operation

Estimate Totals

I. Labor Subtotals						II. Part Replacement Summary			
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals				Amount
Body	13.7	46.00	5.00	0.00	635.20	Taxable Parts			761.18
Refinish	6.1	46.00	0.00	0.00	280.60	Parts Adjustments			40.00
						Sales Tax	@	8.000%	64.09
	Non-Taxable Labor				915.80	Total Replacement Parts Amount			865.27
Labor Summary	19.8				915.80				
III. Additional Costs					Amount	IV. Adjustments			
Taxable Costs					195.20	Insurance Deductible			1,000.00-
Sales Tax			@	8.000%	15.62	Customer Responsibility			1,000.00-
Total Additional Costs					210.82				
Paint Material Method: Rates Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00									
						I. Total Labor:			915.80
						II. Total Replacement Parts:			865.27
						III. Total Additional Costs:			210.82
						Gross Total:			1,991.89
						IV. Total Adjustments:			1,000.00-
						Net Total:			991.89

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.

ESTIMATE RECALL NUMBER: 07/08/2013 11:30:40 CO13010605

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
 All Rights Reserved

Page 2 of 3

Point(s) of Impact

7 Left Rear Corner (P)

Inspection Site: WORK PLACE
Address: 28300 MOUNTAIN VIEW PL
TEMECULA, CA 92587
Inspection Date: 7/5/2013

COLLECT ALL FROM OWNER
***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!!!***

***COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS *NOT* AN ACCEPTANCE OF
COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE
DETERMINED BY ROBERT MORENO INSURANCE COMPANY.
THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY ROBERT
MORENO INSURANCE COMPANY.

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 07/08/2013 11:30:40 CO13010605

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3







