

Property Damage Specialist
P.O. Box 2002, Indio, CA 92202
(760) 275-6795
Fax: (760) 863-5349
Email: pds9593@verizon.com

APPRAISAL REPORT

DAMAGE ASSESSED BY: MITCHELL MITCHELL

FILE NUMBER: 10302013-100001
CLAIM NUMBER: AM13002175
DATE OF LOSS: None
TYPE OF LOSS:
APPRAISED FOR:

ASSIGNMENT DATE: None
CONTACT DATE: 10/29/2013
INSPECTION DATE: 10/30/2013
REC'D DATE: None

Point(s) of Impact

1 Right Front Corner (P)

INSURED: ROBERTO SALGADO
56756 VAN ELLA
BAKER, CA 92309
(760) 590-0864

CLAIMANT: None

OWNER: None

BODY SHOP: NO SHOP CHOICE

INSPECTION SITE: RESIDENCE
56756 VAN ELLA
BAKER, CA 92309

QUALITY RECYCLED PARTS: No
AFTERMARKET NEW PARTS: Yes
VEHICLE DRIVEABLE: Yes

Comments:

10/30 INSPECTED VEHICLE AT RESIDENCE W/O OWNER PRESENT. DAMAGE TO RT
BUMPER, FENDER, AND HEADLIGHT COVER SCRAPED. VEHICLE IN GOOD
CONDITION. NO REGISTRATION AVAILABLE AT TIME OF INSPECTION.

COMPARISON ESTIMATE:	0.00	TOWING:	0.00	ACTUAL CASH VALUE:	12,775.00
APPRAISER ESTIMATE:	637.63	STORAGE:	0.00	SALVAGE VALUE:	0.00
AGREED UPON AMOUNT:	0.00	DEDUCTIBLE:	500.00	SETTLEMENT:	0.00
				REPAIR VS. ACV:	0.00
DRAFT/CHECK NUMBER:	0			ESTIMATE FEE:	0.00
DRAFT/CHECK AMOUNT:	0.00			TRAVEL EXPENSE:	0.00
DATE ISSUED:	None			PHOTO EXPENSE:	0.00
				MISC EXPENSE:	0.00
				TOTAL CHARGES:	0.00