

Claim Summary been saved successfully...



Property Damage Specialist

P.O. Box 2002, Indio

California, United States

92202

Claim Information

Claim Number : CO13010724

Policy Number :

Insurance Company : Robert Moreno Insurance

Adjuster : Sandra Zaragoza

Date of Loss : 2013-06-24

Whose Claim : Claimant

Owner Name : AVA MARTINEZ

Insured Name : TAM CAN NGUYEN

Claimant Name : AVA MARTINEZ

Inspection Location : RESIDENCE

Appraisal Information

File Number : 07012013-1000022

Appraiser : Jaime Munoz

Reinspector : Not Assigned

Loss Type : Collision

Inspection Date : 2013-07-03

Assigned Date/Time : 2013-07-02 19:00:00

Assignment Type : Full Appraisal

ERT (Days) :

Possible Supplement : YES

Vehicle Information

Year : 1998

Make : Honda

Model : CR-V

Sub-model :

VIN : JHLRD1861WC075682

Plate : 4CRS577

State : California

Milage : 140536

Drivable : No

Primary POI : RIGHT

Secondary POI : LEFT FRONT & REAR

Vehicle Condition : Fair

Interior Condition : Fair

Paint Condition : Fair

Engine : Fair

Repair Information

Recommendation : Total Loss

Estimate 1 Total : 5982.00

Estimate 2 Total : 0.00

Estimate 1 Betterment : 0.00

Estimate 2 Betterment : 0.00

Supplement 1 Total : 0.00

Supplement 1 Betterment : 0.00

Supplement 2 Total : 0.00

Supplement 2 Betterment : 0.00

Supplement 3 Total : 0.00

Supplement 3 Betterment : 0.00

Supplement 4 Total : 0.00

Supplement 4 Betterment : 0.00

Subtotal : 5982.00

Deductible : 0.00

Original Net Loss : 5982.00

Gross Total : 5982

Supplement Net Loss : 0.00

Tire Information

Make : HERCULES

Size : 215/70R/16

Tired Depth (in 32nds)

L/F 7/32" R/F 7/32"

L/R 8/32" R/R 8/32"

Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges : N/A

Storage Per Day :

Days :

Approximate Total : NaN

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

***TOTAL LOSS ***

Completed inspection and estimate on the vehicle at RESIDENCE in the town of Fontana , CA. on 5/03/2013 . Right and left side collision as photos show. Right quarter panel, right rear door, right front door, left front wheel and suspension, left and right rear suspension ,etc damaged due to loss. Estimate completed using prevailing labor rates in the area with industry accepted repair procedures. Excessive damage to the vehicle. Repairs exceeded 80% ACV. Therefore we suggest this vehicle appears to be a total loss. Vehicle remains at RESIDENCE . Vehicle interior and exterior condition considered average for year and model. The vehicle is

not drivable. No commitments were made.

No copies of this appraisal were released. Appraisal assignment completed 7/05/2013. Jaime Munoz, Independent Appraiser. CCC Form and KBB value.No storage charges accruing

Date: 7/7/2013 07:40 AM
Estimate ID: CO13010724
Estimate Version: 0
Preliminary
Profile ID: * Robert Moreno Ins.

FOR SUPPLEMENT CALL RICH PEREA 760-275-6795 OR E MAIL
pds9593@verizon.net

PROPERTY DAMAGE SPECIALIST

P.O. BOX 2002, INDIO, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: pds9593@verizon.net

Damage Assessed By: Jaime Munoz

Appraised For: Sandra Zaragoza
(714) 738-1383 ext. 2431

Condition Code: Fair
Date of Loss: 6/24/2013
Contact Date: 6/24/2013
Payer: Insurance
File Number: CO13010724
Claim Number: CO13010724

Type of Loss: Collision
Arrival Date: 7/3/2013
Accident Date: 6/24/2013
Deductible: 0.00

Insured: TAM NGUYEN
Claimant: AVA MARTINEZ
Address: 1841 S. PINE ST., SAN GABRIEL, CA 91776
Owner: AVA MARTINEZ
Address: 1841 S. PINE ST., SAN GABRIEL, CA 91776
Telephone:
Cell Phone: (626) 475-6775

Mitchell Service: 910120

Description: 1998 Honda CR-V EX
Body Style: 4D Ut
VIN: JHLRD1861WC075682
Mileage: 140,536
OEM/ALT: O
Color: BLUE
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, REAR WINDOW DEFOGGER
MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN, ANTI-LOCK BRAKE SYS.
ALUM/ALLOY WHEELS, TINTED GLASS, VARIABLE ASSISTED STEERING, AM/FM STEREO CD
FRONT BUCKET SEATS, KEYLESS ENTRY SYSTEM, POWER LIFTGATE\TRUNK
REAR WINDOW WIPER

Vehicle Production Date: 6/98
Drive Train: 2.0L Inj 4 Cyl 4WD
License: 4CRS577 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	000852	BDY	REMOVE/REPLACE	R Rocker Moulding	71800-S10-A00ZA	133.43	0.3
2	000924	BDY	REMOVE/REPLACE	R Frt Door Shell	Qual Recycled Part	450.00	* 3.5 #r
3	AUTO	REF	REFINISH	R Frt Door Outside			C 2.3
4	AUTO	REF	REFINISH	R Frt Add For Jambs & Interior			C 1.0
5				Schimmick's Auto 310-328-7513			
6				Line Markup %20.00		90.00	
7	000940	BDY	REMOVE/REPLACE	R Frt Door Moulding	75302-S10-003ZA	89.52	INC
8	001068	BDY	REMOVE/REPLACE	R Rear Door Shell	Qual Recycled Part	425.00	* 3.5 r
9	AUTO	REF	REFINISH	R Rear Door Outside			C 1.9
10	AUTO	REF	REFINISH	R Rear Add For Jambs & Interior			C 1.0
11				Schimmick's Auto 310-328-7513			
12				Line Markup %20.00		85.00	
13	001084	BDY	REMOVE/REPLACE	R Rear Door Moulding	75303-S10-003ZA	108.87	INC
14	001237	BDY	REPAIR	R Quarter Outer Panel	Existing		6.0* #

ESTIMATE RECALL NUMBER: 07/07/2013 07:40:54 CO13010724

Mitchell Data Version: JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 4

15	AUTO	REF	REFINISH	R Quarter Panel Outside				C	1.9
16				damage to right quarter leg					
17	001265	BDY	REMOVE/INSTALL	R Quarter Wheel Opening Flare				INC	
18	001267	BDY	REMOVE/INSTALL	R Quarter Mudguard					0.3
19	001269	BDY	REMOVE/REPLACE	R Quarter Wheel Opening Flare		74410-S10-010	65.77		0.2
20	001307	GLS	REMOVE/INSTALL	R Quarter Glass					1.5 #
21	001489	MCH	REMOVE/REPLACE	R UpR Rear Susp Control Arm	-M	52390-SR0-A00	65.63	0.3	#
22	001490	MCH	REMOVE/REPLACE	L UpR Rear Susp Control Arm	-M	52400-SR3-000	65.55	0.3	#
23	001499	MCH	REMOVE/REPLACE	R Lwr Rear Susp Control Arm	-M	52350-S10-A00	100.25	0.5	#
24	001500	MCH	REMOVE/REPLACE	L Lwr Rear Susp Control Arm	-M	52360-S10-A00	100.25	0.5	#
25	001503	MCH	REMOVE/REPLACE	R Rear Susp Bumper	-M	52341-S04-A00	38.65		
26	001504	MCH	REMOVE/REPLACE	L Rear Susp Bumper	-M	52341-S04-A00	38.65		
27	931105	MCH	REMOVE/REPLACE	Four Wheel Alignment		Sublet	89.95	*	0.0*
28	900500	MCH *	REMOVE/REPLACE	Mount & balance wheel 2 x \$ 12		Sublet	24.00	*	0.0*
29	931121	BDY	REMOVE/REPLACE	Left Front Wheel		Qual Recycled Part	125.00	*	0.0*
30				Line Markup %20.00			25.00		
31	001511	MCH	REMOVE/REPLACE	R Rear Susp Trailing Arm	-M	52370-S10-A12	352.48	2.7	#
32	001512	MCH	REMOVE/REPLACE	L Rear Susp Trailing Arm	-M	52371-S10-A12	352.48	1.1	#
33	001649	BDY	REMOVE/INSTALL	R Rear Combination Lamp					0.3
34	001688	BDY	REMOVE/INSTALL	Rear Bumper Assy					0.8
35	933006	FRM	ADD'L OPR	Frame/Rack Set Up					2.0*
36	933035	FRM	ADD'L OPR	Unibody Pull					4.0*
37	AUTO	REF	ADD'L OPR	Clear Coat					2.3
38	933017	BDY *	ADD'L OPR	Finish Sand And Buff					2.0*
39	933026	BDY	ADD'L OPR	LKQ Part Cleanup					1.0*
40	900500	BDY *	REPAIR	Clean adhesive		Existing			0.5*
41	900500	BDY *	REMOVE/REPLACE	Cover car for primer		** QUAL REPL PART	5.00	*	0.3*
42	900500	BDY *	REMOVE/REPLACE	Mask jambs for overspay		** QUAL REPL PART	3.00	*	0.3*
43	900500	BDY *	REMOVE/INSTALL	Set back main harness wiring		Existing			0.5*
44	900500	MCH *	REPAIR	Disconnect & reconnect electrical		Existing			0.5*
45	AUTO		ADD'L COST	Paint/Materials			364.00	*	

* - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc
r - CEG R&R Time Used For This Labor Operation

Estimate Totals

I. Labor Subtotals		Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary			Amount
	Body	19.5	50.00	0.00	0.00	975.00			Taxable Parts	2,394.53
	Refinish	10.4	50.00	0.00	0.00	520.00			Parts Adjustments	175.00
	Glass	1.5	50.00	0.00	0.00	75.00			Sales Tax @ 9.000%	231.26
	Frame	6.0	65.00	0.00	0.00	390.00			Non-Taxable Parts	238.95
	Mechanical	5.9	95.00	0.00	0.00	560.50			Parts Adjustments	25.00
	Non-Taxable Labor					2,520.50			Total Replacement Parts Amount	3,064.74
	Labor Summary	43.3				2,520.50				

ESTIMATE RECALL NUMBER: 07/07/2013 07:40:54 CO13010724

Mitchell Data Version: JUN 13 V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 2 of 4

III.	Additional Costs				Amount	IV.	Adjustments		Amount
	Taxable Costs				364.00		Insurance Deductible		0.00
	Sales Tax	@	9.000%	32.76			Customer Responsibility	0.00	
	Total Additional Costs				396.76				
	Paint Material Method: Rates								
	Init Rate = 35.00 , Init Max Hours = 99.9, Addl Rate = 0.00								

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

15 Total Loss (P)

Insurance Co: Robert Moreno Insurance Services
Address: P.O. BOX 5185
FULLERTON, CA 92838
Telephone: (714) 738-1383
Fax Phone: (714) 738-5035

Inspection Site: RESIDENCE
SAN GABRIEL, CA 91776
Inspection Date: 7/5/2013

Body Shop: OWNER'S CHOICE OF SHOP

COLLECT ALL FROM OWNER
***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER.
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!!!***

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 07/07/2013 07:40:54 CO13010724

Mitchell Data Version: JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 4

Date: 7/7/2013 07:40 AM
Estimate ID: CO13010724
Estimate Version: 0
Preliminary
Profile ID: * Robert Moreno Ins.

ESTIMATE RECALL NUMBER: 07/07/2013 07:40:54 CO13010724

Mitchell Data Version: JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 4 of 4

AUTO 07/12/2013 TO 07/12/2014 TYPE 11 LICENSE NUMBER 4CRS577

REGISTRATION VALID FROM

VEHICLE IDENTIFICATION NUMBER JHLRD1861WC075682

MAKE HOND

BODY TYPE MODEL SW CYLS. DATE FIRST SOLD 00/00/1998 CLASS BA YR 2013 Yr. Model 1998

DATE ISSUED 06/18/2013 TYPE VEH. 12S MP G AX WC UNLADEN/G/GW TOTAL FEES PAID \$107 1900

REGISTERED OWNER

LINENHOLD

MARTINEZ AVA MARIE
1841 S PINE ST
SAN GABRIEL CA 91776-4227

THE GREAT SEAL OF THE STATE OF CALIFORNIA

R0069
L0028

0

142060520130862



MFD. IN JAPAN BY HONDA MOTOR CO., LTD; 6/'98
GVWR 4165LBS GAWR F 2030LBS R 2155LBS
THIS VEHICLE CONFORMS TO ALL APPLICABLE
FEDERAL MOTOR VEHICLE SAFETY,
AND THEFT PREVENTION STANDARDS IN EFFECT
ON THE DATE OF MANUFACTURE SHOWN ABOVE:
V.I.N. **JHLRD1861WC075682**



MPV

JHLRD1861WC075682



























