

Claim Summary been saved successfully...



Property Damage Specialist

P.O. Box 2002, Indio

California, United States

92202

Claim Information

Claim Number : CO13010614

Policy Number :

Insurance Company : Robert Moreno Insurance

Adjuster : Preston Hobbs

Date of Loss : 2013-06-13

Whose Claim : Insured

Owner Name : ARMANDO RAMOS

Insured Name : ARMANDO RAMOS

Claimant Name :

Inspection Location : Owners Residence

Appraisal Information

File Number : 06252013-1000020

Appraiser : Brandon Martini

Reinspector : Not Assigned

Loss Type : Collision

Inspection Date : 2013-06-26

Assigned Date/Time :

Assignment Type : Full Appraisal

ERT (Days) : 2 days

Possible Supplement : Yes

Vehicle Information

Year : 2012

Make : Toyota

Model : Corolla

Sub-model : S

VIN : 5YFBU4EE9CP032593
Plate : 6VUT883
State : California
Milage : 12009
Drivable : Yes
Primary POI : Lt Rear
Secondary POI :
Vehicle Condition : Good
Interior Condition : Good
Paint Condition : Good
Engine : 1.8L

Repair Information

Recommendation : Repairable
Estimate 1 Total : 519.69
Estimate 2 Total : 0.00
Estimate 1 Betterment : 0.00
Estimate 2 Betterment : 0.00
Supplement 1 Total : 0.00
Supplement 1 Betterment : 0.00
Supplement 2 Total : 0.00
Supplement 2 Betterment : 0.00
Supplement 3 Total : 0.00
Supplement 3 Betterment : 0.00
Supplement 4 Total : 0.00
Supplement 4 Betterment : 0.00
Subtotal : 519.69
Deductible : 500.00
Total : 19.69
Original Net Loss : 519.69
Supplement Net Loss : 0.00

Tire Information

Make :
Size :
Tired Depth (in 32nds)

L/F R/F

L/R R/R

Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

The vehicle was inspected at the owners residence on 6/26/2013 at 11:30a. There may be possible hidden damage after the vehicle is torndown.

The owner was present at the time of inspection. The vehicle is repairable at this time. I was unable to photo the vehicle registration, the

registration was not available at the time of inspection; A photo of the glove box is attached to support. The estimated days to repair are 2

and please call 909-917-6777 if you have any questions.

FOR SUPPLEMENTS CALL RICH PEREA 762-275-6795 OR EMAIL
pds9593@verizon.net

Property Damage Specialist

P.O. Box 2002, Indio, CA 92201
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: Brandon Martini

Appraised For: Preston Hobbs

Condition Code: Good Type of Loss: Collision
Deductible: 500.00
File Number: CO13010614
Claim Number: CO13010614

Insured: Armando Ramos
Address: 143 N Alameda Ave., Azusa, CA 91702
Telephone: Home Phone: (626) 264-7082

Mitchell Service: 911092

Description: 2012 Toyota Corolla S Vehicle Production Date: 4/12
Body Style: 4D Sed Drive Train: 1.8L Inj 4 Cyl 4A FWD
VIN: 5YFBU4EE9CP032593 License: 6VUT883 CA
Mileage: 12,009
OEM/ALT: O Search Code: None
Color: Grey
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS
ALUM/ALLOY WHEELS, AUXILIARY INPUT, IPOD ADAPTER, AUTOMATIC TRANSMISSION
FRONT AIR DAM, TINTED GLASS, TRIP COMPUTER, SIDE AIRBAGS, ANTI-THEFT SYSTEM
SIDE HEAD CURTAIN AIRBAGS, DAYTIME RUNNING LIGHTS, AM/FM STEREO CD/MP3 PLAYER
ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS, INTERIOR AIR FILTER
KEYLESS ENTRY SYSTEM, POWER HEATED EXTERIOR MIRRORS, POWER LIFTGATE\TRUNK
REAR SPOILER, STEERING WHEEL AUDIO CONTROLS

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units	CEG Unit
<u>Rear Bumper</u>								
1	103786	BDY	OVERHAUL	Rear Bumper Cover Assy			1.3	1.3
2	103698	BDY	REMOVE/REPLACE	Rear Add w/Spoiler			0.6	0.6
3	103701	BDY	REPAIR	Rear Bumper Cover	Existing		1.5*	1.3
4		REF	REFINISH	Rear Bumper Cover			C 2.3	2.3
5	103706	BDY	REPAIR	L Rear Lwr Bumper Spoiler	Existing		0.5* #	0.2
6		REF	REFINISH	L Rear Lwr Spoiler			C 0.8	0.8
<u>Additional Costs & Materials</u>								
7	936014		ADD'L COST	Flex Additive		8.00 *		T
<u>ADDITIONAL OPERATIONS</u>								
8		REF	ADD'L OPR	Clear Coat			1.1	
<u>ADDITIONAL REFINISH OPERATIONS</u>								
9	933003	BDY *	ADD'L OPR	TINT COLOR			0.5*	
<u>Additional Costs & Materials</u>								
10			ADD'L COST	Paint/Materials		134.40 *		T
11			ADD'L COST	Hazardous Waste Disposal		3.00 *		T

ESTIMATE RECALL NUMBER: 06/28/2013 07:12:56 CO13010614

Mitchell Data Version: OEM: MAY_13_V

Software Version: 7.1.138

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

* - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc

Estimate Totals

I.	Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II.	Part Replacement Summary	Amount
	Body	4.4	42.00	0.00	0.00	184.80	T		
	Refinish	4.2	42.00	0.00	0.00	176.40	T	Total Replacement Parts Amount	0.00
	Taxable Labor					361.20			
	Labor Summary	8.6				361.20			
III.	Additional Costs					Amount	IV.	Adjustments	Amount
	Taxable Costs					145.40		Insurance Deductible	500.00-
	Sales Tax		@	9.000%		13.09		Customer Responsibility	500.00-
	Total Additional Costs					158.49			
	Paint Material Method: Rates								
	Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00								
	I.	Total Labor:							361.20
	II.	Total Replacement Parts:							0.00
	III.	Total Additional Costs:							158.49
		Gross Total:							519.69
	IV.	Total Adjustments:							500.00-
		Net Total:							19.69

Point(s) of Impact

7 Left Rear Corner (P)

Insurance Co: Robert Moreno Ins - Fullerton CA
Address: P.O. Box 5185
Fullerton, CA 92635
Work Phone: (714) 738-1383
Fax Phone: (714) 738-5035

Inspection Site: Owners Residence
Address: 143 N Alameda Ave.
Azusa, CA 91702
Inspection Date: 6/25/2013

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE

ESTIMATE RECALL NUMBER: 06/28/2013 07:12:56 CO13010614

Mitchell Data Version: OEM: MAY_13_V

Software Version: 7.1.138

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 2 of 3

REINSPECTED PRIOR TO REPAIR BY THE APPRAISER.
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!***

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts

















