

**View Claim Summary - File Number: 06112013-1000035**[GO BACK](#)**Claim Summary been saved successfully...****Property Damage Specialist**P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : CO13009865
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Brandt Faraone
Date of Loss : -0001-11-30
Whose Claim : Insured
Owner Name : VINCENTE MIRANDA
Insured Name : VINCENTE MIRANDA
Claimant Name :
Inspection Location :

Appraisal Information

File Number : 06112013-1000035
Appraiser : Tony Nguyen
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-06-29
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) :
Possible Supplement :

Vehicle Information

Year : 1995
Make : GMC
Model : Sonoma
Sub-model :
VIN : 1GTCS1442S8507089
Plate : 7M98658

State : California
Milage : 217354
Drivable : Yes
Primary POI :
Secondary POI :
Vehicle Condition : Fair
Interior Condition :
Paint Condition :
Engine :

Repair Information

Recommendation : Total Loss
Estimate 1 Total : 2969.84
Estimate 2 Total : 1862.36
Estimate 1 Betterment : 0.00
Estimate 2 Betterment : 0.00
Supplement 1 Total : 0.00
Supplement 1 Betterment : 0.00
Supplement 2 Total : 0.00
Supplement 2 Betterment : 0.00
Supplement 3 Total : 0.00
Supplement 3 Betterment : 0.00
Supplement 4 Total : 0.00
Supplement 4 Betterment : 0.00
Subtotal : 4832.20
Deductible : 0.00
Original Net Loss : 4832.20
Gross Total : 4832.2
Supplement Net Loss : 0.00

Tire Information

Make :
Size :
Tired Depth (in 32nds)
L/F R/F
L/R R/R
Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

COMPLETED INSPECTION & ESTIMATE OF INSURED VEHICLE AT RESIDENCE IN MORENO VALLEY ON 6/29/13. INSURED WAS NOT PRESENT BUT STATED RIGHT BEDSIDE AS COLLISION DAMAGE. HE DIDN'T HAVE A CHOICE OF SHOP AT TIME OF INSPECTION. ESTIMATE WRITTEN AT AREAS PREVAILING RATES USING OEM PARTS OVER LKQ. LKQ PARTS LEAVES VEHICLE @ CLOSE TO BORDERLINE TOTAL. REAR SUSPENSION OPEN. ESTIMATE EXCEEDS THRESHOLD AND VEHICLE IS A TOTAL LOSS. PLEASE CALL IF YOU HAVE ANY QUESTIONS TONY NGUYEN 714-757-0906.



Used Vehicle Valuation Report

Report Date: 07/03/2013

Effective Dates: 06/28/2013 - 07/03/2013

1995 GMC Sonoma Regular Cab Short Bed

VIN: 1GTCS1442S8507089

Reference:

Base Values				
	Excellent	Very Good	Good	Fair
MSRP	\$10,820	--	--	--
Certified Pre-Owned	NA	--	--	--
Suggested Retail	\$2,375	--	--	--
Private Party	\$1,650	\$1,525	\$1,450	\$950
Lending Value	\$1,175	--	--	--
Auction	\$1,100	\$1,025	\$950	\$675
Trade-In	\$850	\$775	\$700	\$425
Value as of: 07/03/2013 Engine: 4-Cyl, 2.2 Liter Included Zip Code: 92553 Transmission: Manual, 5-Spd Included Condition: Fair Drivetrain: 2WD Included Mileage: 217,354 \$(50)/\$(50)				
Itemized Equipment				
(Lending Value / Suggested Retail)				
SL	\$75/\$100	AM/FM Stereo	Included	
Air Conditioning	\$175/\$235	Bed Liner	\$50/\$65	
Power Steering	Included	Steel Wheels	\$0/\$0	
Total Itemized Equipment:				\$300/\$400
Total Values including Mileage and Option adjustments				
	Excellent	Very Good	Good	Fair
MSRP	\$10,820	--	--	--
Certified Pre-Owned	NA	--	--	--
Suggested Retail	\$2,725	--	--	--
Private Party	\$2,000	\$1,875	\$1,800	\$1,300
Lending Value	\$1,425	--	--	--
Auction	\$1,350	\$1,275	\$1,200	\$925
Trade-In	\$1,100	\$1,025	\$950	\$675
-- Assumes excellent condition.				
Notes:				

©2013 Kelley Blue Book® Co., Inc. All rights reserved. 06/28/2013 - 07/03/2013 Edition for California 92553. The specific information required to determine the value for this particular vehicle was supplied by the person generating this report. Vehicle valuations are opinions and may vary from vehicle to vehicle. Actual valuations will vary based upon market conditions, specifications, vehicle condition or other particular circumstances pertinent to this particular vehicle or the transaction or the parties to the transaction. This report is intended for the individual use of the person generating this report only and shall not be sold or transmitted to another party. Kelley Blue Book® assumes no responsibility for errors or omissions. (v.13070)

CCC valuescope Basic Claim Information Form



CCC VALUESCOPE.

Report Retrieval Method	<input type="checkbox"/> Email	<input type="checkbox"/> Fax	<input type="checkbox"/> Other (Specify)
CCC Phone: 1-800-621-8070		CCC Fax: 1-800-621-7070	
CCC Email: CCCValuescopeRequest@cccis.com			
Office ID Number		Claim Number CO13009865	
Adjr Name (First & Last) BRANDT FARAONE		Appr Name (First & Last) TONY NGUYEN	
Adjr Contact# 714-738-1383		Insured's Name VICENTE MIRANDA	
Owner's Name SAME		Owner's Phone 951-796-4759	
Loss ZIP Code 92553		Loss State CA	
Loss Type <input checked="" type="checkbox"/> Collision <input type="checkbox"/> Theft		Coverage code <input type="checkbox"/> Collision <input type="checkbox"/> Comprehensive <input type="checkbox"/> Liability <input type="checkbox"/> Other	
3rd Party Claim <input type="checkbox"/> Yes <input type="checkbox"/> No		Leased Vehicle <input type="checkbox"/> Yes <input type="checkbox"/> No	
Date of Loss 6-1-13		Exch#Policy #	
Adjuster ID#		Claim Class	
PA Appr ID#			
VIN 1GTCS1442S8507089			
Year 1995	Make GMC	Model SONOMA SL	
Body Style	<input checked="" type="checkbox"/> 2DR <input type="checkbox"/> 4DR <input type="checkbox"/> Hatchback <input type="checkbox"/> Convertible <input type="checkbox"/> Wagon <input checked="" type="checkbox"/> Pickup <input type="checkbox"/> Van <input type="checkbox"/> Utility		
<input type="checkbox"/> 1/2 Ton <input type="checkbox"/> 3/4 Ton <input type="checkbox"/> 1 Ton <input type="checkbox"/> Short Bed <input type="checkbox"/> Long Bed <input type="checkbox"/> Cab & Chassis <input type="checkbox"/> Fleetside <input type="checkbox"/> Fenderside			
Engine Size 2.2L	Cylinders <input type="checkbox"/> 3 <input checked="" type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6 <input type="checkbox"/> 8 <input type="checkbox"/> 10 <input type="checkbox"/> 12 <input type="checkbox"/> Turbo <input type="checkbox"/> Diesel		
Mileage ("UNK" if unknown) 217354			
Transmission <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> S6 <input type="checkbox"/> S5 <input type="checkbox"/> S4 <input type="checkbox"/> S3 <input type="checkbox"/> OD <input type="checkbox"/> 4W <input type="checkbox"/> PO			
Power Options <input checked="" type="checkbox"/> PS Power Steering <input checked="" type="checkbox"/> PB Power Brakes <input type="checkbox"/> PW Power Windows <input type="checkbox"/> PL Power Locks <input type="checkbox"/> SP Power Driver Seat <input type="checkbox"/> PC Power Passenger Seat <input type="checkbox"/> PA Power Antenna <input type="checkbox"/> PM Power Mirrors <input type="checkbox"/> PT Power Trunk/Tailgate <input type="checkbox"/> PP Power Adjustable Petals <input type="checkbox"/> PD Power Sliding Door <input type="checkbox"/> DP Dual Power Sliding Doors Décor/Convenience <input checked="" type="checkbox"/> AC Air Conditioning <input type="checkbox"/> DA Dual Air Conditioning <input type="checkbox"/> CL Climate Control <input type="checkbox"/> RD Rear Defogger <input type="checkbox"/> IW Intermittent Wipers <input type="checkbox"/> TW Tilt Wheel <input type="checkbox"/> TL Telescopic Wheel <input type="checkbox"/> CC Cruise Control <input type="checkbox"/> KE Keyless Entry <input type="checkbox"/> CN Console/Storage <input type="checkbox"/> CO Overhead Console <input type="checkbox"/> EC Entertainment Center <input type="checkbox"/> NV Navigation System <input type="checkbox"/> C2 Communications System <input type="checkbox"/> HU Heads Up Display <input type="checkbox"/> WT Wood Interior Trim <input type="checkbox"/> EI Electronic Instrumentation <input type="checkbox"/> IB On Board Computer <input type="checkbox"/> MC Message Center <input type="checkbox"/> MM Memory Package <input type="checkbox"/> RJ Remote Start	Seating <input checked="" type="checkbox"/> CS Cloth Seats <input type="checkbox"/> LS Leather Seats <input type="checkbox"/> RL Reclining/ Lounge Seats <input type="checkbox"/> BS Bucket Seats <input type="checkbox"/> SH Heated Seats (2) <input type="checkbox"/> RH Rear Heated Seats <input type="checkbox"/> 3S Third Row Seat <input type="checkbox"/> 3P Power Third Seat <input type="checkbox"/> R3 Retractable Seats <input type="checkbox"/> 2P 12 Passenger Seating <input type="checkbox"/> 5P 15 Passenger Seating <input type="checkbox"/> B2 Captain Chairs (2) <input type="checkbox"/> B4 Captain Chairs (4) <input type="checkbox"/> B6 Captain Chairs (6) Radio <input checked="" type="checkbox"/> AM AM Radio <input checked="" type="checkbox"/> FM FM Radio <input checked="" type="checkbox"/> ST Stereo <input checked="" type="checkbox"/> CA Cassette <input type="checkbox"/> SE Search/Seek <input type="checkbox"/> CD Compact Disc Player <input type="checkbox"/> SK CD Changer/Stacker <input type="checkbox"/> UR Premium Radio <input type="checkbox"/> XM Satellite Radio <input type="checkbox"/> TQ Steering Wheel Touch Controls <input type="checkbox"/> M3 Auxiliary Audio Connection <input type="checkbox"/> EQ Equalizer <input type="checkbox"/> CB CB Radio <input type="checkbox"/> 8T 8 Track Tape Player Wheels <input type="checkbox"/> AW Aluminum/Alloy Wheels <input type="checkbox"/> CJ Chrome Wheels <input type="checkbox"/> W2 20" or Larger Wheels <input type="checkbox"/> DC Deluxe Wheel Covers <input type="checkbox"/> FC Full Wheel Covers <input type="checkbox"/> SA Spoke Aluminum Wheels <input type="checkbox"/> SY Styled Steel Wheels <input type="checkbox"/> WW Wire Wheels <input type="checkbox"/> WC Wire Wheel Covers <input type="checkbox"/> RW Rally Wheels <input type="checkbox"/> KW Locking Wheels <input type="checkbox"/> LC Locking Wheel Covers	Roof <input type="checkbox"/> EG Electric Glass Roof <input type="checkbox"/> ES Electric Steel Roof <input type="checkbox"/> OR Skyview Roof <input type="checkbox"/> SD Dual Power Roofs <input type="checkbox"/> MS Manual Steel Roof <input type="checkbox"/> MG Manual Glass Roof <input type="checkbox"/> FR Flip Roof <input type="checkbox"/> TT T-Top/Panel <input type="checkbox"/> GT Glass T-Top/Panel <input type="checkbox"/> MV Manual Convertible Roof <input type="checkbox"/> VP Power Convertible Roof <input type="checkbox"/> RM Detachable Roof <input type="checkbox"/> VR Vinyl Roof <input type="checkbox"/> RF Cabriolet Roof <input type="checkbox"/> LR Landau Roof <input type="checkbox"/> LP Padded Landau Roof <input type="checkbox"/> PV Padded Vinyl Roof <input type="checkbox"/> CT Soft Top <input type="checkbox"/> HT Hard Top Safety/Brakes <input type="checkbox"/> AG Air Bag <input type="checkbox"/> RG Passenger Air Bag <input type="checkbox"/> XG Front Side Impact Air Bags <input type="checkbox"/> ZG Rear Side Impact Air Bags <input type="checkbox"/> DG Head/Roof Air Bags <input type="checkbox"/> TD Theft Deterrent/Alarm <input type="checkbox"/> VZ Night Vision <input type="checkbox"/> IC Intelligent Cruise <input type="checkbox"/> PJ Parking Sensors <input type="checkbox"/> PX Parking Sensors W/Equip <input type="checkbox"/> AB Anti-Lock Brakes (4) <input type="checkbox"/> A2 Anti-Lock Brakes (2) <input type="checkbox"/> DB 4-Wheel Disc Brakes <input type="checkbox"/> RB Rollover Protection <input type="checkbox"/> TX Traction Control <input type="checkbox"/> T1 Stability Control <input type="checkbox"/> AL Auto Level	Exterior/Paint/Glass <input type="checkbox"/> RR Luggage/Roof Rack <input type="checkbox"/> WG Woodgrain <input type="checkbox"/> WP Rear Window Wiper <input type="checkbox"/> 2T Two Tone Paint <input type="checkbox"/> D2 Deluxe 2 Tone Paint <input type="checkbox"/> HP Three Stage Paint <input checked="" type="checkbox"/> IP Clearcoat Paint <input type="checkbox"/> MP Metallic Paint <input type="checkbox"/> SL Rear Spoiler <input type="checkbox"/> FL Fog Lamps <input type="checkbox"/> TG Tinted Glass <input type="checkbox"/> DT Privacy Glass <input type="checkbox"/> BN Body Side Moldings <input checked="" type="checkbox"/> DM Dual Mirrors <input type="checkbox"/> HM Heated Mirrors <input type="checkbox"/> HV Headlamp Washers <input type="checkbox"/> MX Signal Integrated Mirrors Other <input type="checkbox"/> BD Running Board/Side Steps <input type="checkbox"/> UP Power Retractable Running Boards <input type="checkbox"/> XE Xenon Headlamps <input type="checkbox"/> AR Bed Rails <input checked="" type="checkbox"/> BL Bedliner <input type="checkbox"/> BY Bedliner (Spray On) <input type="checkbox"/> CP Fiberglass Cap <input type="checkbox"/> GG Grill Guard <input type="checkbox"/> SB Rear Step Bumper <input type="checkbox"/> SS Swivel Seats <input type="checkbox"/> SW Rear Sliding Window <input type="checkbox"/> PG Power Rear Window <input type="checkbox"/> TB Tool Box (Permanent) <input type="checkbox"/> TN Tonneau Cover – Soft <input type="checkbox"/> TZ Tonneau Cover – Hard <input type="checkbox"/> TP Trailing Package <input type="checkbox"/> WD Dual Rear Wheels <input type="checkbox"/> XT Auxiliary Fuel Tank <input type="checkbox"/> 3D 3rd Truck Door <input type="checkbox"/> 4D 4th Door Truck/Van <input type="checkbox"/> BC Bumper Cushions <input type="checkbox"/> BG Bumper Guards <input type="checkbox"/> EM California Emissions <input type="checkbox"/> SG Stone Guard <input type="checkbox"/> WI Winch

CCC Valuescope Basic Claim Information Form (Continued)

Office ID Number				Claim Number			
REFURBISHMENTS							
Transmission	Purchase Price		Mileage		Engine	Purchase Price	
Tires	Purchase Price		# of Tires				
Paint	<input type="checkbox"/> Basic	<input type="checkbox"/> Standard	<input type="checkbox"/> Custom	Date Painted	Purchase Price		
Interior	Purchase Price		Date	<input type="checkbox"/> Leather	<input type="checkbox"/> Vinyl	<input type="checkbox"/> Cloth	
Camper Shell	Purchase Price		Date	Carpet Kit	Purchase Price		Date
Special Wheels	Purchase Price		Date				
Other	Description				Purchase Price		Date
<input type="checkbox"/> Restored	Restored Amount						
Package/Special Features/Additional Options (XXXX=CALL BACK)							
CONDITION RATING: Rate each of the following 0=Below Average, 1=Normal, 2=Above Average, 3=Exceptional						COMMENTS	
Seats	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Significantly soiled, stained or faded. Small/few tears, holes or burn marks.		
Carpet	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Significantly soiled or stained. Small/few tears, holes or burn marks. Significant wear or bare spots		
Dashboard	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	No significant cracks, scratches or gouges. Components firmly intact. Light wear or fading		
Headliner	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Clean. No tears or sagging. Light fading		
Body	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Sheetmetal: Large/numerous dents or areas of rust. Misaligned or missing panels. Trim: Heavily damaged, misaligned or missing components. Severe peeling, fading or rusting		
Glass	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	No scratches, pitting or chips. Seals are intact and watertight		
Paint	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Small/few deep chips or scratches. Minimal peeling or flaking. Significant fading. Evidence of repainting		
Engine	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Small/few leaks. Belts and hoses show significant wear. Significant dirt and grease in engine compartment. Minimal burn marks around tailpipe.		
Transmission	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Fluid discolored. Minor seepage		
Front Tires	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	5-7/32" of tread present. 41% to 68% of new. No signs of uneven wear		
Rear Tires	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	5-7/32" of tread present. 41% to 68% of new. No signs of uneven wear		
ADJUSTMENTS							
Pre Tax Adjustment 1					Add	Deduct	
Pre Tax Adjustment 2					Add	Deduct	
Sales Tax %	Leave blank if using AutoTax				Deductible		
Post Tax Adjustment 1					Add	Deduct	
Post Tax Adjustment 2					Add	Deduct	

Date: 7/ 3/2013 07:30 AM
Estimate ID: CO13009865
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: TONY NGUYEN

Appraised For: BRANDT FARAONE / RMIS
(714) 738-1383 ext. 2419

ROBERT MORENO INS
(714) 738-1383

Condition Code: Fair
Date of Loss: 6/ 1/2013
Deductible: 0.00
File Number: CO13009865
Claim Number: CO13009865

Type of Loss: Property Damage

Insured: VICENTE MIRANDA
Owner: VICENTE MIRANDA
Address: 13103 BENDER AVE , MORENO VALLEY, CA 92553
Telephone: Home Phone: (951) 796-4759

Mitchell Service: 916492

Description: 1995 GMC Sonoma SL
Body Style: 2D PkUp 6' Bed 108" WB
VIN: 1GTCS1442S8507089
Mileage: 217,354
OEM/ALT: A
Color: WHITE
Options: POWER STEERING, CASSETTE PLAYER

Drive Train: 2.2L Inj 4 Cyl 2WD
License: 7M98658 CA

Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	608240	BDY	REMOVE/REPLACE	Wheel Spare	9591886 GM PART	136.98	0.3
2				RT REAR			
3	626190	BDY	REMOVE/INSTALL	Bed Assembly			INC
4	900500	BDY *	REMOVE/INSTALL	BEDLINER	Existing		1.0* r
5	601466	BDY	REMOVE/INSTALL	Tailgate Assembly			0.2
6	626380	BDY	REMOVE/REPLACE	R Pickup Bed Side Panel Assy	ORDER FROM DEALER	d1222.26	12.8 #
7	AUTO	REF	REFINISH	R Bed Outer Side Panel			C 3.3
8	AUTO	REF	REFINISH	R Bed Side Panel Inside			C 1.6
9	931105	MCH	ADD'L LABOR OP	FOUR WHEEL ALIGNMENT	Sublet	69.99	* 0.0*
10	931125	BDY	ADD'L LABOR OP	Mount & Balance Tire	Sublet	15.00	* 0.0*
11	629850	BDY	REMOVE/INSTALL	Rear Bumper Assy			INC
12	630010	BDY	REPAIR	R Rear Bumper Extension	Existing		0.0*#
13	AUTO	REF	REFINISH	R Rear Bumper Extension			C 0.6
14	933021	BDY *	ADD'L OPR	De-Nib And Finesse			1.0*

ESTIMATE RECALL NUMBER: 07/03/2013 07:30:05 CO13009865

Mitchell Data Version: OEM: JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

Date: 7/ 3/2013 07:30 AM
 Estimate ID: CO13009865
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

15	AUTO	REF	ADD'L OPR	Clear Coat		2.1
16	933003	BDY *	ADD'L OPR	Tint Color		0.5*
17	933018	BDY *	ADD'L OPR	Mask For Overspray	5.00 *	0.2*
18	AUTO		ADD'L COST	Paint/Materials	258.40 *	

* - Judgment Item
 # - Labor Note Applies
 d - Discontinued by the Manufacturer
 C - Included in Clear Coat Calc
 r - CEG R&R Time Used For This Labor Operation

Prior Damage:
 FRT AND LFT BEDSIDE

Estimate Totals

I. Labor Subtotals						II. Part Replacement Summary				Amount
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	Taxable Parts				
Body	16.0	48.00	5.00	15.00	788.00	Sales Tax	@	8.000%	1,359.24	
Refinish	7.6	48.00	0.00	0.00	364.80				108.74	
Mechanical	0.0	65.00	0.00	69.99	69.99					
Non-Taxable Labor					1,222.79	Total Replacement Parts Amount				1,467.98
Labor Summary	23.6				1,222.79					
III. Additional Costs					Amount	IV. Adjustments				Amount
Taxable Costs					258.40	Insurance Deductible				0.00
Sales Tax					20.67	Customer Responsibility				0.00
Total Additional Costs					279.07					
Paint Material Method: Rates										
Init Rate = 34.00 , Init Max Hours = 99.9, Addl Rate = 0.00										
						I.	Total Labor:		1,222.79	
						II.	Total Replacement Parts:		1,467.98	
						III.	Total Additional Costs:		279.07	
							Gross Total:		2,969.84	
						IV.	Total Adjustments:		0.00	
							Net Total:		2,969.84	
										TOTAL LOSS

Date: 7/ 3/2013 07:30 AM
Estimate ID: CO13009865
Estimate Version: 0
Preliminary
Profile ID: * PDS

Point(s) of Impact

15 Total Loss (P), 3 Right Side (S), 4 Right Rear Side (S)

Inspection Site: RESIDENCE
Address: 13103 BENDER AVE
MORENO VALLEY, CA 92553

COLLECT ALL FROM OWNER

***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***

***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!***

***COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS *NOT* AN ACCEPTANCE OF
COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE
DETERMINED BY ROBERT MORENO INSURANCE COMPANY.
THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY ROBERT
MORENO INSURANCE COMPANY.

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 07/03/2013 07:30:05 CO13009865

Mitchell Data Version: OEM: JUN_13_V

Software Version: MAPP:JUN_13_V 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3

Date: 7/ 3/2013 07:17 AM
Estimate ID: CO13009865
Unrelated Prior Damage
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Unrelated Prior Damage

Damage Assessed By: TONY NGUYEN

Appraised For: BRANDT FARAONE / RMIS
(714) 738-1383 ext. 2419

ROBERT MORENO INS
(714) 738-1383

Condition Code: Fair
Date of Loss: 6/ 1/2013

Type of Loss: Property Damage

File Number: CO13009865
Claim Number: CO13009865

Insured: VICENTE MIRANDA
Owner: VICENTE MIRANDA
Address: 13103 BENDER AVE , MORENO VALLEY, CA 92553
Telephone: Home Phone: (951) 796-4759

Mitchell Service: 916492

Description: 1995 GMC Sonoma SL
Body Style: 2D PkUp 6' Bed 108" WB
VIN: 1GTCS1442S8507089
Mileage: 217,354
OEM/ALT: A
Color: WHITE

Drive Train: 2.2L Inj 4 Cyl 2WD
License: 7M98658 CA

Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	601090	BDY	REPAIR	Frt Bumper Cover	Existing		1.0*#
2	AUTO	REF	REFINISH	Frt Bumper Cover			C 2.0
3	630155	BDY	REMOVE/REPLACE	Grille	15647631 GM PART	d144.94	0.3
4	606280	BDY	REPAIR	R Fender Panel	Existing		3.0*#
5	AUTO	REF	REFINISH	R Fender Outside			C 2.0
6	631770	BDY	REPAIR	L Pickup Bed Side Panel Assy	Existing		14.0*#
7	AUTO	REF	REFINISH	L Bed Outer Side Panel			C 2.7
8	630020	BDY	REPAIR	L Rear Bumper Extension	Existing		1.0*#
9	AUTO	REF	REFINISH	L Rear Bumper Extension			C 0.6
10	AUTO	REF	ADD'L OPR	Clear Coat			1.9
11	AUTO		ADD'L COST	Paint/Materials		312.80	*

ESTIMATE RECALL NUMBER: 07/03/2013 06:38:09 CO13009865

Mitchell Data Version: OEM: JUN_13_V

Software Version: 7.0.486

MAPP:JUN_13_V
Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

Date: 7/ 3/2013 07:17 AM
 Estimate ID: CO13009865
 Unrelated Prior Damage
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

* - Judgment Item
 # - Labor Note Applies
 d - Discontinued by the Manufacturer
 C - Included in Clear Coat Calc

Prior Damage:
 FRT AND LFT BEDSIDE

Estimate Totals

I. Labor Subtotals		Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary						Amount		
Body		19.3	48.00	0.00	0.00	926.40	Taxable Parts						144.94		
Refinish		9.2	48.00	0.00	0.00	441.60	Sales Tax @ 8.000%						11.60		
Non-Taxable Labor						1,368.00	Total Replacement Parts Amount						156.54		
Labor Summary		28.5				1,368.00									
III. Additional Costs						Amount	IV. Adjustments						Amount		
Taxable Costs						312.80	Total Adjustments:						0.00		
Sales Tax @ 8.000%						25.02									
Total Additional Costs						337.82									
Paint Material Method: Rates															
Init Rate = 34.00 , Init Max Hours = 99.9, Addl Rate = 0.00															

Date: 7/ 3/2013 07:17 AM
Estimate ID: CO13009865
Unrelated Prior Damage
Estimate Version: 0
Preliminary
Profile ID: * PDS

Inspection Site: RESIDENCE
Address: 13103 BENDER AVE
MORENO VALLEY, CA 92553

ESTIMATE RECALL NUMBER: 07/03/2013 06:38:09 CO13009865

Mitchell Data Version: OEM: JUN_13_V

Software Version: MAPP:JUN_13_V
7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3









