

**View Claim Summary - File Number: 06272013-100009**[GO BACK](#)**Claim Summary been saved successfully...****Property Damage Specialist**P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : CO13010711
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Josh Turner
Date of Loss : 2013-06-26
Whose Claim : Insured
Owner Name : ROSEMARY GUTIERREZ
Insured Name : ROSEMARY GUTIERREZ
Claimant Name :
Inspection Location : BODYSHOP

Appraisal Information

File Number : 06272013-100009
Appraiser : Tony Nguyen
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-08
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) :
Possible Supplement : YES

Vehicle Information

Year : 2013
Make : Kia
Model : Forte
Sub-model : LX
VIN : KNAFT4A29D5719777
Plate : 6YZL437

State : California
Milage : 9271
Drivable : Yes
Primary POI : FRONT END
Secondary POI : LEFT QUARTER
Vehicle Condition : Good
Interior Condition :
Paint Condition :
Engine :

Repair Information

Recommendation : Total Loss
Estimate 1 Total : 17824.89
Estimate 2 Total : 0.00
Estimate 1 Betterment : 0.00
Estimate 2 Betterment : 0.00
Supplement 1 Total : 0.00
Supplement 1 Betterment : 0.00
Supplement 2 Total : 0.00
Supplement 2 Betterment : 0.00
Supplement 3 Total : 0.00
Supplement 3 Betterment : 0.00
Supplement 4 Total : 0.00
Supplement 4 Betterment : 0.00
Subtotal : 17824.89
Deductible : 500.00
Original Net Loss : 17324.89
Gross Total : 17824.89
Supplement Net Loss : 0.00

Tire Information

Make :
Size :
Tired Depth (in 32nds)
L/F R/F
L/R R/R
Spare :

Shop Information

Shop Name : COLLISION CENTER OF RIVERSIDE
Address 1 : 2376 MAIN ST
Address 2 :
City : RIVERSIDE
State : California
Zip : 92501
Phone Number : 951-683-4458
Fax :
Agreed Price : Yes
Federal Tax ID # : 80-0509190

Miscellaneous

Towing Charges : NO
Storage Per Day : 50
Days : 13
Approximate Total : NaN
Rental Vehicle : Unknown
Total Rental Potential Cost :
Actual Rental Days :
Actual Rental Amount :
Style :

Claim Remarks

COMPLETED INSPECTION OF INSURED'S VEHICLE AT COLLISION EXPERTS OF RIVERSIDE ON 7-8-13. I MET WITH BRIAN AT SHOP AND HE POINTED OUT DAMAGES TO FRONT AND LEFT REAR OF VEHICLE WITH DEPLOYED SIDE AIRBAGS AS PHOTOS SHOW. ESTIMATE CALCULATED IN THE AMOUNT OF \$17824.89 USING OEM PARTS. FRAME RAILS HEAVILY SWAYED AND CANNOT BE REPAIRED. ESTIMATE EXCEEDS THRESHOLD WITH FRT & REAR SUSPENSION OPEN. LARGE SUPPLEMENT ANTICIPATED FOR MECHANICAL, SUSPENSION AND SRS COMPONENTS. I SUGGEST THIS VEHICLE BE DEEMED A STRUCTURAL TOTAL LOSS. NO TOW BILL. VEHICLE WAS DRIVEN IN BUT SHOP COULD NOT FIND KEYS. NO TEARDOWN FEES. PLEASE CALL TONY NGUYEN WITH ANY QUESTIONS 714-757.0906



Used Vehicle Valuation Report

Report Date: 07/09/2013

Effective Dates: 07/04/2013 - 07/11/2013

2013 Kia Forte LX Sedan 4D

VIN: KNAFT4A29D5719777

Reference:

Base Values				
	Excellent	Very Good	Good	Fair
MSRP	\$16,175	--	--	--
Certified Pre-Owned	\$14,300	--	--	--
Suggested Retail	\$14,300	--	--	--
Private Party	\$13,100	\$12,650	\$12,250	\$11,000
Lending Value	\$13,250	--	--	--
Auction	\$12,750	\$12,500	\$11,950	\$10,550
Trade-In	\$11,850	\$11,600	\$11,050	\$9,625
Value as of: 07/09/2013 Engine: 4-Cyl, 2.0 Liter Included Zip Code: 92501 Transmission: Manual, 6-Spd w/OD Included Condition: Very Good Drivetrain: FWD Included Mileage: 9,271 \$250/\$250				
Itemized Equipment (Lending Value / Suggested Retail)				
Traction Control	Included	MP3 (Single Disc)	Included	
Stability Control	Included	SiriusXM Satellite	Included	
ABS (4-Wheel)	Included	Bluetooth Wireless	Included	
Air Conditioning	Included	Dual Air Bags	Included	
Power Steering	Included	Side Air Bags	Included	
Tilt Wheel	Included	F&R Head Curtain Air Bags	Included	
AM/FM Stereo	Included	Steel Wheels	Included	
Total Itemized Equipment:				\$0/\$0
Total Values including Mileage and Option adjustments				
	Excellent	Very Good	Good	Fair
MSRP	\$16,175	--	--	--
Certified Pre-Owned	\$15,200	--	--	--
Suggested Retail	\$14,550	--	--	--
Private Party	\$13,350	\$12,900	\$12,500	\$11,250
Lending Value	\$13,500	--	--	--
Auction	\$13,000	\$12,750	\$12,200	\$10,800
Trade-In	\$12,100	\$11,850	\$11,300	\$9,875
-- Assumes excellent condition.				

©2013 Kelley Blue Book® Co., Inc. All rights reserved. 07/04/2013 - 07/11/2013 Edition for California 92501. The specific information required to determine the value for this particular vehicle was supplied by the person generating this report. Vehicle valuations are opinions and may vary from vehicle to vehicle. Actual valuations will vary based upon market conditions, specifications, vehicle condition or other particular circumstances pertinent to this particular vehicle or the transaction or the parties to the transaction. This report is intended for the individual use of the person generating this report only and shall not be sold or transmitted to another party. Kelley Blue Book® assumes no responsibility for errors or omissions. (v.13071)



Used Vehicle Valuation Report

Report Date: 07/09/2013

Effective Dates: 07/04/2013 - 07/11/2013

2013 Kia Forte LX Sedan 4D

VIN: KNAFT4A29D5719777

Reference:

Notes:

©2013 Kelley Blue Book® Co., Inc. All rights reserved. 07/04/2013 - 07/11/2013 Edition for California 92501. The specific information required to determine the value for this particular vehicle was supplied by the person generating this report. Vehicle valuations are opinions and may vary from vehicle to vehicle. Actual valuations will vary based upon market conditions, specifications, vehicle condition or other particular circumstances pertinent to this particular vehicle or the transaction or the parties to the transaction. This report is intended for the individual use of the person generating this report only and shall not be sold or transmitted to another party. Kelley Blue Book® assumes no responsibility for errors or omissions. (v.13071)

CCC valuescope Basic Claim Information Form



CCC VALUESCOPE.

Report Retrieval Method	<input type="checkbox"/> Email	<input type="checkbox"/> Fax	<input type="checkbox"/> Other (Specify)
CCC Phone: 1-800-621-8070		CCC Fax: 1-800-621-7070	
CCC Email: CCCValuescopeRequest@cccis.com			
Office ID Number		Claim Number CO13010711	
Adjr Name (First & Last) JOSH TURNER		Appr Name (First & Last) TONY NGUYEN	
Adjr Contact# 714-738-1383		Insured's Name ROSEMARY GUTIERREZ	
Owner's Name SAME		Owner's Phone 951-220-4148	
Loss ZIP Code 92551		Loss State CA	
Loss Type <input checked="" type="checkbox"/> Collision <input type="checkbox"/> Theft		Coverage code <input type="checkbox"/> Collision <input type="checkbox"/> Comprehensive <input type="checkbox"/> Liability <input type="checkbox"/> Other	
3rd Party Claim <input type="checkbox"/> Yes <input type="checkbox"/> No		Leased Vehicle <input type="checkbox"/> Yes <input type="checkbox"/> No	
Date of Loss 6-26-13		Exch#Policy #	
Adjuster ID#		Claim Class	
PA Appr ID#			
VIN KNAFT4A29D5719777			
Year 2013	Make KIA	Model FORTE LX	
Body Style	<input type="checkbox"/> 2DR <input checked="" type="checkbox"/> 4DR	<input type="checkbox"/> Hatchback	<input type="checkbox"/> Convertible
<input type="checkbox"/> 1/2 Ton	<input type="checkbox"/> 3/4 Ton	<input type="checkbox"/> 1 Ton	<input type="checkbox"/> Short Bed
<input type="checkbox"/> Long Bed	<input type="checkbox"/> Cab & Chassis	<input type="checkbox"/> Fleetside	<input type="checkbox"/> Fenderside
Engine Size 2.0L	Cylinders	<input type="checkbox"/> 3 <input checked="" type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6 <input type="checkbox"/> 8 <input type="checkbox"/> 10 <input type="checkbox"/> 12	<input type="checkbox"/> Turbo <input type="checkbox"/> Diesel
Mileage ("UNK" if unknown) 9271			
Transmission	<input type="checkbox"/> Automatic	<input checked="" type="checkbox"/> S6	<input type="checkbox"/> S5 <input type="checkbox"/> S4 <input type="checkbox"/> S3 <input type="checkbox"/> OD <input type="checkbox"/> 4W <input type="checkbox"/> PO
Power Options		Seating	
<input checked="" type="checkbox"/> PS Power Steering		<input checked="" type="checkbox"/> CS Cloth Seats	
<input checked="" type="checkbox"/> PB Power Brakes		<input type="checkbox"/> LS Leather Seats	
<input type="checkbox"/> PW Power Windows		<input checked="" type="checkbox"/> RL Reclining/ Lounge Seats	
<input type="checkbox"/> PL Power Locks		<input checked="" type="checkbox"/> BS Bucket Seats	
<input type="checkbox"/> SP Power Driver Seat		<input type="checkbox"/> SH Heated Seats (2)	
<input type="checkbox"/> PC Power Passenger Seat		<input type="checkbox"/> RH Rear Heated Seats	
<input type="checkbox"/> PA Power Antenna		<input type="checkbox"/> 3S Third Row Seat	
<input type="checkbox"/> PM Power Mirrors		<input type="checkbox"/> 3P Power Third Seat	
<input checked="" type="checkbox"/> PT Power Trunk/Tailgate		<input type="checkbox"/> R3 Retractable Seats	
<input type="checkbox"/> PP Power Adjustable Petals		<input type="checkbox"/> 2P 12 Passenger Seating	
<input type="checkbox"/> PD Power Sliding Door		<input type="checkbox"/> 5P 15 Passenger Seating	
<input type="checkbox"/> DP Dual Power Sliding Doors		<input type="checkbox"/> B2 Captain Chairs (2)	
Décor/Convenience		<input type="checkbox"/> B4 Captain Chairs (4)	
<input checked="" type="checkbox"/> AC Air Conditioning		<input type="checkbox"/> B6 Captain Chairs (6)	
<input type="checkbox"/> DA Dual Air Conditioning		Radio	
<input type="checkbox"/> CL Climate Control		<input checked="" type="checkbox"/> AM AM Radio	
<input checked="" type="checkbox"/> RD Rear Defogger		<input checked="" type="checkbox"/> FM FM Radio	
<input checked="" type="checkbox"/> IW Intermittent Wipers		<input checked="" type="checkbox"/> ST Stereo	
<input checked="" type="checkbox"/> TW Tilt Wheel		<input type="checkbox"/> CA Cassette	
<input checked="" type="checkbox"/> TL Telescopic Wheel		<input checked="" type="checkbox"/> SE Search/Seek	
<input type="checkbox"/> CC Cruise Control		<input checked="" type="checkbox"/> CD Compact Disc Player	
<input type="checkbox"/> KE Keyless Entry		<input type="checkbox"/> SK CD Changer/Stacker	
<input checked="" type="checkbox"/> CN Console/Storage		<input type="checkbox"/> UR Premium Radio	
<input type="checkbox"/> CO Overhead Console		<input type="checkbox"/> XM Satellite Radio	
<input type="checkbox"/> EC Entertainment Center		<input type="checkbox"/> TQ Steering Wheel Touch	
<input type="checkbox"/> NV Navigation System		Controls	
<input type="checkbox"/> C2 Communications System		<input type="checkbox"/> M3 Auxiliary Audio Connection	
<input type="checkbox"/> HU Heads Up Display		<input type="checkbox"/> EQ Equalizer	
<input type="checkbox"/> WT Wood Interior Trim		<input type="checkbox"/> CB CB Radio	
<input type="checkbox"/> EI Electronic Instrumentation		<input type="checkbox"/> 8T 8 Track Tape Player	
<input type="checkbox"/> IB On Board Computer		Wheels	
<input type="checkbox"/> MC Message Center		<input type="checkbox"/> AW Aluminum/Alloy Wheels	
<input type="checkbox"/> MM Memory Package		<input type="checkbox"/> CJ Chrome Wheels	
<input type="checkbox"/> RJ Remote Start		<input type="checkbox"/> W2 20" or Larger Wheels	
		<input type="checkbox"/> DC Deluxe Wheel Covers	
		<input checked="" type="checkbox"/> FC Full Wheel Covers	
		<input type="checkbox"/> SA Spoke Aluminum Wheels	
		<input type="checkbox"/> SY Styled Steel Wheels	
		<input type="checkbox"/> WW Wire Wheels	
		<input type="checkbox"/> WC Wire Wheel Covers	
		<input type="checkbox"/> RW Rally Wheels	
		<input type="checkbox"/> KW Locking Wheels	
		<input type="checkbox"/> LC Locking Wheel Covers	
		Roof	
		<input type="checkbox"/> EG Electric Glass Roof	
		<input type="checkbox"/> ES Electric Steel Roof	
		<input type="checkbox"/> OR Skyview Roof	
		<input type="checkbox"/> SD Dual Power Roofs	
		<input type="checkbox"/> MS Manual Steel Roof	
		<input type="checkbox"/> MG Manual Glass Roof	
		<input type="checkbox"/> FR Flip Roof	
		<input type="checkbox"/> TT T-Top/Panel	
		<input type="checkbox"/> GT Glass T-Top/Panel	
		<input type="checkbox"/> MV Manual Convertible Roof	
		<input type="checkbox"/> VP Power Convertible Roof	
		<input type="checkbox"/> RM Detachable Roof	
		<input type="checkbox"/> VR Vinyl Roof	
		<input type="checkbox"/> RF Cabriolet Roof	
		<input type="checkbox"/> LR Landau Roof	
		<input type="checkbox"/> LP Padded Landau Roof	
		<input type="checkbox"/> PV Padded Vinyl Roof	
		<input type="checkbox"/> CT Soft Top	
		<input type="checkbox"/> HT Hard Top	
		Safety/Brakes	
		<input checked="" type="checkbox"/> AG Air Bag	
		<input checked="" type="checkbox"/> RG Passenger Air Bag	
		<input checked="" type="checkbox"/> XG Front Side Impact Air Bags	
		<input type="checkbox"/> ZG Rear Side Impact Air Bags	
		<input checked="" type="checkbox"/> DG Head/Roof Air Bags	
		<input type="checkbox"/> TD Theft Deterrent/Alarm	
		<input type="checkbox"/> VZ Night Vision	
		<input type="checkbox"/> IC Intelligent Cruise	
		<input type="checkbox"/> PJ Parking Sensors	
		<input type="checkbox"/> PX Parking Sensors W/Equip	
		<input checked="" type="checkbox"/> AB Anti-Lock Brakes (4)	
		<input type="checkbox"/> A2 Anti-Lock Brakes (2)	
		<input checked="" type="checkbox"/> DB 4-Wheel Disc Brakes	
		<input type="checkbox"/> RB Rollover Protection	
		<input checked="" type="checkbox"/> TX Traction Control	
		<input checked="" type="checkbox"/> T1 Stability Control	
		<input type="checkbox"/> AL Auto Level	
		Exterior/Paint/Glass	
		<input type="checkbox"/> RR Luggage/Roof Rack	
		<input type="checkbox"/> WG Woodgrain	
		<input type="checkbox"/> WP Rear Window Wiper	
		<input type="checkbox"/> 2T Two Tone Paint	
		<input type="checkbox"/> D2 Deluxe 2 Tone Paint	
		<input type="checkbox"/> HP Three Stage Paint	
		<input checked="" type="checkbox"/> IP Clearcoat Paint	
		<input type="checkbox"/> MP Metallic Paint	
		<input type="checkbox"/> SL Rear Spoiler	
		<input type="checkbox"/> FL Fog Lamps	
		<input checked="" type="checkbox"/> TG Tinted Glass	
		<input type="checkbox"/> DT Privacy Glass	
		<input type="checkbox"/> BN Body Side Moldings	
		<input checked="" type="checkbox"/> DM Dual Mirrors	
		<input type="checkbox"/> HM Heated Mirrors	
		<input type="checkbox"/> HV Headlamp Washers	
		<input type="checkbox"/> MX Signal Integrated Mirrors	
		Other	
		<input type="checkbox"/> BD Running Board/Side Steps	
		<input type="checkbox"/> UP Power Retractable Running Boards	
		<input type="checkbox"/> XE Xenon Headlamps	
		<input type="checkbox"/> AR Bed Rails	
		<input type="checkbox"/> BL Bedliner	
		<input type="checkbox"/> BY Bedliner (Spray On)	
		<input type="checkbox"/> CP Fiberglass Cap	
		<input type="checkbox"/> GG Grill Guard	
		<input type="checkbox"/> SB Rear Step Bumper	
		<input type="checkbox"/> SS Swivel Seats	
		<input type="checkbox"/> SW Rear Sliding Window	
		<input type="checkbox"/> PG Power Rear Window	
		<input type="checkbox"/> TB Tool Box (Permanent)	
		<input type="checkbox"/> TN Tonneau Cover – Soft	
		<input type="checkbox"/> TZ Tonneau Cover – Hard	
		<input type="checkbox"/> TP Trailing Package	
		<input type="checkbox"/> WD Dual Rear Wheels	
		<input type="checkbox"/> XT Auxiliary Fuel Tank	
		<input type="checkbox"/> 3D 3rd Truck Door	
		<input type="checkbox"/> 4D 4th Door Truck/Van	
		<input type="checkbox"/> BC Bumper Cushions	
		<input type="checkbox"/> BG Bumper Guards	
		<input type="checkbox"/> EM California Emissions	
		<input type="checkbox"/> SG Stone Guard	
		<input type="checkbox"/> WI Winch	

CCC Valuescope Basic Claim Information Form (Continued)

Office ID Number				Claim Number			
REFURBISHMENTS							
Transmission	Purchase Price		Mileage		Engine	Purchase Price	
Tires	Purchase Price		# of Tires				
Paint	<input type="checkbox"/> Basic	<input type="checkbox"/> Standard	<input type="checkbox"/> Custom	Date Painted	Purchase Price		
Interior	Purchase Price		Date		<input type="checkbox"/> Leather	<input type="checkbox"/> Vinyl	<input type="checkbox"/> Cloth
Camper Shell	Purchase Price		Date		Carpet Kit	Purchase Price	Date
Special Wheels	Purchase Price		Date				
Other	Description				Purchase Price		Date
<input type="checkbox"/> Restored	Restored Amount						
Package/Special Features/Additional Options (XXXX=CALL BACK)							
CONDITION RATING: Rate each of the following 0=Below Average, 1=Normal, 2=Above Average, 3=Exceptional						COMMENTS	
Seats	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Clean. No significant fading. No tears, holes or burn marks		
Carpet	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Clean. No tears, holes or burn marks		
Dashboard	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	No damage. Components intact.		
Headliner	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Clean. No tears, sagging or fading		
Body	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Sheetmetal: No dents. No significant dings. No rust evident. Trim: No damage to components. No significant peeling or fading. No rust apparent		
Glass	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	No scratches, pitting or chips. Seals are intact and watertight.		
Paint	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	No surface chips. No significant scratches or fading.		
Engine	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Very clean. No seepage evident. No dirt or grease covered areas. Oil translucent.		
Transmission	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Fluid has red translucent color. No seepage evident.		
Front Tires	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	8-10/32" of original tread. 69% to 90% of new. Normal wear patterns evident.		
Rear Tires	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	8-10/32" of original tread. 69% to 90% of new. Normal wear patterns evident.		
ADJUSTMENTS							
Pre Tax Adjustment 1					Add	Deduct	
Pre Tax Adjustment 2					Add	Deduct	
Sales Tax %	Leave blank if using AutoTax				Deductible		
Post Tax Adjustment 1					Add	Deduct	
Post Tax Adjustment 2					Add	Deduct	

Date: 7/9/2013 08:14 AM
Estimate ID: CO13010711
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: TONY NGUYEN

Appraised For: JOSH TURNER
(714) 738-1383 ext. 2205

ROBERT MORENO INS
(714) 738-1383

Condition Code: Good
Date of Loss: 6/26/2013
Deductible: 500.00
File Number: CO13010711
Claim Number: CO13010711

Type of Loss: Property Damage

Insured: ROSEMARY GUTIERREZ
Owner: ROSEMARY GUTIERREZ
Address: 15172 MARTE CIRCLE, MORENO VALLEY, CA 92551
Telephone: Home Phone: (951) 220-4148

Mitchell Service: 911226

Description: 2013 Kia Forte LX
Body Style: 4D Sed
VIN: KNAFT4A29D5719777
Mileage: 9,271
OEM/ALT: A
Color: BLACK
Options: PASSENGER AIRBAG, DRIVER AIRBAG, REAR WINDOW DEFOGGER, MANUAL AIR CONDITION
TILT STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, AUXILIARY INPUT
SATELLITE RADIO, FRONT AIR DAM, TINTED GLASS, VARIABLE ASSISTED STEERING
SIDE AIRBAGS, AUTOMATIC HEADLIGHTS, SIDE HEAD CURTAIN AIRBAGS
AM/FM STEREO CD/MP3 PLAYER, ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS
POWER DISC BRAKES, POWER LIFTGATE/TRUNK, STEERING WHEEL AUDIO CONTROLS

Vehicle Production Date: 11/12
Drive Train: 2.0L Inj 4 Cyl 6A FWD
License: 6YZL437 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	AUTO	BDY	OVERHAUL	Frnt Bumper Assy			1.3 #
2	100328	BDY	REMOVE/REPLACE	Frnt Bumper Cover	86511 1M000	213.57	INC #
3	AUTO	REF	REFINISH	Frnt Bumper Cover			C 2.4
4	100336	BDY	REMOVE/REPLACE	L Frnt Bumper Opening Cover	ORDER FROM DEALER	20.13	INC #
5	AUTO	BDY	REMOVE/INSTALL	Frnt Bumper Cover			INC #
6	100337	BDY	REMOVE/REPLACE	Frnt Bumper Impact Absorber	86520 1M000	70.42	INC
7	100338	BDY	REMOVE/REPLACE	R Frnt Up'r Bumper Bracket	86518 1M000	18.43	0.2 #
8	100339	BDY	REMOVE/REPLACE	L Frnt Up'r Bumper Bracket	86517 1M000	18.96	0.2 #
9	100340	BDY	REMOVE/REPLACE	Frnt Bumper Reinforcement Bar	86530 1M000	164.47	INC #

ESTIMATE RECALL NUMBER: 07/09/2013 08:14:54 CO13010711

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Software Version: 7.0.486

All Rights Reserved

Page 1 of 5

Date: 7/9/2013 08:14 AM
 Estimate ID: CO13010711
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

10	101634	BDY	REMOVE/REPLACE	Grille	86350 1M600	125.44	INC
11	102131	BDY	REMOVE/REPLACE	R Front Combination Lamp Assembly	92102 1M230	244.90	INC
12	AUTO	BDY	CHECK/ADJUST	Headlamps			0.4
13	102132	BDY	REMOVE/REPLACE	L Front Combination Lamp Assembly	92101 1M230	244.90	INC
14	100014	BDY	REMOVE/REPLACE	Hood Panel	66400 1M010	390.67	0.7
15	AUTO	REF	REFINISH	Hood Outside			C 2.6
16	AUTO	REF	REFINISH	Add For Hood Underside			C 1.3
17	100015	BDY	REMOVE/REPLACE	R Hood Hinge	79120 1M000	24.26	0.2 #
18	AUTO	REF	REFINISH	R Hinge			C 0.5
19	AUTO	BDY	REMOVE/INSTALL	Hood Assy			INC
20	100016	BDY	REMOVE/REPLACE	L Hood Hinge	79110 1M000	21.93	0.2 #
21	AUTO	REF	REFINISH	L Hinge			C 0.5
22	101910	BDY	REMOVE/REPLACE	Cooling Radiator	25310 1M320	362.82	INC #
23	100472	BDY	REMOVE/REPLACE	L Cooling Air Deflector	29135 1M000	8.20	
24	101882	BDY	REMOVE/REPLACE	Cooling Fan/Motor & Shroud Assy	25380 1M050	229.72	INC
25	101919	MCH	REMOVE/REPLACE	Air Cond Condenser -M	97606 1M102	375.10	INC #
26	AUTO	MCH	REMOVE/REPLACE	Evacuate & Recharge A/C -M			1.4
27	101646	MCH	REMOVE/REPLACE	Air Cond Compressor Tube -M	97775 1M101	314.07	1.6
28	100395	MCH	REMOVE/REPLACE	Air Cond Discharge Hose -M	97762 1M100	61.90	0.7
29	100526	BDY	REMOVE/REPLACE	R Fender Panel	66321 1M040	193.00	1.1 #
30	AUTO	REF	REFINISH	R Fender Outside			C 1.6
31	AUTO	REF	REFINISH	R Add To Edge Fender			C 0.5
32	100527	BDY	REMOVE/REPLACE	L Fender Panel	66311 1M040	185.00	1.1 #
33	AUTO	REF	REFINISH	L Fender Outside			C 1.6
34	AUTO	REF	REFINISH	L Add To Edge Fender			C 0.5
35	100530	BDY	REMOVE/REPLACE	R Fender Liner	86812 1M000	37.52	0.3
36	100531	BDY	REMOVE/REPLACE	L Fender Liner	86811 1M000	37.52	0.3
37	100537	BDY	REMOVE/REPLACE	Front Body Radiator Support (Com)	64101 1M000	272.82	4.5 #
38	AUTO	MCH	REMOVE/REPLACE	Add To R&R Mechanical Components -M			0.6 #
39	AUTO	REF	REFINISH	L Apron/Sidemember Complete			1.5
40	100539	BDY	REMOVE/REPLACE	L Front Body Apron Panel -S	64501 1M010	232.28	8.0 #
41	100540	BDY	REMOVE/REPLACE	R Front Body Sidemember -S	64602 1M010	435.69	9.5 #
42	AUTO	REF	REFINISH	R Sidemember			1.0
43	100541	BDY	REMOVE/REPLACE	L Front Body Sidemember -S	64601 1M010	435.62	9.0 #
44	100542	MCH	REMOVE/INSTALL	Sub-Frame Assy -M	Existing		5.7 r
45	100383	MCH	REMOVE/REPLACE	Air Bag Control Module -M	95910 1M100	514.23	0.5 #
46	AUTO	BDY	REMOVE/INSTALL	Console			0.5
47	102117	MCH	REMOVE/REPLACE	Air Bag Module/Seat Back Driver -M	88300 1M910AF1	497.00	0.6 #
48	AUTO	BDY	REMOVE/INSTALL	L Seat Assy			0.3
49	100421	MCH	REMOVE/REPLACE	L Air Bag Side Curtain Module -M	85020 1M000	941.19	INC #
50	AUTO	BDY	REMOVE/INSTALL	Roof Headliner			INC #
51	100423	MCH	REMOVE/REPLACE	L Frt Air Bag Side Impact Sensor -M	95920 1M200	201.23	0.4 #
52	100784	MCH	REMOVE/INSTALL	Engine & Trans Assy -M			8.7
53	AUTO	REF	REFINISH	L Door Opening Panel Complete			C 3.6
54	100973	BDY	REPAIR	L Ctr Pillar Panel -S	Existing		0.5*#
55	100975	BDY	REPAIR	L Rocker Outer Panel -S	Existing		0.5*#
56	101330	BDY	REMOVE/REPLACE	L Frt Seat Belt	88810 1M500WK	262.80	0.9 #
57	101178	REF	BLEND	L Frt Door Outside			C 0.9
58	101338	BDY	REPAIR	R Frt Door Repair Panel	Existing		0.5*#
59	AUTO	REF	REFINISH	R Frt Door Outside			C 1.7
60	100837	BDY	REMOVE/INSTALL	R Frt Otr Belt Moulding			0.5 #
61	100838	BDY	REMOVE/INSTALL	L Frt Otr Belt Moulding			0.5 #
62	100841	BDY	REMOVE/INSTALL	R Frt Rear View Mirror			INC
63	100842	BDY	REMOVE/INSTALL	L Frt Rear View Mirror			INC
64	100847	BDY	REMOVE/INSTALL	R Frt Door Trim Panel			INC
65	100848	BDY	REMOVE/INSTALL	L Frt Door Trim Panel			INC

ESTIMATE RECALL NUMBER: 07/09/2013 08:14:54 CO13010711

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Page 2 of 5

Software Version:

7.0.486

All Rights Reserved

Date: 7/9/2013 08:14 AM
 Estimate ID: CO13010711
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

66	100856	BDY	REMOVE/INSTALL	R Frt Otr Door Handle				INC #
67	100857	BDY	REMOVE/INSTALL	L Frt Otr Door Handle				INC #
68	102099	BDY	REMOVE/INSTALL	R Frt Door Carrier Module				1.6 #
69	102092	BDY	REMOVE/INSTALL	L Frt Door Carrier Module				1.6 #
70	101572	BDY	REMOVE/REPLACE	L Rear Door Repair Panel	77111 1M010	180.91	6.9 #	
71	AUTO	REF	REFINISH	L Rear Door Outside			C 1.7	
72	AUTO	REF	REFINISH	L Rear Add For Jambs			C 0.5	
73	101864	BDY	REMOVE/REPLACE	Roof Headliner	ORDER FROM DEALER	379.91	3.3 #	
74	101182	BDY *	REMOVE/INSTALL	Back Window			0.3 #	
75	100756	BDY *	REMOVE/REPLACE	Back Window Adhesive	** QUAL REPL PART	25.00 *		
76	100758	BDY	REMOVE/REPLACE	Back Window Moulding	87130 1M000	44.00		
77	931105	MCH	ADD'L LABOR OP	FOUR WHEEL ALIGNMENT	Sublet	79.99 *	0.0*	
78	100790	BDY	REMOVE/REPLACE	L Quarter Outer Panel Assy	70100 1MA10	922.88	20.5 #	
79	AUTO	MCH	REMOVE/REPLACE	L Add To R&I/R&R Side Curtain Air Bags-M			0.8 #	
80	AUTO	REF	REFINISH	L Quarter Panel Outside			C 1.8	
81	AUTO	REF	REFINISH	L Add For Pillar			C 0.5	
82	AUTO	REF	REFINISH	L Quarter Panel Edge			C 0.5	
83	100266	BDY	REMOVE/REPLACE	L Quarter Fuel Door	69510 1M000	40.45	INC	
84	AUTO	REF	REFINISH	L Fuel Door			INC #	
85	AUTO	REF	REFINISH	L Add For Inside Fuel Door			C 0.2	
86	100880	BDY	REMOVE/REPLACE	L Quarter Liner	86821 1M000	23.65	0.3	
87	100886	BDY	REPAIR	Quarter Package Tray Panel	Existing		0.5*	
88		REF	REFINISH/REPAIR	Quarter Package Tray Panel			1.0*	
89	100005	REF	BLEND	Luggage Lid Outside			C 0.9	
90	100902	BDY	REMOVE/INSTALL	Luggage Lid Garnish			0.5 #	
91	101084	BDY	REMOVE/REPLACE	Luggage Lid Adhesive Emblem	86318 2G000	44.43	0.2	
92	101087	BDY	REMOVE/REPLACE	Luggage Lid Adhesive Nameplate	86310 1M000	19.98	0.2	
93	100701	BDY	REMOVE/INSTALL	R Rear Combination Lamp			0.3	
94	100702	BDY	REMOVE/INSTALL	L Rear Combination Lamp			0.3	
95	936012		ADD'L COST	Hazardous Waste Disposal		5.00 *		
96	936014		ADD'L COST	Flex Additive		6.00 *		
97	936016		ADD'L COST	Weld Thru Primer		15.00 *		
98	933006	FRM	ADD'L OPR	Frame/Rack Set Up			2.0*	
99	933035	FRM	ADD'L OPR	Unibody Pull			4.0*	
100	933021	BDY *	ADD'L OPR	De-Nib And Finesse			3.0*	
101	933002	REF	ADD'L OPR	Clear Coat			2.5*	
102	933003	BDY *	ADD'L OPR	Tint Color			0.5*	
103	933005	BDY	ADD'L OPR	Restore Corrosion Protection		10.00 *	0.3*	
104	933018	BDY *	ADD'L OPR	Mask For Overspray		5.00 *	0.2*	
105	AUTO		ADD'L COST	Paint/Materials		1,013.20 *		

* - Judgment Item

- Labor Note Applies

C - Included in Clear Coat Calc

r - CEG R&R Time Used For This Labor Operation

ESTIMATE RECALL NUMBER: 07/09/2013 08:14:54 CO13010711

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Software Version: 7.0.486

All Rights Reserved

Page 3 of 5

Estimate Totals

		Units	Rate	Add'l Labor Amount	Sublet Amount	Totals			Amount
I.	Labor Subtotals						II.	Part Replacement Summary	
	Body	81.7	46.00	15.00	0.00	3,773.20		Taxable Parts	8,837.00
	Refinish	29.8	46.00	0.00	0.00	1,370.80		Sales Tax @ 8.000%	706.96
	Frame	6.0	60.00	0.00	0.00	360.00		Total Replacement Parts Amount	9,543.96
	Mechanical	21.0	75.00	0.00	79.99	1,654.99			
	Non-Taxable Labor					7,158.99			
	Labor Summary	138.5				7,158.99			
III.	Additional Costs					Amount	IV.	Adjustments	Amount
	Taxable Costs					1,034.20		Insurance Deductible	500.00-
	Sales Tax @ 8.000%					82.74		Customer Responsibility	500.00-
	Non-Taxable Costs					5.00			
	Total Additional Costs					1,121.94			
	Paint Material Method: Rates								
	Init Rate = 34.00 , Init Max Hours = 99.9, Addl Rate = 0.00								
							I.	Total Labor:	7,158.99
							II.	Total Replacement Parts:	9,543.96
							III.	Total Additional Costs:	1,121.94
								Gross Total:	17,824.89
							IV.	Total Adjustments:	500.00-
								Net Total:	17,324.89
								TOTAL LOSS	

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

15 Total Loss (P), 8 Left Rear Side (S), 10 Left Front Side (S), 11 Left Front Corner (S), 12 Front Center (S)

Body Shop: COLLISION EXPERTS OF RIVERSIDE
Address: 2376 MAIN ST
RIVERSIDE , CA 92501
Telephone: (951) 683-4458
Fax Phone: : (951) 683-4486
State Lic. No: 80-0509190

ESTIMATE RECALL NUMBER: 07/09/2013 08:14:54 CO13010711

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Software Version: 7.0.486

All Rights Reserved

Page 4 of 5

Date: 7/9/2013 08:14 AM
Estimate ID: CO13010711
Estimate Version: 0
Preliminary
Profile ID: * PDS

Inspection Site: COLLISION EXPERTS OF RIVERSIDE
Address: 2376 MAIN ST
RIVERSIDE , CA 92501
(951) 683-4458
Inspection Date: 7/8/2013

COLLECT ALL FROM OWNER
***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!!!***

***COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS *NOT* AN ACCEPTANCE OF
COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE
DETERMINED BY ROBERT MORENO INSURANCE COMPANY.
THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY ROBERT
MORENO INSURANCE COMPANY.

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 07/09/2013 08:14:54 CO13010711

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 5 of 5













