

 **View Claim Summary - File Number: 06252013-1000026**

GO BACK

Claim Summary been saved successfully...



Property Damage Specialist
P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : CO13010600
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Preston Hobbs
Date of Loss : -0001-11-30
Whose Claim : Insured
Owner Name : DANIELLE DON
Insured Name : DANIELLE DON
Claimant Name :
Inspection Location : RESIDENCE

Appraisal Information

File Number : 06252013-1000026
Appraiser : Tony Nguyen
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-03
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) :
Possible Supplement :

Vehicle Information

Year : 2011
Make : Toyota
Model : Camry
Sub-model : HYBRID
VIN : 4T1BB3EK8BU137564
Plate : 6UGZ615

State : California
Milage : 27154
Drivable : Yes
Primary POI : RT FRT
Secondary POI :
Vehicle Condition : Good
Interior Condition :
Paint Condition :
Engine :

Repair Information

Recommendation : Repairable
Estimate 1 Total : 0.00
Estimate 2 Total : 0.00
Estimate 1 Betterment : 0.00
Estimate 2 Betterment : 0.00
Supplement 1 Total : 0.00
Supplement 1 Betterment : 0.00
Supplement 2 Total : 0.00
Supplement 2 Betterment : 0.00
Supplement 3 Total : 0.00
Supplement 3 Betterment : 0.00
Supplement 4 Total : 0.00
Supplement 4 Betterment : 0.00
Subtotal : 0.00
Deductible : 0.00
Original Net Loss : 0.00
Gross Total : 0
Supplement Net Loss : 0.00

Tire Information

Make :
Size :
Tired Depth (in 32nds)
L/F R/F
L/R R/R
Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

COMPLETED INSPECTION OF INSURED VEHICLE AT RESIDENCE IN LAKE ELSINORE ON 7-3-13. INSURED WAS PRESENT AND POINTED OUT IMPACT TO RIGHT FRONT TIRE OF VEHICLE. NO DAMAGES SEEN AS PHOTOS SHOW. PLEASE CALL TONY NGUYEN W/ANY QUESTIONS.

Date: 7/5/2013 12:46 PM
Estimate ID: CO13010600
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: TONY NGUYEN

Appraised For: PRESTON HOBBS
(714) 738-1383 ext. 2330

ROBERT MORENO INS
(714) 738-1383

Condition Code: Good
Date of Loss: 6/20/2013
Deductible: 500.00
File Number: CO13010600
Claim Number: CO13010600

Type of Loss: Property Damage

Insured: DANIELLE DON
Owner: DANIELLE DON
Address: 29148 OUTRIGGER ST, LAKE ELSINORE, CA 92530
Telephone: Home Phone: (619) 964-1208

Mitchell Service: 910207

Description: 2011 Toyota Camry Hybrid
Body Style: 4D Sed
VIN: 4T1BB3EK8BU137564
Mileage: 27,154
OEM/ALT: A
Color: RED
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW
REAR WINDOW DEFOGGER, CRUISE CONTROL, TILT STEERING COLUMN
TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS
AUXILIARY INPUT, POWER ADJUSTABLE EXTERIOR MIRROR, FRONT AIR DAM, TINTED GLASS
AUTO AIR CONDITION, TRIP COMPUTER, UNIVERSAL GARAGE DOOR OPENER
VARIABLE ASSISTED STEERING, SIDE AIRBAGS, ANTI-THEFT SYSTEM
AUTOMATIC HEADLIGHTS, FRONT SIDE AIRBAG WITH HEAD PROTECTION
INTERIOR AUTOMATIC DAY/NIGHT OR ELECTROCHROMATIC MIRROR
SIDE HEAD CURTAIN AIRBAGS, DAYTIME RUNNING LIGHTS, AM/FM STEREO CD/MP3 PLAYER
ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS
FRONT SEATS WITH POWER LUMBAR SUPPORT, INTERIOR AIR FILTER, KEYLESS ENTRY SYSTEM
POWER DISC BRAKES, POWER LIFTGATE/TRUNK, STEERING WHEEL AUDIO CONTROLS

Vehicle Production Date: 7/10
Drive Train: 2.4L Inj 4 Cyl A FWD
License: 6UGZ615 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	900500	BDY *	ADD'L LABOR OP	NO DAMAGE	Existing		0.0*

ESTIMATE RECALL NUMBER: 07/05/2013 12:46:49 CO13010600

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

* - Judgment Item

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Labor Summary	0.0				0.00	Total Replacement Parts Amount	0.00
III. Additional Costs					Amount	IV. Adjustments	Amount
Total Additional Costs					0.00	Insurance Deductible	500.00-
						Subtotal of Adjustments Exceeds Gross Total	
						Customer Responsibility	0.00
						I. Total Labor:	0.00
						II. Total Replacement Parts:	0.00
						III. Total Additional Costs:	0.00
						Gross Total:	0.00
						IV. Total Adjustments:	0.00
						Net Total:	0.00

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

2 Right Front Side (P)

Inspection Site: RESIDENCE
Address: 29148 OUTRIGGER SR
LAKE ELSINORE, CA 92530
Inspection Date: 7/3/2013

COLLECT ALL FROM OWNER
***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!!!***

ESTIMATE RECALL NUMBER: 07/05/2013 12:46:49 CO13010600

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 2 of 3

Date: 7/5/2013 12:46 PM
Estimate ID: CO13010600
Estimate Version: 0
Preliminary
Profile ID: * PDS

***COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS *NOT* AN ACCEPTANCE OF
COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE
DETERMINED BY ROBERT MORENO INSURANCE COMPANY.

THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY ROBERT
MORENO INSURANCE COMPANY.

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 07/05/2013 12:46:49 CO13010600

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3





