

**View Claim Summary - File Number: 07022013-100008**[GO BACK](#)**Claim Summary been saved successfully...****Property Damage Specialist**P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : CO13010901
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Lorena Bautista
Date of Loss : 2013-06-29
Whose Claim : Insured
Owner Name : RAMON MEZA VERA
Insured Name : RAMON MEZA VERA
Claimant Name :
Inspection Location : RESIDENCE

Appraisal Information

File Number : 07022013-100008
Appraiser : Rich Perea
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-03
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) : 4
Possible Supplement :

Vehicle Information

Year : 2004
Make : GMC
Model : 1500
Sub-model : EXT
VIN : 1GTEC19V14Z338333
Plate :

State :
Milage :
Drivable : Unknown
Primary POI :
Secondary POI :
Vehicle Condition :
Interior Condition :
Paint Condition :
Engine :

Repair Information

| | |
|---------------------------|------------|
| Recommendation : | Repairable |
| Estimate 1 Total : | 1849.26 |
| Estimate 2 Total : | 0.00 |
| Estimate 1 Betterment : | 0.00 |
| Estimate 2 Betterment : | 0.00 |
| Supplement 1 Total : | 0.00 |
| Supplement 1 Betterment : | 0.00 |
| Supplement 2 Total : | 0.00 |
| Supplement 2 Betterment : | 0.00 |
| Supplement 3 Total : | 0.00 |
| Supplement 3 Betterment : | 0.00 |
| Supplement 4 Total : | 0.00 |
| Supplement 4 Betterment : | 0.00 |
| Subtotal : | 1849.26 |
| Deductible : | 500.00 |
| Original Net Loss : | 1349.26 |
| Gross Total : | 1849.26 |
| Supplement Net Loss : | 0.00 |

Tire Information

Make :
Size :
Tired Depth (in 32nds)
L/F R/F
L/R R/R
Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

COMPLETED INSPECTION & ESTIMATE OF INSURED VEHICLE AT RESIDENCE IN COACHELLA ON 7/3/13. INSURED WAS PRESENT & POINTED OUT RT SIDE IMPACT DAMAGE. SHE DIDN'T HAVE A CHOICE OF SHOP AT TIME OF INSPECTION. ESTIMATE WRITTEN AT AREAS PREVAILING RATES USING AN AVAILABLE LKQ DOOR ASSY AT A COST EFFECTIVE SAVINGS OVER THE NEW OEM PARTS. APPROXIMATE REPAIR TIME IS 4 DAYS. PLEASE CALL IF YOU HAVE ANY QUESTIONS 760-275-6795.

Date: 7/7/2013 03:35 PM
Estimate ID: CO13010901
Estimate Version: 0
Preliminary
Profile ID: * RMIS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795 OR EMAIL
pds9593@verizon.net

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: pds9593@verizon.net

Damage Assessed By: RICH PEREA

Appraised For: LORENA BAUTISTA

Condition Code: Good
Date of Loss: 6/29/2013
Contact Date: 7/3/2013
Deductible: 500.00
File Number: CO13010901
Claim Number: CO13010901

Type of Loss: Collision

Insured: RAMON MEZA VERA
Owner: RAMON MEZA VERA
Address: 85101 DAMASCUS AVE, COACHELLA, CA 92236
Telephone: Home Phone: (760) 391-5067

Mitchell Service: 915495

Description: 2004 GMC Pickup Sierra C1500
Body Style: 4D PkUpXCb 6' Bed 143" WB
VIN: 1GTEC19V14Z338333
Mileage: 145,978
OEM/ALT: O
Color: RED
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER STEERING, MANUAL AIR CONDITION
CRUISE CONTROL, TILT STEERING COLUMN, ANTI-LOCK BRAKE SYS., CHROME WHEELS
FRONT AIR DAM, TINTED GLASS, ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS
DAYTIME RUNNING LIGHTS, AM/FM STEREO CD, FRONT SPLIT BENCH SEAT
POWER DISC BRAKES, STEP BUMPER

Drive Train: 4.8L Inj 8 Cyl 2WD
License: 7N54386 CA

Search Code: None

| Line Item | Entry Number | Labor Type | Operation | Line Item Description | Part Type/ Part Number | Dollar Amount | Labor Units |
|----------------------------|--------------|------------|----------------|--|---------------------------|---------------|-------------|
| <u>Front Fender</u> | | | | | | | |
| 1 | 500281 | REF | BLEND | R Fender Outside | | | C 0.8 |
| <u>Front Door</u> | | | | | | | |
| 2 | 505739 | BDY | REMOVE/REPLACE | R Frt Door Shell | Qual Recycled Part | 350.00 | * 4.7 #r |
| 3 | | REF | REFINISH | R Frt Add For Jamb & Interior | | | C 1.0 |
| 4 | | REF | REFINISH | R Frt Door Outside | | | C 2.6 |
| 5 | | | | AVAILABLE THRU ALLIED SALVAGE 877-784-0057 | | | |
| 6 | | | | REF # 00008078 | | | |
| 7 | | | | Line Markup %20.00 | | 70.00 | |
| 8 | 504891 | BDY | REMOVE/INSTALL | R Frt Otr Belt Moulding | | | INC # |
| 9 | 501293 | BDY | REMOVE/INSTALL | R Frt Rear View Mirror | | | INC |
| 10 | 501285 | BDY | REMOVE/REPLACE | R Frt Door Adhesive Moulding | ORDER FROM DEALER | 92.72 | 0.1 |
| 11 | 501321 | BDY | REMOVE/INSTALL | R Frt Door Trim Panel | | | INC |
| 12 | 502180 | BDY | REMOVE/INSTALL | R Frt Door Handle | | | INC # |
| 13 | 501385 | BDY | REMOVE/INSTALL | R Frt Door Glass Run | Existing | | INC #r |
| <u>Rear Door</u> | | | | | | | |
| 14 | 505517 | BDY | REPAIR | R Rear Door Repair Panel | Existing | | 2.5* # |
| 15 | | REF | REFINISH | R Rear Door Outside | | | C 2.0 |
| 16 | 505184 | BDY | REMOVE/REPLACE | R Rear Door Adhesive Moulding | ORDER FROM DEALER | 107.82 | 0.2 |

ESTIMATE RECALL NUMBER: 07/07/2013 15:35:45 CO13010901

Mitchell Data Version: OEM: JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Software Version: 7.0.486

Page 1 of 3

| | | | | | | | | | |
|--|--------|-------|----------------|----------------------------|-------------------|--|------|---|----------|
| 17 | 501418 | GLS | REMOVE/INSTALL | R Rear Door Moveable Glass | | | | | 1.8 # |
| <u>ADDITIONAL OPERATIONS</u> | | | | | | | | | |
| 18 | | REF | ADD'L OPR | Clear Coat | | | | | 1.8 |
| <u>MANUAL ENTRIES</u> | | | | | | | | | |
| 19 | 900500 | BDY * | REPAIR | TINT | Existing | | | | 0.5* |
| 20 | 900500 | BDY * | REMOVE/REPLACE | MASK FOR OVERSPRAY | ** QUAL REPL PART | | 5.00 | * | 0.3* |
| 21 | 900500 | BDY * | REMOVE/REPLACE | HAZARDOUS WASTE DISPOSAL | Sublet | | 3.00 | * | INC* |
| <u>Additional Costs & Materials</u> | | | | | | | | | |
| 22 | | | ADD'L COST | Paint/Materials | | | | | 262.40 * |

* - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc
r - CEG R&R Time Used For This Labor Operation

Estimate Totals

| | | Units | Rate | Add'l Labor Amount | Sublet Amount | Totals | | | Amount |
|---|------------------------|--------------------------|-------|--------------------|---------------|--------|-----|--------------------------------|----------|
| I. | Labor Subtotals | | | | | | II. | Part Replacement Summary | |
| | Body | 8.3 | 48.00 | 0.00 | 0.00 | 398.40 | | Taxable Parts | 555.54 |
| | Refinish | 8.2 | 48.00 | 0.00 | 0.00 | 393.60 | | Parts Adjustments | 70.00 |
| | Glass | 1.8 | 48.00 | 0.00 | 0.00 | 86.40 | | Sales Tax @ 9.000% | 56.30 |
| | Non-Taxable Labor | | | | | 878.40 | | Non-Taxable Parts | 3.00 |
| | Labor Summary | 18.3 | | | | 878.40 | | Total Replacement Parts Amount | 684.84 |
| III. | Additional Costs | | | | | Amount | IV. | Adjustments | Amount |
| | Taxable Costs | | | | | 262.40 | | Insurance Deductible | 500.00- |
| | Sales Tax @ 9.000% | | | | | 23.62 | | Customer Responsibility | 500.00- |
| | Total Additional Costs | | | | | 286.02 | | | |
| Paint Material Method: Rates Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00 | | | | | | | | | |
| | I. | Total Labor: | | | | | | | 878.40 |
| | II. | Total Replacement Parts: | | | | | | | 684.84 |
| | III. | Total Additional Costs: | | | | | | | 286.02 |
| | | Gross Total: | | | | | | | 1,849.26 |
| | IV. | Total Adjustments: | | | | | | | 500.00- |
| | | Net Total: | | | | | | | 1,349.26 |

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

3 Right Side (P)

Insurance Co: ROBERT MORENO INSURANCE SERVICES
Address: PO BOX 5185
FULLERTON, CA 92838
Telephone: (714) 578-3366
Fax Phone: (714) 738-5035

Inspection Site: INSUREDS RESIDENCE
Address: 85101 DAMASCUS AVE
COACHELLA, CA 92236
Inspection Date: 7/3/2013

COLLECT ALL FROM OWNER

***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***

***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER.
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!***

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.







