

PROPERTY DAMAGE SPECIALIST

P.O. BOX 3237, INDIO, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: PDS9593@VERIZON.NET

APPRAISAL REPORT

DAMAGE ASSESSED BY: ROBERTA KEAR

FILE NUMBER: CO13009790-C
CLAIM NUMBER: CO13009790-C
DATE OF LOSS: 5/29/2013
TYPE OF LOSS: Property Damage
APPRAISED FOR: ROBERT MORENO INSURANCE - SHELLEY RAMOS

ASSIGNMENT DATE: None
CONTACT DATE: None
INSPECTION DATE: 6/13/2013
REC'D DATE: None

Point(s) of Impact

6 Rear Center (P)

INSURED: ARISTIDE LENORE WOLF

CLAIMANT: LUIS MEDINA
613 S KEENAN AVE
LOS 8812, CA 90022

OWNER: LUIS MEDINA
613 S KEENAN AVE
LOS 8812, CA 90022

BODY SHOP: None

INSPECTION SITE: RESIDENCE
613 S KEENAN AVE
LOS ANGELES, CA 90022

QUALITY RECYCLED PARTS: No
AFTERMARKET NEW PARTS: No
VEHICLE DRIVEABLE: Yes

Comments:

6/13/2013 - I INSPECTED THE CLAIMANT'S 2007 FORD F-150 XLT FX4 AT THE CLAIMANT'S NEW RESIDENCE, 613 S KEENAN AVE, LOS ANGELES AT APPROX 9:30 AM.

I NOTED DAMAGE TO THE REAR OF THE VEHICLE. APPROX REPAIR TIME IS 1 DAY & THE VEHICLE IS DRIVABLE.

LKQ/QRP SEARCH FOUND A RECONDITIONED REAR BUMPER AT KEYSTONE, 800-421-7866. I WAS UNABLE TO FIND A RECONDITIONED OR LKQ TRAILER HITCH AT EITHER CAR=PART.COM OR LKQCORP.COM.

NO UPD WAS NOTED TO THE VEHICLE.

NO BETTERMENT WAS APPLIED. NO TOW BILL.

NO SHOP INFORMATION.

OPEN ITEMS INCLUDE SHOP LABOR RATES, EXPENSES, DETRIM & POSSIBLE
ADDITIONAL DAMAGE AFTER TEARDOWN.

THIS VEHICLE IS REPAIRABLE.

COMPARISON ESTIMATE:	0.00	TOWING:	0.00	ACTUAL CASH VALUE:	21,025.00
APPRaiser ESTIMATE:	1,537.43	STORAGE:	0.00	SALVAGE VALUE:	0.00
AGREED UPON AMOUNT:	0.00	DEDUCTIBLE:	NONE	SETTLEMENT:	0.00
				REPAIR VS. ACV:	0.00
DRAFT/CHECK NUMBER:	0			ESTIMATE FEE:	0.00
DRAFT/CHECK AMOUNT:	0.00			TRAVEL EXPENSE:	0.00
DATE ISSUED:	None			PHOTO EXPENSE:	0.00
				MISC EXPENSE:	0.00
				TOTAL CHARGES:	0.00

Date: 6/14/2013 08:04 AM
Estimate ID: CO13009790-C
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA, 760-275-6795 OR EMAIL
PDS9593@VERIZON.NET

PROPERTY DAMAGE SPECIALIST

P.O. BOX 3237, INDIO, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: PDS9593@VERIZON.NET

Damage Assessed By: ROBERTA KEAR

Appraised For: ROBERT MORENO INSURANCE - SHELLEY RAMOS

Condition Code: Good
Date of Loss: 5/29/2013
Deductible: NONE
File Number: CO13009790-C
Claim Number: CO13009790-C

Type of Loss: Property Damage
Arrival Date: 6/13/2013

Insured: ARISTIDE LENORE WOLF
Claimant: LUIS MEDINA
Address: 613 S KEENAN AVE, LOS 8812, CA 90022
Owner: LUIS MEDINA
Address: 613 S KEENAN AVE, LOS 8812, CA 90022
Telephone:
Cell Phone: (323) 947-8812

Mitchell Service: 910158

Description: 2007 Ford Pickup F150 FX4
Body Style: 4D PkpwCrw 6' Bed 139" WB
VIN: 1FTPW14527KC64070
Mileage: 76,663
OEM/ALT: A
Color: RED
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW
POWER STEERING, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
SKID PLATES, ANTI-LOCK BRAKE SYS., FOG LIGHTS, ALUM/ALLOY WHEELS
AUXILIARY INPUT, LEATHER STEERING WHEEL, FRONT AIR DAM, TINTED GLASS
ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS, AM/FM STEREO CD, FRONT SPLIT BENCH SEAT
KEYLESS ENTRY SYSTEM, LIMITED SLIP DIFFERENTIAL, POWER DISC BRAKES
POWER FOLDING EXTERIOR MIRRORS, STEERING WHEEL MOUNTED CONTROLS

Vehicle Production Date: 3/07
Drive Train: 5.4L Inj 8 Cyl 4WD
License: 8P41804 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	005245	BDY	REMOVE/REPLACE	Frame Trailer Hitch	7L3Z 17D826 D	515.23	1.0
2	000288	BDY	REMOVE/REPLACE	Frame Wiring Connector	XL3Z 14489 BA	47.25	
3	AUTO	BDY	OVERHAUL	Rear Bumper Assy			1.2
4	007088	BDY	REMOVE/REPLACE	Rear Bumper Face Bar	Remanufactured	352.00	* INC
5	AUTO	REF	REFINISH	Rear Face Bar			C 2.2
6				KEYSTONE, 800-421-7866			
7	007092	BDY	REMOVE/REPLACE	Rear Bumper Pad	7L3Z 17B807 B	170.32	INC
8	936012		ADD'L COST	Hazardous Waste Disposal		3.00	*
9	AUTO	REF	ADD'L OPR	Clear Coat			0.9
10	933003	BDY *	ADD'L OPR	Tint Color			0.5*
11	AUTO		ADD'L COST	Paint/Materials		99.20	*

ESTIMATE RECALL NUMBER: 06/14/2013 08:04:51 CO13009790-C

Mitchell Data Version: OEM: MAY_13_V
MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

* - Judgment Item
C - Included in Clear Coat Calc

Estimate Totals

Date: 6/14/2013 08:04 AM
Estimate ID: CO13009790-C
Estimate Version: 0
Preliminary
Profile ID: * PDS

Inspection Site: RESIDENCE
Address: 613 S KEENAN AVE
LOS ANGELES, CA 90022
(323) 947-8812
Inspection Date: 6/13/2013

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

















OML		REGISTRATION VALID FROM				TYPE		LICENSE NUMBER	
07/31/2011 TO 07/31/2012		31		8P41804					
VEHICLE IDENTIFICATION NUMBER						MAKE			
1FTPW14527KC64070						FORD			
BODY TYPE MODEL		CYLS	DATE FIRST SOLD		CLASS	YR	Yr Model		
PK			00/00/2007		KH		2007		
DATE ISSUED		TYPE VEH	MP	AX	WC	UNLADEN/GCOW	TOTAL FEES PAID		
08/04/2011		32P	G	2	E	05327	\$395		
						1900			
<p>OWNER</p> <p>CONTRERASMEDINA LUIS G 4551 E 6TH ST LOS ANGELES CA 90022-2418</p>									
<p>FORD MOTOR CRDT CO 260 INTERSTATE N PKWY NW ATLANTA GA</p>						<p>W0154 R0069 L0142</p>			
<p>0</p> <p>STATE OF CALIFORNIA DEPARTMENT OF MOTOR VEHICLES VALIDATED REGISTRATION CARD</p>						<p>30339 RI8080120114002</p>			

06/13/2013













