

**View Claim Summary - File Number: 06282013-1000012**[GO BACK](#)**Claim Summary been saved successfully...****Property Damage Specialist**P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : co13010483
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Kelly Campos
Date of Loss : 2013-06-18
Whose Claim : Insured
Owner Name : abel morando
Insured Name : abel morando
Claimant Name :
Inspection Location : RESIDENCE

Appraisal Information

File Number : 06282013-1000012
Appraiser : Tony Nguyen
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-03
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) :
Possible Supplement :

Vehicle Information

Year : 2004
Make : Saturn
Model : Ion
Sub-model : ION2
VIN : 1G8AZ52F44Z219600
Plate : 5JMB246

State : California
Milage : 181831
Drivable : Yes
Primary POI : RT FENDER
Secondary POI :
Vehicle Condition : Good
Interior Condition :
Paint Condition :
Engine :

Repair Information

Recommendation : Repairable
Estimate 1 Total : 0.00
Estimate 2 Total : 0.00
Estimate 1 Betterment : 0.00
Estimate 2 Betterment : 0.00
Supplement 1 Total : 0.00
Supplement 1 Betterment : 0.00
Supplement 2 Total : 0.00
Supplement 2 Betterment : 0.00
Supplement 3 Total : 0.00
Supplement 3 Betterment : 0.00
Supplement 4 Total : 0.00
Supplement 4 Betterment : 0.00
Subtotal : 0.00
Deductible : 0.00
Original Net Loss : 0.00
Gross Total : 0
Supplement Net Loss : 0.00

Tire Information

Make :
Size :
Tired Depth (in 32nds)
L/F R/F
L/R R/R
Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

INSPECTION OF INSURED'S VEHICLE AT THE RESIDENCE IN MORENO VALLEY ON 7-3-13. I OBSERVED MINIMAL DAMAGE TO FRONT BUMPER COVER AND RT FRONT FENDER.

Date: 7/8/2013 07:05 AM
Estimate ID: CO13010483
Estimate Version: 0
Preliminary
Profile ID: PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: TONY NGUYEN

Appraised For: KELLEY CAMPOS
(714) 738-1383

ROBERT MORENO INS
(714) 738-1383

Condition Code: Good
Date of Loss: 6/18/2013
Deductible: 0.00
File Number: CO13010483
Claim Number: CO13010483

Type of Loss: Property Damage

Insured: ABEL MORANDO
Owner: ABEL MORANDO
Address: 23285 MERRYGROVE CIRCLE, MORENO VALLEY, CA 92553
Telephone: Home Phone: (909) 965-7769

Mitchell Service: 910022

Description: 2004 Saturn ION 2
Body Style: 4D Sed
VIN: 1G8AZ52F44Z219600
Mileage: 181,831
OEM/ALT: A
Color: CHARC GREY
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, REAR WINDOW DEFOGGER
MANUAL AIR CONDITION, TILT STEERING COLUMN, FOG LIGHTS, FRONT AIR DAM
TINTED GLASS, VARIABLE ASSISTED STEERING, ANTI-THEFT SYSTEM
DAYTIME RUNNING LIGHTS, AM/FM STEREO CD, FRONT BUCKET SEATS, INTERIOR AIR FILTER
POWER LIFTGATE/TRUNK, REAR AC & HEATER

Vehicle Production Date: 6/04
Drive Train: 2.2L Inj 4 Cyl 5M FWD
License: 5JMB246 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	900500	BDY *	ADD'L LABOR OP	PHOTOS ONLY	Existing		0.0*

* - Judgment Item

ESTIMATE RECALL NUMBER: 07/08/2013 07:05:49 CO13010483

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Labor Summary	0.0				0.00	Total Replacement Parts Amount	0.00
III. Additional Costs					Amount	IV. Adjustments	Amount
Total Additional Costs					0.00	Insurance Deductible	0.00
						Customer Responsibility	0.00
						I. Total Labor:	0.00
						II. Total Replacement Parts:	0.00
						III. Total Additional Costs:	0.00
						Gross Total:	0.00
						IV. Total Adjustments:	0.00
						Net Total:	0.00

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

1 Right Front Corner (P)

Inspection Site: RESIDENCE
 Address: 23285 MERRYGROVE CIRCLE
 MORENO VALLEY, CA 92553
 Inspection Date: 7/6/2013

COLLECT ALL FROM OWNER
 ***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
 GUARANTEE OF PAYMENT.***
 ***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
 REINSPECTED PRIOR TO REPAIR BY THE APPRAISER
 FAILURE TO HAVE REINSPECTION WILL RESULT IN
 NON-PAYMENT!!!!!!!!!!!!***

***COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS *NOT* AN ACCEPTANCE OF
 COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE
 DETERMINED BY ROBERT MORENO INSURANCE COMPANY.
 THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY ROBERT
 MORENO INSURANCE COMPANY.

Pursuant to California Code of Regulations Section 2695.8(g)

ESTIMATE RECALL NUMBER: 07/08/2013 07:05:49 CO13010483

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Software Version: 7.0.486

All Rights Reserved

Page 2 of 3

Date: 7/8/2013 07:05 AM
Estimate ID: CO13010483
Estimate Version: 0
Preliminary
Profile ID: PDS

The insurance company named on this damage estimate warrants that all non-original equipment replacement parts listed herein are of like, kind, quality, safety, fit and performance as original equipment manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 07/08/2013 07:05:49 CO13010483

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3







