

 **View Claim Summary - File Number: 07032013-100005**

GO BACK

Claim Summary been saved successfully...



Property Damage Specialist
P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : CO13010957
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Lorena Bautista
Date of Loss : 2013-06-29
Whose Claim : Insured
Owner Name : LAURA DE ANDA
Insured Name : LAURA DE ANDA
Claimant Name :
Inspection Location : TOW YARD

Appraisal Information

File Number : 07032013-100005
Appraiser : Tony Nguyen
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-06
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) :
Possible Supplement :

Vehicle Information

Year : 2003
Make : Honda
Model : Accord
Sub-model : EX
VIN : 1HGCM66523A089545
Plate : 5ECG977

State : California
Milage : UNK
Drivable : No
Primary POI : FRT AND REAR
Secondary POI :
Vehicle Condition : Good
Interior Condition :
Paint Condition :
Engine :

Repair Information

Recommendation :	Total Loss
Estimate 1 Total :	24992.82
Estimate 2 Total :	0.00
Estimate 1 Betterment :	0.00
Estimate 2 Betterment :	0.00
Supplement 1 Total :	0.00
Supplement 1 Betterment :	0.00
Supplement 2 Total :	0.00
Supplement 2 Betterment :	0.00
Supplement 3 Total :	0.00
Supplement 3 Betterment :	0.00
Supplement 4 Total :	0.00
Supplement 4 Betterment :	0.00
Subtotal :	24992.82
Deductible :	500.00
Original Net Loss :	24492.82
Gross Total :	24992.82
Supplement Net Loss :	0.00

Tire Information

Make :
Size :
Tired Depth (in 32nds)
L/F R/F
L/R R/R
Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

COMPLETED INSPECTION OF INSUREDS VEHICLE AT TYLER TOWING ON SATURDAY 7-6-13. NO CHARGES AVAILABLE DUE TO WEEKEND INSPECTION. I OBSERVED EXTENSIVE STRUCTURAL DAMAGES TO ALL OVER VEHICLE. VEHICLE IS A STRUCTURAL TOTAL LOSS.



Used Vehicle Valuation Report

Report Date: 07/07/2013

Effective Dates: 07/04/2013 - 07/11/2013

2003 Honda Accord EX Sedan 4D

VIN: 1HGCM66523A089545

Reference:

Base Values				
	Excellent	Very Good	Good	Fair
MSRP	\$22,860	--	--	--
Certified Pre-Owned	NA	--	--	--
Suggested Retail	\$9,150	--	--	--
Private Party	\$7,275	\$6,925	\$6,700	\$5,775
Lending Value	\$5,950	--	--	--
Auction	\$5,975	\$5,850	\$5,475	\$4,650
Trade-In	\$5,525	\$5,400	\$5,025	\$4,200
Value as of: 07/07/2013 Engine: 4-Cyl, VTEC, 2.4 Liter Included Zip Code: 92509 Transmission: Automatic Included Condition: Good Drivetrain: FWD Included Mileage: 122,000 Included				
Itemized Equipment (Lending Value / Suggested Retail)				
ABS (4-Wheel)	Included	CD (Multi Disc)	Included	
Air Conditioning	Included	Dual Air Bags	\$0/\$0	
Power Windows	Included	Side Air Bags	\$0/\$0	
Power Door Locks	Included	Dual Power Seats	\$25/\$35	
Cruise Control	Included	Leather	\$125/\$165	
Power Steering	Included	Moon Roof	Included	
Tilt Wheel	Included	Alloy Wheels	\$25/\$35	
AM/FM Stereo	Included			
Total Itemized Equipment:			\$175/\$235	

©2013 Kelley Blue Book® Co., Inc. All rights reserved. 07/04/2013 - 07/11/2013 Edition for California 92509. The specific information required to determine the value for this particular vehicle was supplied by the person generating this report. Vehicle valuations are opinions and may vary from vehicle to vehicle. Actual valuations will vary based upon market conditions, specifications, vehicle condition or other particular circumstances pertinent to this particular vehicle or the transaction or the parties to the transaction. This report is intended for the individual use of the person generating this report only and shall not be sold or transmitted to another party. Kelley Blue Book® assumes no responsibility for errors or omissions. (v.13071)



Used Vehicle Valuation Report

Report Date: 07/07/2013

Effective Dates: 07/04/2013 - 07/11/2013

2003 Honda Accord EX Sedan 4D

VIN: 1HGCM66523A089545

Reference:

Total Values including Mileage and Option adjustments				
	Excellent	Very Good	Good	Fair
MSRP	\$22,860	--	--	--
Certified Pre-Owned	NA	--	--	--
Suggested Retail	\$9,385	--	--	--
Private Party	\$7,510	\$7,160	\$6,935	\$6,010
Lending Value	\$6,125	--	--	--
Auction	\$6,150	\$6,025	\$5,650	\$4,825
Trade-In	\$5,700	\$5,575	\$5,200	\$4,375

-- Assumes excellent condition.

Notes: MILEAGE UNK.

©2013 Kelley Blue Book® Co., Inc. All rights reserved. 07/04/2013 - 07/11/2013 Edition for California 92509. The specific information required to determine the value for this particular vehicle was supplied by the person generating this report. Vehicle valuations are opinions and may vary from vehicle to vehicle. Actual valuations will vary based upon market conditions, specifications, vehicle condition or other particular circumstances pertinent to this particular vehicle or the transaction or the parties to the transaction. This report is intended for the individual use of the person generating this report only and shall not be sold or transmitted to another party. Kelley Blue Book® assumes no responsibility for errors or omissions. (v.13071)

CCC valuescope Basic Claim Information Form



CCC VALUESCOPE.

Report Retrieval Method	<input type="checkbox"/> Email	<input type="checkbox"/> Fax	<input type="checkbox"/> Other (Specify)
CCC Phone: 1-800-621-8070		CCC Fax: 1-800-621-7070	CCC Email: CCCValuescopeRequest@cccis.com
Office ID Number		Claim Number CO13010957	
Adjr Name (First & Last) LORENA BAUTISTA		Appr Name (First & Last) TONY NGUYEN	
Adjr Contact# 714-738-1383		Insured's Name LAURA DE ANDA	
Owner's Name SAME		Owner's Phone 951-347-3193	
Loss ZIP Code 92509		Loss State CA	
Loss Type <input checked="" type="checkbox"/> Collision <input type="checkbox"/> Theft		Coverage code <input type="checkbox"/> Collision <input type="checkbox"/> Comprehensive <input type="checkbox"/> Liability <input type="checkbox"/> Other	
3rd Party Claim <input type="checkbox"/> Yes <input type="checkbox"/> No		Leased Vehicle <input type="checkbox"/> Yes <input type="checkbox"/> No	
Date of Loss 6-29-13		Exch#Policy #	
Adjuster ID#		Claim Class	
PA Appr ID#			
VIN 1HGCM66523A089545			
Year 2003	Make HONDA	Model ACCORD EX	
Body Style	<input type="checkbox"/> 2DR <input checked="" type="checkbox"/> 4DR	<input type="checkbox"/> Hatchback	<input type="checkbox"/> Convertible
<input type="checkbox"/> 1/2 Ton	<input type="checkbox"/> 3/4 Ton	<input type="checkbox"/> 1 Ton	<input type="checkbox"/> Short Bed
<input type="checkbox"/> Long Bed	<input type="checkbox"/> Cab & Chassis	<input type="checkbox"/> Fleetside	<input type="checkbox"/> Fenderside
Engine Size 3.0L	Cylinders	<input type="checkbox"/> 3	<input type="checkbox"/> 4
<input type="checkbox"/> 5	<input checked="" type="checkbox"/> 6	<input type="checkbox"/> 8	<input type="checkbox"/> 10
<input type="checkbox"/> 12	<input type="checkbox"/> Turbo	<input type="checkbox"/> Diesel	
Mileage ("UNK" if unknown) UNK			
Transmission	<input checked="" type="checkbox"/> Automatic	<input type="checkbox"/> S6	<input type="checkbox"/> S5
<input type="checkbox"/> S4	<input type="checkbox"/> S3	<input type="checkbox"/> OD	<input type="checkbox"/> 4W
<input type="checkbox"/> PO			
Power Options	Seating	Roof	Exterior/Paint/Glass
<input checked="" type="checkbox"/> PS Power Steering	<input type="checkbox"/> CS Cloth Seats	<input checked="" type="checkbox"/> EG Electric Glass Roof	<input type="checkbox"/> RR Luggage/Roof Rack
<input checked="" type="checkbox"/> PB Power Brakes	<input checked="" type="checkbox"/> LS Leather Seats	<input type="checkbox"/> ES Electric Steel Roof	<input type="checkbox"/> WG Woodgrain
<input checked="" type="checkbox"/> PW Power Windows	<input checked="" type="checkbox"/> RL Reclining/ Lounge Seats	<input type="checkbox"/> OR Skyview Roof	<input checked="" type="checkbox"/> WP Rear Window Wiper
<input checked="" type="checkbox"/> PL Power Locks	<input checked="" type="checkbox"/> BS Bucket Seats	<input type="checkbox"/> SD Dual Power Roofs	<input type="checkbox"/> 2T Two Tone Paint
<input checked="" type="checkbox"/> SP Power Driver Seat	<input type="checkbox"/> SH Heated Seats (2)	<input type="checkbox"/> MS Manual Steel Roof	<input type="checkbox"/> D2 Deluxe 2 Tone Paint
<input checked="" type="checkbox"/> PC Power Passenger Seat	<input type="checkbox"/> RH Rear Heated Seats	<input type="checkbox"/> MG Manual Glass Roof	<input type="checkbox"/> HP Three Stage Paint
<input type="checkbox"/> PA Power Antenna	<input type="checkbox"/> 3S Third Row Seat	<input type="checkbox"/> FR Flip Roof	<input checked="" type="checkbox"/> IP Clearcoat Paint
<input checked="" type="checkbox"/> PM Power Mirrors	<input type="checkbox"/> 3P Power Third Seat	<input type="checkbox"/> TT T-Top/Panel	<input type="checkbox"/> MP Metallic Paint
<input checked="" type="checkbox"/> PT Power Trunk/Tailgate	<input type="checkbox"/> R3 Retractable Seats	<input type="checkbox"/> GT Glass T-Top/Panel	<input type="checkbox"/> SL Rear Spoiler
<input type="checkbox"/> PP Power Adjustable Petals	<input type="checkbox"/> 2P 12 Passenger Seating	<input type="checkbox"/> MV Manual Convertible Roof	<input type="checkbox"/> FL Fog Lamps
<input type="checkbox"/> PD Power Sliding Door	<input type="checkbox"/> 5P 15 Passenger Seating	<input type="checkbox"/> VP Power Convertible Roof	<input checked="" type="checkbox"/> TG Tinted Glass
<input type="checkbox"/> DP Dual Power Sliding Doors	<input type="checkbox"/> B2 Captain Chairs (2)	<input type="checkbox"/> RM Detachable Roof	<input type="checkbox"/> DT Privacy Glass
Décor/Convenience	<input type="checkbox"/> B4 Captain Chairs (4)	<input type="checkbox"/> VR Vinyl Roof	<input checked="" type="checkbox"/> BN Body Side Moldings
<input checked="" type="checkbox"/> AC Air Conditioning	<input type="checkbox"/> B6 Captain Chairs (6)	<input type="checkbox"/> RF Cabriolet Roof	<input checked="" type="checkbox"/> DM Dual Mirrors
<input type="checkbox"/> DA Dual Air Conditioning	Radio	<input type="checkbox"/> LR Landau Roof	<input type="checkbox"/> HM Heated Mirrors
<input type="checkbox"/> CL Climate Control	<input checked="" type="checkbox"/> AM AM Radio	<input type="checkbox"/> LP Padded Landau Roof	<input type="checkbox"/> HV Headlamp Washers
<input checked="" type="checkbox"/> RD Rear Defogger	<input checked="" type="checkbox"/> FM FM Radio	<input type="checkbox"/> PV Padded Vinyl Roof	<input type="checkbox"/> MX Signal Integrated Mirrors
<input checked="" type="checkbox"/> IW Intermittent Wipers	<input checked="" type="checkbox"/> ST Stereo	<input type="checkbox"/> CT Soft Top	Other
<input checked="" type="checkbox"/> TW Tilt Wheel	<input type="checkbox"/> CA Cassette	<input type="checkbox"/> HT Hard Top	<input type="checkbox"/> BD Running Board/Side Steps
<input checked="" type="checkbox"/> TL Telescopic Wheel	<input type="checkbox"/> SE Search/Seek	Safety/Brakes	<input type="checkbox"/> UP Power Retractable Running Boards
<input checked="" type="checkbox"/> CC Cruise Control	<input checked="" type="checkbox"/> CD Compact Disc Player	<input checked="" type="checkbox"/> AG Air Bag	<input type="checkbox"/> XE Xenon Headlamps
<input checked="" type="checkbox"/> KE Keyless Entry	<input type="checkbox"/> SK CD Changer/Stacker	<input checked="" type="checkbox"/> RG Passenger Air Bag	<input type="checkbox"/> AR Bed Rails
<input checked="" type="checkbox"/> CN Console/Storage	<input type="checkbox"/> UR Premium Radio	<input checked="" type="checkbox"/> XG Front Side Impact Air Bags	<input type="checkbox"/> BL Bedliner
<input type="checkbox"/> CO Overhead Console	<input type="checkbox"/> XM Satellite Radio	<input type="checkbox"/> ZG Rear Side Impact Air Bags	<input type="checkbox"/> BY Bedliner (Spray On)
<input type="checkbox"/> EC Entertainment Center	<input type="checkbox"/> TQ Steering Wheel Touch Controls	<input checked="" type="checkbox"/> DG Head/Roof Air Bags	<input type="checkbox"/> CP Fiberglass Cap
<input type="checkbox"/> NV Navigation System	<input type="checkbox"/> M3 Auxiliary Audio Connection	<input checked="" type="checkbox"/> TD Theft Deterrent/Alarm	<input type="checkbox"/> GG Grill Guard
<input type="checkbox"/> C2 Communications System	<input type="checkbox"/> EQ Equalizer	<input type="checkbox"/> VZ Night Vision	<input type="checkbox"/> SB Rear Step Bumper
<input type="checkbox"/> HU Heads Up Display	<input type="checkbox"/> CB CB Radio	<input type="checkbox"/> IC Intelligent Cruise	<input type="checkbox"/> SS Swivel Seats
<input type="checkbox"/> WT Wood Interior Trim	<input type="checkbox"/> 8T 8 Track Tape Player	<input type="checkbox"/> PJ Parking Sensors	<input type="checkbox"/> SW Rear Sliding Window
<input type="checkbox"/> EI Electronic Instrumentation	Wheels	<input type="checkbox"/> PX Parking Sensors W/Equip	<input type="checkbox"/> PG Power Rear Window
<input type="checkbox"/> IB On Board Computer	<input checked="" type="checkbox"/> AW Aluminum/Alloy Wheels	<input checked="" type="checkbox"/> AB Anti-Lock Brakes (4)	<input type="checkbox"/> TB Tool Box (Permanent)
<input type="checkbox"/> MC Message Center	<input type="checkbox"/> CJ Chrome Wheels	<input type="checkbox"/> A2 Anti-Lock Brakes (2)	<input type="checkbox"/> TN Tonneau Cover – Soft
<input type="checkbox"/> MM Memory Package	<input type="checkbox"/> W2 20" or Larger Wheels	<input checked="" type="checkbox"/> DB 4-Wheel Disc Brakes	<input type="checkbox"/> TZ Tonneau Cover – Hard
<input type="checkbox"/> RJ Remote Start	<input type="checkbox"/> DC Deluxe Wheel Covers	<input type="checkbox"/> RB Rollover Protection	<input type="checkbox"/> TP Trailing Package
	<input type="checkbox"/> FC Full Wheel Covers	<input checked="" type="checkbox"/> TX Traction Control	<input type="checkbox"/> WD Dual Rear Wheels
	<input type="checkbox"/> SA Spoke Aluminum Wheels	<input type="checkbox"/> T1 Stability Control	<input type="checkbox"/> XT Auxiliary Fuel Tank
	<input type="checkbox"/> SY Styled Steel Wheels	<input type="checkbox"/> AL Auto Level	<input type="checkbox"/> 3D 3rd Truck Door
	<input type="checkbox"/> WW Wire Wheels		<input type="checkbox"/> 4D 4th Door Truck/Van
	<input type="checkbox"/> WC Wire Wheel Covers		<input type="checkbox"/> BC Bumper Cushions
	<input type="checkbox"/> RW Rally Wheels		<input type="checkbox"/> BG Bumper Guards
	<input type="checkbox"/> KW Locking Wheels		<input type="checkbox"/> EM California Emissions
	<input type="checkbox"/> LC Locking Wheel Covers		<input type="checkbox"/> SG Stone Guard
			<input type="checkbox"/> WI Winch

CCC Valuescope Basic Claim Information Form (Continued)

Office ID Number				Claim Number			
REFURBISHMENTS							
Transmission	Purchase Price		Mileage		Engine	Purchase Price	
Tires	Purchase Price		# of Tires				
Paint	<input type="checkbox"/> Basic	<input type="checkbox"/> Standard	<input type="checkbox"/> Custom	Date Painted	Purchase Price		
Interior	Purchase Price		Date		<input type="checkbox"/> Leather	<input type="checkbox"/> Vinyl	<input type="checkbox"/> Cloth
Camper Shell	Purchase Price		Date		Carpet Kit	Purchase Price	Date
Special Wheels	Purchase Price		Date				
Other	Description				Purchase Price	Date	
<input type="checkbox"/> Restored	Restored Amount						
Package/Special Features/Additional Options (XXXX=CALL BACK)							
CONDITION RATING: Rate each of the following 0=Below Average, 1=Normal, 2=Above Average, 3=Exceptional					COMMENTS		
Seats	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Lightly soiled or stained. Minimal fading, tears, holes or burn marks.		
Carpet	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Lightly soiled or stained. Minimal tears, holes or burn marks. Light wear in primarily driver's area		
Dashboard	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Small/few cracks or scratches. No broken or missing components. Light wear or fading		
Headliner	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Small/few tears or light fading. Minimal staining or soiling		
Body	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Sheetmetal: No dents. Small/few dings. No significant surface rust. Trim: No significant damage to components. Minimal peeling or fading. No rust apparent.		
Glass	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Minimal surface scratches and pitting. Few chips. Seals are intact and watertight		
Paint	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Minimal surface chipping or scratching. Slight fading		
Engine	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	No seepage evident. Belts and hoses firm, show no wear. No significant dirt and grease in engine compartment. No burn marks around tailpipe		
Transmission	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Fluid may be slightly discolored. No seepage evident		
Front Tires	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	5-7/32" of tread present. 41% to 68% of new. No signs of uneven wear		
Rear Tires	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	5-7/32" of tread present. 41% to 68% of new. No signs of uneven wear		
ADJUSTMENTS							
Pre Tax Adjustment 1					Add	Deduct	
Pre Tax Adjustment 2					Add	Deduct	
Sales Tax %	Leave blank if using AutoTax				Deductible		
Post Tax Adjustment 1					Add	Deduct	
Post Tax Adjustment 2					Add	Deduct	

Date: 7/7/2013 02:51 PM
Estimate ID: CO13010957
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: TONY NGUYEN

Appraised For: LORENA BAUTISTA / LB
(714) 738-1383

ROBERT MORENO INS
(714) 738-1383

Condition Code: Good
Date of Loss: 6/29/2013
Deductible: 500.00
File Number: CO13010957
Claim Number: CO13010957

Type of Loss: Property Damage

Insured: LAURA DE ANDA
Owner: LAURA DE ANDA
Address: 8315 SANTIAGO CIRCLE, RIVERSIDE, CA 92509
Telephone: Home Phone: (951) 347-3193

Mitchell Service: 910017

Description: 2003 Honda Accord EX
Body Style: 4D Sed
VIN: 1HGCM66523A089545
OEM/ALT: A
Color: WHITE
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW
REAR WINDOW DEFOGGER, CRUISE CONTROL, TILT STEERING COLUMN, LEATHER SEAT
POWER PASSENGER SEAT, TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS.
TRACTION CONTROL, ALUM/ALLOY WHEELS, LEATHER STEERING WHEEL
AUTOMATIC TRANSMISSION, TINTED GLASS, AUTO AIR CONDITION
UNIVERSAL GARAGE DOOR OPENER, VARIABLE ASSISTED STEERING, SIDE AIRBAGS
ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS, SIDE HEAD CURTAIN AIRBAGS
AM/FM STEREO CD CHANGER, FRONT HEATED BUCKET SEATS, INTERIOR AIR FILTER
KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, POWER LIFTGATE\TRUNK
STEERING WHEEL AUDIO CONTROLS, SUNROOF/MOONROOF (POWER)

Vehicle Production Date: 6/03
Drive Train: 3.0L Inj 6 Cyl 5A FWD
License: 5ECG977 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	AUTO	BDY	OVERHAUL	Frnt Bumper Cover Assy			2.3 #
2	000387	BDY	REMOVE/REPLACE	Frnt Bumper Cover	04711-SDA-A90ZZ	305.33	INC #
3	AUTO	REF	REFINISH	Frnt Bumper Cover			C 2.7
4	000963	BDY	REMOVE/REPLACE	R Front Combination Lamp Assembly	33101-SDA-A01	250.75	INC #
5	AUTO	BDY	CHECK/ADJUST	Headlamps			0.4
6	000836	BDY	REMOVE/REPLACE	R Fender Panel	04620-SDA-A90ZZ	245.35	2.1 #
7	AUTO	REF	REFINISH	R Fender Outside			C 2.0

ESTIMATE RECALL NUMBER: 07/07/2013 14:51:36 CO13010957

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Software Version: 7.0.486

All Rights Reserved

Page 1 of 4

Date: 7/7/2013 02:51 PM
Estimate ID: CO13010957
Estimate Version: 0
Preliminary
Profile ID: * PDS

8	AUTO	REF	REFINISH	R Add To Edge Fender				C 0.5
9	000100	MCH	REMOVE/REPLACE	Air Bag Module-Driver Front	-M	06770-SDB-A80ZB	804.96	0.3
10	000104	MCH	REMOVE/REPLACE	Air Bag Module-Passenger Front	-M	06780-SDB-A80ZB	837.83	0.6 #
11	000114	MCH	REMOVE/REPLACE	R Air Bag Side Module	-M	06783-SDA-A82	317.05	0.3 #
12	000115	MCH	REMOVE/REPLACE	L Air Bag Side Module	-M	06788-SDA-A82	317.05	0.3 #
13	000121	MCH	REMOVE/REPLACE	Air Bag OPDS Sensor	-M	81161-SDA-A01	173.97	0.5 #
14	AUTO	BDY	REMOVE/INSTALL	R Frt Seat Assy				INC
15	000132	MCH	REMOVE/REPLACE	R Frt Air Bag Side Impact Sensor	-M	77970-SDA-A82	138.70	0.3 #
16	000133	MCH	REMOVE/REPLACE	L Frt Air Bag Side Impact Sensor	-M	77970-SDA-A82	138.70	0.3 #
17	AUTO	BDY	REMOVE/INSTALL	L Frt Seat Assy				INC
18	002484	GLS	REMOVE/REPLACE	W/Shield Glass		** QUAL REPL PART	285.00	* INC*#
19	000735	BDY	REMOVE/REPLACE	R Frt Door Shell (HSS)		Qual Recycled Part	500.00	* 5.5 #r
20	AUTO	REF	REFINISH	R Frt Door Outside				C 1.6
21	AUTO	REF	REFINISH	R Frt Add For Jambs & Interior				C 1.0
22				Line Markup %20.00			100.00	
23	002008	BDY	REMOVE/REPLACE	R Rear Door Shell (HSS)		Qual Recycled Part	450.00	* 4.7 r
24	AUTO	REF	REFINISH	R Rear Door Outside				C 1.6
25	AUTO	REF	REFINISH	R Rear Add For Jambs & Interior				C 1.0
26				Line Markup %20.00			90.00	
27	002009	BDY	REMOVE/REPLACE	L Rear Door Shell (HSS)		Qual Recycled Part	450.00	* 4.7 r
28	AUTO	REF	REFINISH	L Rear Door Outside				C 1.8
29	AUTO	REF	REFINISH	L Rear Add For Jambs & Interior				C 1.0
30				Line Markup %20.00			90.00	
31	002250	BDY	REMOVE/REPLACE	Roof Panel		62100-SDA-A40ZZ	977.91	INC
32	AUTO	REF	REFINISH	Roof Panel Outside				C 2.4
33	002230	BDY	REMOVE/REPLACE	Roof Headliner		83200-SDA-A22ZB	414.54	INC
34	000144	GLS	REMOVE/REPLACE	Back Window Glass		** QUAL REPL PART	365.00	* INC #
35	AUTO	BDY	REMOVE/REPLACE	Roof/Both Qtrs/Rear Body Panel				48.1
36	001648	BDY	REMOVE/REPLACE	R Quarter Outer Panel		04636-SDA-306ZZ	801.83	INC #
37	AUTO	REF	REFINISH	R Quarter Panel Outside				C 1.7
38	AUTO	REF	REFINISH	R Quarter Panel Edge				C 0.5
39	AUTO	REF	REFINISH	R Add For Pillar				C 0.5
40	001649	BDY	REMOVE/REPLACE	L Quarter Outer Panel		04646-SDA-306ZZ	765.67	INC #
41	AUTO	REF	REFINISH	L Quarter Panel Outside				C 1.7
42	AUTO	REF	REFINISH	L Quarter Panel Edge				C 0.5
43	AUTO	REF	REFINISH	L Add For Pillar				C 0.5
44	001668	BDY	REMOVE/REPLACE	R Quarter Inner Panel	-S	64300-SDA-315ZZ	1,210.37	7.5
45	001669	BDY	REMOVE/REPLACE	L Quarter Inner Panel	-S	64700-SDA-315ZZ	2,021.68	7.5
46	001518	BDY	REMOVE/REPLACE	Luggage Lid Panel		68500-SDA-A91ZZ	698.59	2.0 #
47	AUTO	REF	REFINISH	Luggage Lid Outside				C 1.8
48	AUTO	REF	REFINISH	Luggage Lid Underside				C 1.1
49	001523	BDY	REMOVE/REPLACE	R Luggage Lid Hinge		68610-SV1-000ZZ	37.10	1.3 #
50	AUTO	REF	REFINISH	R Hinge				C 0.5
51	AUTO	BDY	REMOVE/INSTALL	Luggage Lid Assy				INC
52	001524	BDY	REMOVE/REPLACE	L Luggage Lid Hinge		68660-SV1-A00ZZ	37.10	0.2 #
53	AUTO	REF	REFINISH	L Hinge				C 0.5
54	002166	MCH	REMOVE/REPLACE	R Rear Susp Shock Absorber Assy	-M	52610-SDB-A03	439.85	1.0 #
55	002167	MCH	REMOVE/REPLACE	L Rear Susp Shock Absorber Assy	-M	52610-SDB-A13	385.67	0.8 #
56	002075	MCH	REMOVE/REPLACE	R Rear Susp Track Arm	-M	52380-SDA-A00	57.07	1.0 #
57	002076	MCH	REMOVE/REPLACE	L Rear Susp Track Arm	-M	52380-SDA-A00	57.07	1.0 #
58	002105	MCH	REMOVE/REPLACE	R Rear Susp Stabilizer Brkt	-M	52340-SDA-A00	18.97	#
59	002106	MCH	REMOVE/REPLACE	L Rear Susp Stabilizer Brkt	-M	52345-SDA-A00	18.97	#
60	002113	MCH	REMOVE/REPLACE	Rear Susp Crossmember	-M	50300-SDA-L00	806.07	5.4 #
61	001715	BDY	REMOVE/REPLACE	Rear Body Panel		66100-SDA-A00ZZ	335.00	INC
62	AUTO	REF	REFINISH	Rear Body Panel				C 1.6
63	AUTO	REF	REFINISH	Add For Inside				1.0

ESTIMATE RECALL NUMBER: 07/07/2013 14:51:36 CO13010957

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Page 2 of 4

Software Version: 7.0.486

All Rights Reserved

64	002949	BDY	REMOVE/REPLACE	R Rear Combination Lamp Assembly	33501-SDA-A01	148.73	INC #
65	AUTO	BDY	REMOVE/INSTALL	Rear Bumper Assy			INC
66	002950	BDY	REMOVE/REPLACE	L Rear Combination Lamp Assembly	33551-SDA-A01	148.73	INC #
67	002973	BDY	REMOVE/REPLACE	R Rear Combination Lamp Assembly	34151-SDA-A01	162.87	INC #
68	002974	BDY	REMOVE/REPLACE	L Rear Combination Lamp Assembly	34156-SDA-A01	162.87	INC #
69	AUTO	BDY	OVERHAUL	Rear Bumper Cover Assy			0.4
70	001774	BDY	REMOVE/REPLACE	Rear Bumper Cover	04715-SDA-A90ZZ	365.32	INC
71	AUTO	REF	REFINISH	Rear Bumper Cover			C 2.6
72	001782	BDY	REMOVE/REPLACE	R Rear Bumper Spacer	71593-SDA-A01	12.01	INC
73	001783	BDY	REMOVE/REPLACE	L Rear Bumper Spacer	71598-SDA-A01	12.01	INC
74	001784	BDY	REMOVE/REPLACE	Rear Bumper Impact Absorber	71570-SDA-A00	46.52	INC
75	001786	BDY	REMOVE/REPLACE	Rear Bumper Reinforcement Bar (HSS)	71530-SDA-A01ZZ	164.42	0.4 #
76	933006	FRM	ADD'L OPR	Frame/Rack Set Up			2.0*
77	933002	REF	ADD'L OPR	Clear Coat			2.5*
78	933003	BDY *	ADD'L OPR	Tint Color			0.5*
79	AUTO		ADD'L COST	Paint/Materials		1,043.20	*

- * - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc
r - CEG R&R Time Used For This Labor Operation

Estimate Totals

<div> <div>I. Labor Subtotals</div> <div> <div>Units</div> <div>Rate</div> <div>Add'l Labor Amount</div> <div>Sublet Amount</div> <div>Totals</div> </div> </div>						<div> <div>II. Part Replacement Summary</div> <div>Amount</div> </div>			
Body	87.6	46.00	0.00	0.00	4,029.60	Taxable Parts	15,886.63		
Refinish	32.6	46.00	0.00	0.00	1,499.60	Parts Adjustments	280.00		
Frame	2.0	55.00	0.00	0.00	110.00	Sales Tax @ 8.000%	1,293.33		
Mechanical	11.8	65.00	0.00	0.00	767.00				
Non-Taxable Labor					6,406.20	Total Replacement Parts Amount	17,459.96		
Labor Summary	134.0				6,406.20				
<div> <div>III. Additional Costs</div> <div>Amount</div> </div>						<div> <div>IV. Adjustments</div> <div>Amount</div> </div>			
Taxable Costs					1,043.20	Insurance Deductible	500.00-		
Sales Tax @ 8.000%					83.46				
Total Additional Costs					1,126.66	Customer Responsibility	500.00-		
Paint Material Method: Rates Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00									
						I. Total Labor:	6,406.20		
						II. Total Replacement Parts:	17,459.96		
						III. Total Additional Costs:	1,126.66		
						Gross Total:	24,992.82		

ESTIMATE RECALL NUMBER: 07/07/2013 14:51:36 CO13010957

Mitchell Data Version: OEM: JUN 13 V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International

All Rights Reserved

Page 3 of 4

Date: 7/7/2013 02:51 PM
Estimate ID: CO13010957
Estimate Version: 0
Preliminary
Profile ID: * PDS

IV. Total Adjustments: 500.00-
Net Total: 24,492.82
TOTAL LOSS

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

15 Total Loss (P), 3 Right Side (S), 6 Rear Center (S), 9 Left Side (S), 12 Front Center (S), 19 All Over (S)

Inspection Site: TYLER TOWING
Address: 12520 MAGNOLIA ST
RIVERSIDE , CA 92509
Inspection Date: 7/ 6/2013

COLLECT ALL FROM OWNER
***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!!!***

***COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS *NOT* AN ACCEPTANCE OF
COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE
DETERMINED BY ROBERT MORENO INSURANCE COMPANY.
THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY ROBERT
MORENO INSURANCE COMPANY.

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 07/07/2013 14:51:36 CO13010957

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 4 of 4





